From (Person	Gnoh pau loong	of	SMO	Plate/Timer	8/2/19@9.09an
Estunated Co	Diff:		Bill to:	Doto (date	Gring Frian
OD (II) W	'S / TP RES / OD RES / E	VA/INV/MV7	cs		
To Inspect V	ehicle No:	SDS 335	38) Insu	red SLU	2711R .
at Workshop	m/ii	per formance	L Motor Centre L	6319	0174
Ol	303	Alexandro	Road		
Policy No.	DISMIPPOIOIS	425	Claim No: CM	TD 19007	76 .
Sum Insured			Excess:		
Make of Veh (Client's Record			2	D.O.A. 4	2/2019
CA / REV	/ REP. / REV 24 HRS	up)		H.O.D. Endo	Table 1
Date/Time:	8/2/190 9:22am	Person Contacted:	Ceroline.	Vehicle (IN)	our
Date/Time	Action/Instruction () Estimate	p		
	SDS 33381-				
	SLU DANK ->				
	Sand preli rei	1			

West and 12

Lump Sum At Life is

12, 800 =

RUPE

...CLAIM SUBFOLDER...(Pending for Survey Report)

Main 07 Feb 2019 Main Re CLAIM SUBFOLDER DETAILS Insured: HOE YIWEN, ID: S884813	08 Feb 2019 09:09 Edit Adj Røt	Adj Rpt	Last:IA 11 Feb 2 14:04			Pending fo Report Cancel Case	4	
CLAIM SUBFOLDER DETAILS	ference	7	VEST DES ENTREM				for Survey	
			aim Details		Documer	nts	Show All	
Insured: HOE YIWEN, ID: S884813				[Creat	ed by insurer]			
	2A							
Main Claimant: CHEW WAI KIN, ID: S15	86380C							
Vehicle Reg. No.: SDS3338J	SDS33383			04/02/2 [54 Mo	04/02/2019 08:00 - :59 [54 Months and 17 Days From LTA Reg Date (Man Yr)]			
Claim Type: TP / CMTD1900746	TP / CMTD1900746			D18MTPV01018425 (Comprehensive)				
Vehicle Reg. No. SLU2711R (Insured):	SLU2711R		Policy No. (Claimant):					
			Excess:					
Repairer: Centre Line Car Spray Pai 68468203	nting (HQ) 2 K/	AKI BUKIT AVI	VEUE 2, #02-2	3 KAKI B	UKIT AUTOHUB, 4	17921 Kaki Buk	t - Tei:	
Handling Insurer: Sompo Insurance Singapo								
Adjuster: LKK Auto Consultants Pte 19/02/2019]	Ltd (HQ) - Tel:	6256-3561	[Handled by I	монр т	AUFIKH BIN HAM	IID] [Final	Rpt due	
Adj AsgPLEASE BE INFORMED THAT	OUR INSURED	HAS NOT REP	ORTED THE AC	CIDENT				
ASSOCIATED MAIL RECEIVED						View All. Co.	mpose Case Ma	
There are no mail for this case.								
ALL ASSOCIATED TASKS				View /	All Search Tasks	Create New 1	Task Complet	

...CLAIM SUBFOLDER...(New Assignment)

Case	Natified	Est Submitted	Adj Assigned	Act Rpt	Adj 5	ubmitted	Ins Authord	Statu	
Main	07 Feb 2019		08 Feb 2019 09:09 Assign					New	Assignment of Case
	tain	Re	ference		Claim Detail	,	Docum	ents	Show All
CLAIM SU	FOLDER DE	TAILS				ICres	ited by insurer)		
Insured:	HOE YIW	EN, ID: 5884813	2A			1,6,000,000	nes ey maerer		
Main Claimant:	CHEW WA	I KIN, ID: 515	86380C						
Vehicle Reg. No.:	SDS33383				Date of Los	s: 04/02	2019 08:00 - :59		
Claim Type:	TP / CMT	D1900746	Policy/Cover Note No.: D18MTPV01018425 (Comprehensive)			e)			
Vehicle Reg. No. (Insured):	5LU2711F	ι			Policy No. (Claimant)				
					Excess:				
Repairer:	63190172/	nce Motors Limit 63190174	ed (Alexandra)	303 Alexar	ndra Road, Sin	e Darby F	Performance Centre	e, 159941 A	lexandra - Tel:
Handling Insurer:	Sompo In	surance Singapo	re Pte. Ltd. (He	Q) - Tel: 64	61 6555 [H	andled by	GNOH PAU LOOP	NG - 63295	217]
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Final R	t due 19	9/02/20191		
Adj Asg. Remarks:		INFORMED THAT							
ASSOCIATI	D MAIL REG	CEIVED						View All I	Compose Case Ma
There are no	mall for this	case.						27877 358	annyese sest me
ALL ASSOC	IATED TAS	ks⊟				View	All I Consect Thete	. 1	New Task Complet
Due Date	Priority	KS⊟ Type Task 0	iroup Suble	ect Han	diar Acci	View	All Search Tasks	-	New Task Co

Veron Chen (LKKAuto)

From:

Admin-D (LKKAuto)

Sent:

Friday, 22 February 2019 3:26 PM

To:

Veron Chen (LKKAuto)

Subject:

FW: CMTD1900746/GPL - LIA(LKK)/ SLU2711R(Sompo) & SDS3338J ACC ON

04/02/2019

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: stephanie.lin@mbmwheelpower.com.sg [mailto:stephanie.lin@mbmwheelpower.com.sg]

Sent: Monday, 18 February 2019 3:40 PM

To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments@lkkauto.com; admin-d@lkkauto.com

Cc: danny.ong@mbmwheelpower.com.sg; 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; 'Ye, Yong Kang Melvin'

<melvin.ye@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>

Subject: RE: CMTD1900746/GPL - LIA(LKK)/ SLU2711R(Sompo) & SDS3338J ACC ON 04/02/2019

Dear all,

Please cancel my request as owner has decided do his claim somewhere else

Warmest Regards,

Stephanie Lin | Claims Officer



mbm wheelpower

T 6262 8888 | F 6250 9015 | M 8686 5188

Email: stephanie.lin@mbmwheelpower.com.sg

MBM Wheelpower Pte Ltd 160 Sin Ming Drive • #06-02

Sin Ming AutoCity • Singapore 575722

www.mbmwheelpower.com.sg

From: Teo, Grace <grace.teo@sompo.com.sg> Sent: Monday, 18 February 2019 11:56 AM

To: stephanie.lin@mbmwheelpower.com.sg; 'assignments@lkkauto.com' <assignments@lkkauto.com'>; 'admin-

d@lkkauto.com' <admin-d@lkkauto.com>

Cc: danny.ong@mbmwheelpower.com.sg; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Ye, Yong Kang Melvin

<melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: CMTD1900746/GPL - LIA(LKK)/ SLU2711R(Sompo) & SDS3338J ACC ON 04/02/2019

Without Prejudice

Our Claim Reference: CMTD1900746/GPL

Your Reference: SDS3338J

Hi Stephanie,

We acknowledged receipt of your claim documents.

Please be informed that Mr. Gnoh Pau Loong is the handler of this case.

As spoken, kindly let us have a copy of the authorisation letter from the insured and we will appoint LKK AUTO to survey the above vehicle.

Aside to LKK AUTO,

Please make arrangement to conduct the survey for SDS3338J on a without Prejudice and any admission of liability basis.

Please submit with your report via Merimen upon completion of survey.

Aside to Pau Loong,

Please refer to the liability request from MBM Wheelpower Pte Ltd.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @





¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click html

From: stephanie.lin@mbmwheelpower.com.sg [mailto:stephanie.lin@mbmwheelpower.com.sg]

Sent: Monday, February 18, 2019 10:33 AM

To: Claims - Motor Survey

Cc: danny.ong@mbmwheelpower.com.sg

Subject: RE: Liability Status - Accident involving SDS3338J & SLU2711R (Sompo) on 04/02/2019

Dear all,

Please provide the list of surveyors for us to choose from.

Thank you

Warmest Regards,

Stephanie Lin | Claims Officer



T 6262 8888 | F 6250 9015 | M 8686 5188

Email: stephanie.lin@mbmwheelpower.com.sg

MBM Wheelpower Pte Ltd 160 Sin Ming Drive • #06-02 Sin Ming AutoCity • Singapore 575722

www.mbmwheelpower.com.sg

From: stephanie.lin@mbmwheelpower.com.sg <stephanie.lin@mbmwheelpower.com.sg>

Sent: Saturday, 16 February 2019 1:50 PM

To: 'motorsurvey@sompo.com.sg' <motorsurvey@sompo.com.sg>

Cc: 'danny.ong@mbmwheelpower.com.sg' <danny.ong@mbmwheelpower.com.sg>

Subject: Liability Status - Accident involving SDS3338J & SLU2711R (Sompo) on 04/02/2019

Dear All

Appreciate if you can advise us on the liability status for the below loss and arrange a survey on Tues 19/02.

Please find attached for the GIA report.

Our Client's Vehicle Number:	SDS3338J
Sompo's Vehicle Number:	SLU2711R
Date/Time of Loss:	04/02/2019 0830 hrs

Kindly arrange your surveyor to survey the vehicle at 160 Sin Ming Drive #06-03 Sin Ming Autocity Singapore 575722

Please contact Stephanie @ 86865188 for the survey arrangement

Thank you

Warmest Regards, Stephanie Lin | Claims Officer



T 6262 8888 | F 6250 9015 | M 8686 5188

Email: stephanie.lin@mbmwheelpower.com.sg
MBM Wheelpower Pte Ltd
160 Sin Ming Drive • #06-02
Sin Ming AutoCity • Singapore 575722
www.mbmwheelpower.com.sg

This message has been scanned for viruses and dangerous content by QUAPE SPAM Protection, and is believed to be clean.



This email has been checked for viruses by AVG antivirus software. www.avg.com

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

GNOH PAU LOONG Attn:

11 Feb 2019 Date:

Preliminary Advice

Insured Vehicle No :: SLU2711R

TP Vehicle No ; SDS3338J

Accident Date

: 04/02/2019

Make

: BMW 528I

Assignment Date

: 08/02/2019

Date of Inspection : 08/02/2019

Est. Duration of Repair

: 7-9.00

Inspection At

: PERFORMANCE MOTORS LIMITED (ALEXANDRA)

303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE

SINGAPORE 159941

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and n/s body and parts claimed are consistent to the

Repairer's Estimate (Gross)	:S\$	32,078.10
Revised Amount	:S\$	15,077.70
Check Items (Estimated)	:S\$	13,114.35
Total	:S\$	28,192.05

:S\$ Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

(X)

The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage, Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: The above survey was conducted on a 'Without Prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	6380C	
Vehicle No.:	SD53338J	
Vehicle to be Exported:	No	
Intended Deregistration Date:	11 Feb 2019	
Vehicle Make:	B.M.W.	
Vehicle Model:	528I GT AT D/AB DSC LED SR NAV	
Primary Colour:	Grey	
Manufacturing Year:	2014	
Engine No.:	A2200B40N20B20A	
Chassis No.:	WBA5Z620X0DZ35949	
Maximum Power Output:	180.0 kW (241 bhp)	
Open Market Value:	\$58,362.00	
Original Registration Date:	18 Jul 2014	
First Registration Date:	18 Jul 2014	
Transfer Count:	1	
Actual ARF Paid: Intended PARF Rebate Details	\$77,052.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	17 Jul 2024	
PARF Rebate Amount: Intended COE Rebate Details	\$57,789.00	
COE Expiry Date:	17 Jul 2024	
COE Category:	E - Open Category	
COE Period(Years):	10	
QP Paid:	\$65,301.00	
COE Rebate Amount:	\$35,476,00	
Total Rebate Amount:	\$93,265.00	

The information contained herein is correct as at 11 Feb 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

THE RESERVE OF THE PERSON NAMED IN	ACCIDENT STATEMENT	
Date Of Report	07/02/2019 13:32	
Date Of Accident	04/02/2019 08:30	
Exact Location Of Accident	LAVENDER STREET	

Country/State of Loss SINGAPORE

TAILS	OF OWN	VEHICLE
i	TAILS	TAILS OF OWN

Vehicle Registration Number SDS3338J

Insured/Policyholder

Name Of Registered Owner CHEW WAI KIN

NRIC No S1586380C

Email Address CISCOCOSCO@GMAIL.COM

 Mobile Phone No
 (LOCAL) +65-98230741

 Alternative Phone No
 OFFICE-98230741

Vehicle Particulars

Manufacturer BMW

Model 528I-2.0 D/AB 2WD 4DR GAS/D NAV (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY PRIVATE CAR

Insurance Company

Vehicle Category

Name of Insurance Company

QBE INSURANCE (SINGAPORE) PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 8-VX020133-MVA

Cover Note Number

Driver

 Name of Driver
 CHEW WAI KIN

 NRIC No
 \$1586380C

 Date Of Birth
 21/12/1963

 Occupation
 INDOOR

 Date Of Driving Pass
 08/10/1982

Driving Experience 36 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98230741

Fax Number

Contact Number OFFICE-98230741

EMail Address CISCOCOSCO@GMAIL.COM

77 COUNTRYSIDE ROAD Address

789824 Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

OWNER

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by NO ambulance?

YES Was any other material or property damaged?

I have been approached by unknown person(s) NO soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 1

Details of Police Action

YES Was the accident reported to the police?

If Yes, Please state which Police Station

Police Station Name BISHAN NEIGHBOURHOOD POLICE CENTRE

ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: Police Station Address

SINGAPORE

NO

Police Station Contact TEL NO: 1800-5529999 - FAX NO: 65561905

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER ATTACHMENT AND POLICE REPORT. VEHICLE ALREADY TOW TO WORKSHOP SO NO PHOTO TAKEN.

Attachment(s)

NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT Are accident photos available for attachment?

Was there any video captured by Car Camera? NO Was there any audio recorded? NO

Details of Witness 1

FRANK 97699078 Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLU2711R Vehicle Make/Model/Colour VW GOLF

Details Of Properties

Vehicle Category PRIVATE CAR Name of Driver HOE YIWEN S8848132A NRIC/Passport Number Contact Number 91125247

Page Z of 8

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of .
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (III) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could invoive disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, hendling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes: and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information to collected under (d) above may be shared il disclosed.
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

illi for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Tth Fel 2019

Driver's Signature (if driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name:

COMPORTDELGRO ENGINEERING PTE LTD 383 SIN MING DRIVE SINGAPORE 575717 TEL: 6583 0400

NRIC/FIN No.:

SKETCH PLAN		
Lone to	Foch Park Seu 27112	The God
Lavenose St. Line	日から日	
	Sps 33	NIEVZ TAE
DESCRIBE CIRCUMSTANCES OF TH	IE ACCIDENT	1 1 0
As Police Report	Attorched.	
PECLARATION We declare the foregoing particulars a 7-Peb 2019	re true in every respect.	GOMFORTDELGRO ENGINEERING PTE LTD 383 SIN MING DRIVE SINGAPORE 575717 SINGAPORE 575717 1EL. 6563 0400
Oliomolder's Signature	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Date & Time:





T/20190204/2084

1 of 3

Report No. T/20190204/2084

Police Station Of Origin: Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

REPORT OF A TRAFFIC ACCIDENT

	ne Report N 019 13:40	Made:	Vide Report No.: A/20190204/0049	Station Diary No.:	
Informa	nt's Partic	ulars		VETUITE THE DE	
	f Informant: NAI KIN		Address: 77 COUNTRYSIDE ROAD SINGAPORE 789824		
	/ ID No.: O / S15863	80C	Contact No.: Home/Office:	Mobile: 98230741	
National SINGAP	ity: PORE CITIZ	'EN	Email:		
Sex: Male	Age: 55	Date of Birth: 21/12/1963	Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: Company director			Driving Licence Information: Class: 3	Date of Expiry:	

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 04/02/2019 08:30	Type of Location Straight Road	
Location: Along Road 1 LAVENDER S		Road Surface:	R	oad Speed Limit:	
Clear Traffic Flow: One Way		Dry Traffic Control:	100	Traffic Volume: Heavy	
Traffic Flow: One Way			H	eavv	

Details of V	ehicle Invo	lved		12.63		
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SDS3338J	Car	BMVV	528I GT AT D/AB DSC LED SR NAV	Grey		0
SLU2711R	Car	VOLKSWAGO N	GOLF 1.4 TSI AT 5G13HZ HID SR			0
SV31U	Car	TOYOTA	HARRIER G GRADE			0





2 of 3

Report No. T/20190204/2084

Police Station Of Origin: Bishan N.P.C 20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

CONTINUATION OF REPORT

Details of V	ehicle Insurance			
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SDS3338J	QBE Insurance (Singapore) Pte Ltd	VX020133	18/01/2019	17/01/2020

Brief Details.

Same.

On the above mentioned date and time, I was driving my vehicle SDS3338J along Lavender Street heading towards Jalan Besar, the traffic was heavy at the point of time and I was driving along lane 1. All the vehicles on lane 2 and 3 were stationary while the vehicles on lane 1 were moving. Suddenly, one vehicle SLU2711R cut into the front of my vehicle, into my lane and collided onto my vehicle's front left bumper in the process. The driver of SLU2711R had also collided onto another vehicle's (SV31U) right rear bumper which was along lane 2, in front of SLU2711R at the point of time.

I alighted from my vehicle and noted that my left front signal light, bumper and left passenger doors were damaged. After taking some photographs of the accident scene and exchanging contact details, the driver of SV31U left prior to police arrival as her vehicle was still able to move. The driver of SLU2711R also claimed that he wanted to merge onto my lane, lane 1 and had turned on his right signal before merging. did not notice his vehicle signal however when I saw his vehicle suddenly merging into my lane. I quickly stepped on my brakes, sounded my horn to warn him and tried swerving my vehicle towards the right to avoid the collision.

Police came to scene and towing crew was activated to tow SLU2711R as his vehicle was unable to move. I am lodging the report as advised by the police officer at scene. I have a witness for the accident and his details are as listed below. The witness had approached me after the accident and informed that he saw the entire incident from the back of my vehicle.

Witness: Frank 97699078





3 of 3

Report No. T/20190204/2084

Police Station Of Origin: Bishan N.P.C 20 Bishan Street 23 SINGAPORE 579757 Tel No: 1800-5529999

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: E / Sgt 2 PUA JIAN YAN, JEREMIAH	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 04/02/2019 13:40
Officer In Charge Of Case: TP / GIT / SI MOHAMMAD SHAHRIL BIN ABDULLAH Contact No.: 65476083	Classification Of Case:
\$168 SIGNATURE	



BLK 200A SENGKANG EAST ROAD #04-20 SINGAPORE 541200 H/P: 96311733 FAX: 6384 1950

Reg. No: 52879605D

CASH / WORK ORDER

Messrs: PSC NR	TAN Date: 4/4/9
Vehicle no: SPS 3338	C Model: BMW Cot
From: Lavanda	To: Betet molace
Remarks: accident	•
Time rec'd: 10 W	Time completed: // cro cr
Driver: Mas	Tow truck no: 1 870514
Order by:	Total amount:
Received by:	Issued by:
	Using King Dolly Use Car Carrier Low Spoiler / Jump Start Crane Up / Winch out Accident / Over-turn Loaded / Transport Charge

Note: The receipient of service or his presentative is required to follow along to the towing destination, failing which the tow operator shall not be liable for any alleged damage(s) to the car nor missing item(s) from the same.

con In

DMW Dealer

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

103, Alexandra Road Dine Darby Performance Centre Bingapore 159941

Tel. 63190103 (Sales & Admin) 53190111 (AfterSales) Fax. 64747773

280, Kampong Arang Boad Bast Coast Centre Bingapure 438180

Tel. 63190888 (AfterSales) Pax. 63449773

GST REG. NO : M2 -

LKK Auto Consultants hence notify the Repairer of the following:

A.A. Spresument before latter spray painting Darby, Suriness Centry spore 1959 and damaged parts) during resurvey 1177 perty three Staff's "Without Prejudice" banis

No illegal modification(s) is allowed

Supplementary Item(s) must be resurveyed and 0020093 to final X-royal from Insurance Comp.

07 FEB 2019

E S T I M A That Enterged by Repairer

Signature:

Page No. : 1 of 5

Estimate No.

: b1 50004

Date Estimated

: 07/02/2019

Prepared By

: Chua Kee Sin

- ESTIMATE REPAIR FOR -

Chew Wai Kin

77 Countryside Road

ACCOUNT -40000

Cash Sales - Service

Singapore

Singapore 789824

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL.

MILEAGE

SDS3338J

DZ35949

18/07/2014

5281A GT

0

3323

DESCRIPTION VALUE Replace left front side fender front bumper and remove attach. 2550 3,400,00 ment etc include knock on accident dent

Spray painting left front side fender ,front bumper and

left both side door

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

To replace left headlight.

To check steering geometry and conduct wheel alignment according to BMW specification (1x)

To remove and install front suspension to facilitate the jacking of chassis and mounting of car on celette bench including to replace damaged parts.

To replace tyre and wheel rim including balancing, (1x). left front

To carry out body cavity preservation. (Per panel).

Sundries.

To tow accident vehicle to PML workshop.

150 177.00

3,693.00

481.00

531.00

plat ? 2256 2,655.00

94.00

118.00

195.00

11,494.00

150.00

Total Labour 1:

DESCRIPTION	QTY	PRIC	VALUE
LH TENSION STRUT WITH HYDR MOUNT	1	505.20	7 505.20
WISHBONE TOP	1	555.75	7 555.75
LH WISHBONE BOTTOM WITH RUBBER MOUN	1	606.25	7 606.25
WHEEL HUB WITH BEARING FRT	1	503.00	7 503.00

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

309, Alexandra Boad Sime Darby Performance Centre Singapore 198941 Tel. 63180100 (Sales & Admin) 63180111 (AfterSales) Fax. 6474770

BMW Dealer

260, Kumpong Arang Kosd East Coast Centre Singapore 436180 Tel. 83190888 (AfterSales) Fax. 63449773

318, Alexandra Boad Sime Darby Business Centra Bingapora 159944 Tel. 63189528 (AfterSales) 63189523/530 (Motorrad) Fam. 44186624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. Date Estimated Prepared By	: b1 5000 : 07/02/2019 : Chua Kee	9			Page No.	: 2	of 5
REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	CIII		M	ILEAGE
SDS3338J	DZ35949	18/07/2014	528iA	GT			
DESC	RIPTION			QTY	PRIC		VALUE
****	H KING PIN			1	659.40		2 659.4
FRON	T SWING SUPPORT			2	113.35		? 226.7
	LIZER FRT WITH RUE	BER MOUNTING		1	481.00		7 481.0
	ROD			1	361.75		7 361.7
	EROD			1	361.75		× 361.7
	IR KIT BELLOWS (ZF)			2	101.80		203.6
	STEERING BOX ELEC			1	4,610.65		74,610.6
	PULSE GENERATOR F			1	208.70		7 208.7
	Y RIM 8.5X19 MULTI S			1	1,308.60		al 1,308.6
	CAP WITH CHROME E			1	28.35		7 28.3
Brack		DOL (DINITY)		1	34.25		34.2
	PANEL BRACKET FRT	THI		1	57.05		? 57.0
	H FENDER	LITT		1	804.50		4/- 804.5
	H BOTTOM DEFORMA	ATION ELEMENT		1	106.35		7 106.3
	UMPER LH CONNECT				61.80		61.8
	UMPER CARRIER	IOR			730.20		× 730.2
	UMPER BOTTOM MO	LINE		- 1	164.65		7 164.6
		UNI					- A
	light grille cover	D # LINITED		1	68.90		68.9
	H PROTECTIVE STRIF	P (LUXURY)		1	55.65		√ 55.6
	CT ABSORDER TOP			1	50.65		der 1 382 1
	UMPER PANEL PRIM			1	1,362.10	0	1,004
	UMPER PANEL PRIM	ED (PDC)		3	1,362.10	Repo	
	EM WITH BASE			1	71.25		AA - 71.2
GROM				2	0.75		AC1-15
	UMPER LH SPACER			1	13.40		13.4
	R LEFT			1	5.45		. 5.4
	H WHEELHOUSE FRT	SECTION		1	128.20		128.2
	R BOTTOM LH		290	1	55.95		55.9
LH HI	GH PRESSURE NOZZ	LE ~>	EA /	1	183.80		183.8
	LIGHT LED TECHNOL	OGY LH		1	4,203.70	(4	4,203.7
LH FC	G LIGHT LED		1,0	1	441.95		441.9
		()	14/11	To	tal Parts		20,584.1
	C2	ed losses / Direct Settlerne	ni l				
	D. Lags-any Linkson						
		Claim No.					
Destruction		Entert At					
Surveyor's	Name Turklu	Sign		Labour	1	23	11,494.0
Surveyor's	0 - 11 - 116	Authorised Yes / No.		Parts	the second		20,584.1
	- 0				2		
numonited		Time		Labour	2	8	0.0
RESURVE	Y PERTS PHOTO BY SUR	VEYOR YOU NO PM. TIME	290	Excess		2	0.0
Timeson's	La h.L	LC Thurstown		Total G	ST @ 7%	:	2,245.4
	yang Days Recommand	7-40an		Grand T	37 - 37	_	

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

wner ID Type:	Singapore NRIC
Owner ID:	6380C
Vehicle Details	
Vehicle No.:	SDS3338J
Vehicle to be Exported:	No
ntended Deregistration Date:	21 Feb 2019
Vehicle Make:	B.M.W.
Vehicle Model:	528I GT AT D/AB DSC LED SR NAV
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	A2200840N20B20A
Chassis No.:	WBASZ620X0DZ35949
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$58,362.00
Original Registration Date:	18 Jul 2014
First Registration Date:	18 Jul 2014
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$77,052.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jul 2024
PARF Rebate Amount: Intended COE Rebate Details	\$57,789.00
COE Expiry Date:	17 Jul 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$65,301.00
COE Rebate Amount:	\$35,288.00
Total Rebate Amount:	\$93,077.00

The information contained herein is correct as at 21 Feb 2019

OK

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Post an Ad

ANNOUNCING Carway

as sgCarMart Premium Dealer for the 2nd Consecutive Year

Just Start Your Business With Low Risk



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Opel Combo 1,7m; Previous Owner Use To Light Goods Only. Net Link Partners StarAd



v Browse by Category

Nuke

Advertiser Login

bmw 528

Ways of Selling

Depreciation Acre

Reg Date 2014 Eng Cap

Arry

Sort by Date Posted

Advanced Search: M.

Mileage

Arry

Veh Type

Submit (

Available

Search Selection

8 vehicles

brow \$28

BMW 5 Series 528i

\$117,555

\$15,840 /yr

24-Apr-2014

1,997 cc

Linury

Available

72,000 km

Status

✓ 20 results/page ✓

Enjoy 2.28% Loan Interest! 100% Loan Available! The Finance With Guaranteed 100% Loan Approval. 1 Owner Only! Highest Trade In For Your Used Car. Hurry Buy Now Before The Offer End. Call Now To View!

Cars Inn Credit Pte Ltd

Posted: 30 Feb-3119 Tags: 2014 89W 52B, 2014 bow 52B, 89W 52B, brow 52B, brow 52B, BMW, 53B, Used 89W



BMW 5 Series 528i

\$113,800

\$15.690 /vr

26-Jun-2014

1.997 cc

73,000 km

Luxury

Available

1 Owner Pristine 528T Facelifted Model, Sporty Black On Black, PML Unit, 100% Accident Free, 4 x New Tyres, Regular Service And Maintain At No Expense Spared, Guarantee Stunning Tip Top Cond, Welcome ...

Posted: 19-Feb-2019 Tags: 2014 BMW 528; 2014 briw 528; BMW 528; briw 528; BMW, 528; Used BMW



BMW 5 Series 528i Gran Turismo Luxury

\$122,000

\$17:160 /vr

27-Jan-2014

1,997 cc

43,853 km

Available

One And Only In The Market, Grab It While Available! Sporty And Luxury, Contrasting Black Body Color With Beige Interior. Well Maintained By 1 Owner, Flawless Condition! All Inspection Welcome For Gre...

Postest: 18-Feb-2019 Tags: 2014 BMW 528i, 2014 bmw 538i, 8MW 538i, bmw 538i, 8MW, 528i, Used BMW



BMW 5 Series 528i SE

\$120,800

\$16,270 /yr

19-Jun-2014

1.997 CE

78,000 km

Luxury

Available

New Facelifted BMW 528i, One Owner, New Tyres, And Battery, Major Servicing Just Done, Trade In Welcomed, Bank/High In-House Loan Available, Consignment Unit, Call Us Now To Arrange Viewing!

Posted: 16-Feb-2019 Tags: 3014 BPW 528, 2014 brow 528, BPW 528, brow 528, BPW, 528, Used BMW



Complete Bodykit

BMW F10 5 series M Style Bodykits Include Front Lip. 2 Lights, 2 Side Skirt, Rear Lip and Boot Lid Spoller

More info about this product



BMW 5 Series 528i

\$118,800

\$16,880 Art

16-May-2014

1,997 CE

51,000 km

Luxury

12 Months Warranty, Attractive 2.28% Interest Rate & Free Titan XI Low Mileage Of 10,000km Done Yearly Only! Gorgoous Sapphire Black Metallic Paintwork And Leather Interior! Flexible In House Financin...

me Cars Pte Ltd

Posted: 15-Feb-2019 Page: 3014 BMW 536, 2014 Inno 526, BMW 536, from 526, BMW, 526, (seed BMW



BMW 5 Series 528i

\$107,800

\$15,750 /vr

16-Jan-2014

1.997 27

85,000 km

Lunury

Available

Available

STREET, SQUARE,

1 Owner! Pl Unit! Low Mileage Unit! Popular Luxury Sedan! Classic Yet Sporty Unit! Flexible In House Financing And High Trade In Available! Call Now To View!

Hui Hua Credit Pta Ltd

Posted: 01-Feb-2019 Tack: 2014 BMW 528, 2014 bow \$28, 898W 528, boxe \$28, 899W 528, base \$280, 899W 528, base \$280, 899W 528, boxe \$280

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available
 aforesaid.

	ACCIDENT STATEMENT	
Date Of Report	07/02/2019 13:32	
Date Of Accident	04/02/2019 08:30	
Exact Location Of Accident	LAVENDER STREET	
Country/State of Loss	SINGAPORE	

	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SDS3338J	
Insured/Policyholder		
Name Of Registered Owner	CHEW WAI KIN	
NRIC No	S1586380C	
Email Address	CISCOCOSCO@GMAIL.COM	
Mobile Phone No	(LOCAL) +65-98230741	
Alternative Phone No	OFFICE-98230741	
Vehicle Particulars		
AND COURT OF THE C	Security and a second of	

Manufacturer BMW

Model 528I-2.0 D/AB 2WD 4DR GAS/D NAV (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken Vehicle Category THIRD PARTY PRIVATE CAR

Insurance Company

Name of Insurance Company QBE INSURANCE (SINGAPORE) PTE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 8-VX020133-MVA

Cover Note Number

Driver

 Name of Driver
 CHEW WAI KIN

 NRIC No
 \$1586380C

 Date Of Birth
 21/12/1963

 Occupation
 INDOOR

 Date Of Driving Pass
 08/10/1982

Driving Experience 36 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98230741

Fax Number

Contact Number OFFICE-98230741

EMail Address CISCOCOSCO@GMAIL.COM

Address 77 COUNTRYSIDE ROAD

Postcode 789824

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWI

Vehicle Registration Number of Driver's Own

Vehicle

OWNER

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

2

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

NO

NO

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

YES

18

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name BISHAN NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY:

SINGAPORE

Police Station Contact TEL NO: 1800-5529999 - FAX NO: 65561905

Was notice of intended Prosecution given?

If Yes, against whom?

NO

Circumstances of Accident

REFER ATTACHMENT AND POLICE REPORT. VEHICLE ALREADY TOW TO WORKSHOP SO NO PHOTO TAKEN.

Attachment(s)

Are accident photos available for attachment?

NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

Details of Witness 1

Name

FRANK

91125247

Phone Number 97699078

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLU2711R

Vehicle Make/Model/Colour VW GOLF

Details Of Properties

Contact Number

Vehicle Category PRIVATE CAR

Name of Driver HOE YIWEN NRIC/Passport Number S8848132A

Page 2 of 8

Postcode
Insurance Company Name
Nature Of Damage

KETCH PLAN				_	
Lavemore St	Lane of Lane 1	SLU Z711R	Foch and	Thur Gener	1
SCRIBE CIRCUMST	ANCES OF THE ACCI	DENT -	505 33387	SV3IU	,
	Report A			1	V V
LARATION					

I/We declare the foregoing particulars are true in every respect.

Poliomolder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Same

Date & Time:

GOMFORTDELGRO ENGINEERING PTE LTD

SRO SIN MING DRIVE
SINGAPORE 575717

TEL 6553 0400

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

a t

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the loggment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- ny Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
- (e) the information to collected under (d) above may be shared i disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(iii) for complying with requirements under any regulations, laws or court orders.

Palcyholder's Signature

Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time: COMFORTDELGRO ENGINEERING PTE LTD 383 SIN MING DRIVE SINGAPORE 575717

TEL: 6553 0400

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:





Police Station Of Origin: Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

1 of 3 Report No. T/20190204/2084

REPORT OF A TRAFFIC ACCIDENT

	ne Report M 019 13:40	/lade:	Vide Report No.: A/20190204/0049	Station Diary No 80
Informa	nt's Partic	ulars		
Name of	f Informant: WAI KIN		Address: 77 COUNTRYSIDE ROAD SI	NGAPORE 789824
	/ ID No.: 0 / S15863	80C	Contact No.: Home/Office:	Mobile: 98230741
National SINGAP	ity: ORE CITIZ	EN	Email:	KO.
Sex: Male	Age: 55	Date of Birth: 21/12/1963	Type of Informant. Driver	
Race: Chinese			Language: English	Institution / School Name.
Occupat	ion: y director		Driving Licence Information: Class: 3	Date of Expiry:

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 04/02/2019 08:30	Type of Location Straight Road
Location: Along Road 1 LAVENDER 5		9		
Weather:		Road Surface:		Road Speed Limit:
Weather: Clear Traffic Flow One Way		Road Surface: Dry Traffic Control		Road Speed Limit: Traffic Volume: Heavy

Details of V	ehicle Invo	lved				
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SDS3338J	Car	BMW	528I GT AT D/AB DSC LED SR NAV	Grey		0
SLU2711R	Car	VOLKSWAGO N	GOLF 1.4 TSI AT 5G13HZ HID SR			0
SV31U	Car	TOYOTA	HARRIER G GRADE			0





Police Station Of Origin: Bishan N.P.C 20 Rishan Street 23 SING

Report No. T/20190204/2084

2 of 3

20 Bishan Street 23 SINGAPORE 579757 Tel No: 1800-5529999

CONTINUATION OF REPORT

Details of Vehicle Insurance					
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date	
SDS3338J	QBE Insurance (Singapore) Pte Ltd	VX020133	18/01/2019	17/01/2020	

Brief Details.

On the above mentioned date and time, I was driving my vehicle SDS3338J along Lavender Street heading towards Jalan Besar, the traffic was heavy at the point of time and I was driving along lane 1. All the vehicles on lane 2 and 3 were stationary while the vehicles on lane 1 were moving. Suddenly, one vehicle SLU2711R cut into the front of my vehicle, into my lane and collided onto my vehicle's front left bumper in the process. The driver of SLU2711R had also collided onto another vehicle's (SV31U) right rear bumper which was along lane 2. In front of SLU2711R at the point of time.

I alighted from my vehicle and noted that my left front signal light, bumper and left passenger doors were damaged. After taking some photographs of the accident scene and exchanging contact details, the driver of SV31U left prior to police arrival as her vehicle was still able to move. The driver of SLU2711R also claimed that he wanted to merge onto my lane, lane 1 and had turned on his right signal before merging. I did not notice his vehicle signal however when I saw his vehicle suddenly merging into my lane. I quickly stepped on my brakes, sounded my horn to warn him and tried swerving my vehicle towards the right to avoid the collision.

Police came to scene and towing crew was activated to tow SLU2711R as his vehicle was unable to move. I am lodging the report as advised by the police officer at scene. I have a witness for the accident and his details are as listed below. The witness had approached me after the accident and informed that he saw the entire incident from the back of my vehicle.

Witness: Frank 97699078





Police Station Of Origin: Bishan N.P.C 20 Bishan Street 23 SINGAPORE 579757 Tel No: 1800-5529999

3 of 3 Report No. T/20190204/2084

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 PUA JIAN YAN, JEREMIAH	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 04/02/2019 13:40
Officer in Charge Of Case: TP / GIT / SI MOHAMMAD SHAHRIL BIN ABDULLAH Contact No : 65476083	Classification Of Case:
SIGNATURE	



SINGAPORE POLICE FORCE

Police Station Of Origin: Listnan N P C 20 Bishan Street 23 SINGAPORE 579757 Tel No. 1800-5529999



3 etc) Report No. T/20190204/2004

CONTINUATION OF REPORT

Sketch Plan

informant is not able to provide sketch plan

IMPORTANT. Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report

E.J.

Sgt 2 PUA JIAN YAN, JEREMIAH

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case
TP / GIT /
SI MOHAMMAD SHAHRIL BIN ABDULLAH
Contact No. 65476083

SIGNATURE

Date/Time
04/02/2019 13:40

Classification Of Case

General Informa	General Information of the Accident			
Type of Accident	Non-Injury Attended by Police	Drive:	Date/Time of Accident 04/02/2019 08:30	Type of Location Straight Road
Location: Along Road 1 LAVENDER STREET	REET			
Weather		Road Surface: Dry	R	Road Speed Limit
Traffic Flow: One Way		Traffic Control:	H	Traffic Volume Heavy
Type of Collision Between Moving	Type of Collision Between Moving Vehicles - Head To Side	e	Any am	Anyone conveyed by ambulance:

Details of Vehicle Involved	ehicle Invo	Ived				
Vehicle No. Type	Type	Make	Model	Color	Condition	No of Passenger
SDS3338J	Car	BMW	528I GT AT D/AB DSC LED SR NAV	Grey		0
SLU2711R Car	Car	VOLKSWAGO GOLF 1.4 N TSI AT 5G13HZ F	GOLF 1.4 TSI AT 5G13HZ HID SR			0
SV31U	Car	TOYOTA	HARRIER G GRADE			0



Police Station Of Origin Bishan N P C 20 Bishan Street 23 SINGAPORE 579757 Tel No. 1800-5529999



72.050

Report No. T/20190204/2084

CONTINUATION OF REPORT

Details of Vehicle Insurance				Comies Date
Valuele No	Insurance Company	Insurance No	Effective	Expiry Date
		MW000123	18/01/2019	17/01/2020
SDS3338J	QBE Insurance (Singapore) Pte Ltd	VX020133	10/0/1/2010	7 2 1 2 3 2 3 2 3 2 3

Brief Details.

On the above mentioned date and time, I was driving my vehicle SDS3338J along Lavender Street heading towards Jalan Besar, the traffic was heavy at the point of time and I was driving along lane 1. All the vehicles on lane 2 and 3 were stationary while the vehicles on lane 1 were moving. Suddenly one vehicle SLU2711R cut into the front of my vehicle, into my lane and collided onto my vehicle's front left bumper in the process. The driver of SLU2711R had also collided onto another vehicle's (SV31U) right lear bumper which was along lane 2. In front of SLU2711R at the point of time.

I alighted from my vehicle and noted that my left front signal light, bumper and left passenger doors were damaged. After taking some photographs of the accident scene and exchanging contact details, the driver of SV31U left prior to police arrival as her vehicle was still able to move. The driver of SLU2711R also claimed that he wanted to merge onto my lane, lane 1 and had turned on his right signal before merging did not notice his vehicle signal however when I saw his vehicle suddenly merging into my lane. I quickly stepped on my brakes, sounded my horn to warn him and tried swerving my vehicle towards the right to avoid the collision.

Police came to scene and towing crew was activated to tow SLU2711R as his vehicle was unable to move. I am lodging the report as advised by the police officer at scene. I have a witness for the accident and his details are as listed below. The witness had approached me after the accident and informed that he saw the entire incident from the back of my vehicle.


Witness: Frank 97699078















CENTRE LINE CAR SPRAY PAINTING .

2 KAKI BUKIT AVE 2 #02-18/23 (KAKI BUKIT AUTOHUB) SINGAPORE 417921

TEL: 6846 8203 FAX:6538 4108

Vehicle No.: SDS 3338J

Model: BMW (1

21/1/19 1/5 12.800 1. he he May

Prices \$

QTY List Price:

<u>qii</u>	LIST Price:	Files 3
1	Front bumper /362:10	り ・ノ 1562.10
1	Front bumper BMW logo 7/-25	rec 85.58
1	Front bumper fog lamp- LH	1 551.95 X
1	Front bumper fog lamp grille 68.90	415 89.65
1	Front bumper chrome moulding- LH \$1.65	M. J 120.35
2	Front bumper PDC sensor @ 313.75 281-80	Should 627.50 (1°C
1	Front bumper spray nozzle cover	4 3 62.15 ×
1	Front bumper top seal 68.90	Nec 89.95
1	Front bumper sponge	19-2 130.95 -
1	Front bumper carrier	1 1 785.50 X
1	Front bumper side bracket- LH	CM 89.60
10	Front bumper clips @ 4.50	re 45.00
1	Front bumper bottom mount	11 164.65 X
1	Front bumper bottom deformation element	106.35 ≪
1	Front fender- LH 804-50	7-5 899.55
1	Front fender emblem 75.30	ru 91.50
1	Front fender inner shield 106.35	Tra 142.63
1	Front fender iner shield extension (24.2)	Tom 128.65
15	Front fender inner shield plug @ 4.50	ser 67.50 -
1	Front fender stay	4 1 86.50 ×
6	Front fender top cover plug @ 5.50	33.00 ×
1	Front headlamp HID - LH 4203.70	4556.90
1	Front headlamp H.I.D control unit	Shi 861.50
1	Front headlamp H.I.D belb	481.90 ×
1	Front headlamp L.E.D light	41, 560.90 ℃
1	Front headlamp L.E.D control	sund 767.30
1	Front headlamp frame bracket	cm 189.60
1	Front headlamp spray nozzle pen	195.50 💥
1	Front headlamp spray nozzle hose	162.60 X
1	Front sport wheel- LH / 308-60	M/Sul 1560.50

805-75

1 Front shock absorber- LH

1 Front shock absorber top mount

1655.95 / 215.20 X

Vehicle No.: SDS 3338J

 $f_{ij} \in \mathcal{F}_{ij} = \emptyset$

1	Front shock absorber stopper	1 142.20 ×
1	Front wishbone-Top	But 659.50
1	Front wishbone- Lower 606.25	38x+ 680.60
1	Front stabilizer bar	1 1 481.90 X
1	Front stabilizer bar link	A 141.30 [∞]
1	Front knuckle arm 1/04:00	Sul 1265.50
1	Front wheel hub bearing 103.20	Dye 581.90
1	Front electrical steering rack	But 4810.65 XLR 200
2	Front tie rod- R/L @ 361.75	16 Buy 723.50 12 C
1	Front axle carrier	11 1551.60 X
		28207.11
	Less 5%	(1276.78)
		Subtotal 26930.33

		Subtotal	20930.33
	Special Nett Items:	Car	V
1	Fron tyre	81	C 850.00 X
		Subtotal	850.00
	Labour Charges:		
			300.00 /20
	Towing charges		
	To remove, refix F/undercarriage		650.00 300
	To check wheel alignment		150.00 /20
	To checking F/electrical wiring		50.00 30
	To dignos erase fault memory after repair		450.00/00
	To respray undercoating		120.00 3 0
	To respray painting and etc		1200.00 800
	Panel beating, cut, weld, remove and replacing above p	arts	1200.00 520
		7524 VIVE BY VI	11/11/20/20/2000

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

31900.33

4120.00

Subtotal



13846.12 13846.12 1611612

31766-76

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj 5	Submitted	Ins Auth'ed	Status		
Main	07 Feb 2019		08 Feb 2019 09:09 Edit Adj Rpt	5\$12,800.00 Edit Estimates	12000	2,800.00 w Rpt		Pending f Report Cancel Ca	for Survey	
	Main	R	eference	Claim De	tails		Documents		5how All	
CLAIM SU	BFOLDER DI	ETAILS				[Created	by insurer]			
Insured:	HOE YIW	EN, ID: 588481	32A							
Main Claimant:	CHEW W	AI KIN, 1D: S15	586380C							
Vehicle Reg No.:	SDS333	83		Date of	Loss:		9 08:00 - :59 and 17 Days Fron	n LTA Reg Dat	e (Man Yr)]	
Claim Type	TP / CM	TD1900746		Policy/G Note No		D18MTPV0	1018425 (Compreh	nensive)		
Vehicle Reg No. (Insured):	SLU2711	R		Policy N (Claims						
				Excess						
Repairer:	Centre Li	ne Car Spray Pai	inting (HQ) 2 KAKI	BUKIT AVNEUE 2,	102-23	KAKI BUKIT	AUTOHUB, 41792	1 Kaki Bukit -	Tel: 6846820	
Handling Insurer:	Sompo Ir	nsurance Singap	ore Pte. Ltd. (HQ)	- Tel: 6461 6555	[Hand	lled by GNO	H PAU LOONG - 6	3295217]		
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Handle	d by M	ARCUS CHI	JA] [Final Rp	t due 19/02	2/2019]	
Adj Asg. Remarks:	-PLEASE B	SE INFORMED THA	T DUR INSURED HA	S NOT REPORTED T	HE ACC	IDENT				
ASSOCIA	TED MAIL RE	CEIVED					View	All Comp	ose Case Mail	
There are r	o mail for this	case.								
ALL ASSO	CIATED TAS	SKS =			V	/iew All S	Search Tasks Cr	eate New Task	Complete	
Due Dat	e Priority	Type Task	Group Subjec	t Handler	Assign	ed By	Completed On	Created	On Done	

Merimen e-Claims Page 1 of 4

Claim Documents

*SDS3338J (CMTD1900746)

[SLU2711R]

TP

CHEW WAI KIN
Feb 4 2019 8:00AM

[HOE YIWEN]

Centre Line Car Spray Painting


Ass	essment Reports		1 per	page: V	V
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/02/19 14:04	Adjuster Immediate Advice	0	Load HTM	
Pho	tos/Images		3 per	page V	V
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	- Louisian	Thumbnail	and the second second
1	08/02/19 09:05	Accident Photo	0	Load JPG	8
2	08/02/19 09:05	Accident Photo	0	Load JPG	V
3	08/02/19 09:05	Accident Photo	0	Load JPG	V
4	08/02/19 09:05	Accident Photo	0	Load 3PG	V
5	08/02/19 09:05	Accident Photo	0	Load 3PG	V
6	08/02/19 09:05	Accident Photo	0	Load JPG	1
7	08/02/19 09:05	Accident Photo	0	Load JPG	V
8	08/02/19 09:05	Accident Photo	0	Load JPG	50
9	08/02/19 09:05	Accident Photo	0	Load JPG	V
10	08/02/19 09:05	Accident Photo	0	Load JPG	W
11	08/02/19 09:05	Accident Photo	0	Load 3PG	V
12	08/02/19 09:05	Accident Photo	0	Load JPG	V
13	08/02/19 09:05	Accident Photo	0	Load JPG	50
14	08/02/19 09:05	Accident Photo	0	Load JPG	V
15	08/02/19 09:05	Accident Photo	0	Load JPG	2
16	08/02/19 09:05	Accident Photo	0	Load JPG	N
17	08/02/19 09:05	Accident Photo	0	Load JPG	V
18	08/02/19 09:05	Accident Photo	0	Load JPG	2
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	100000
1	11/04/19 10:34	General View	0	Load JPG	V
2	11/04/19 10:34	General View	0	Load 3PG	W
3	11/04/19 10:34	General View	0	Load JPG	3
4	11/04/19 10:34	General View	0	Load 3PG	V
S	11/04/19 10:34	General View	0	Load 3PG	V
6	11/04/19 10:34	General View	0	Load JPG	V
7	11/04/19 10:34	General View	0	Load 3PG	1
8	11/04/19 10:34	General View	0	Load JPG	V
9	11/04/19 10:34	General View	0	Load 3PG	\square
10	11/04/19 10:34	General View	0	Load JPG	3
11	11/04/19 10:34	General View	0	Load JPG	☑
12	11/04/19 10:34	General View	0	Load JPG	V
13	11/04/19 10:34	General View	0	Load JPG	V
14	11/04/19 10:34	General View	0	Load JPG	52
15	11/04/19 10:34	General View	0	Load JPG	1

Merimen e-Claims Page 2 of 4

Ass	essment Reports		1 per page	v 5
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbn	and the second
16	11/04/19 10:34	General View	● Load JP	G ⋤
17	11/04/19 10:34	General View	■ Load JP	G E
18:	11/04/19 10:34	General View	■ Load JP	G E
19.	11/04/19 10:34	General View	■ Load JP	G 🔽
20	11/04/19 10:34	General View	■ Load 3P	G 🖫
21	11/04/19 10:34	General View	Load 3P	G ⋤
22	11/04/19 10:34	General View	■ Load JP	G E
23	11/04/19 10:34	General View	● Load 3P	G E
24	11/04/19 10:34	General View	1 Load JP	G 5
15	11/04/19 10:34	General View	1 Load JP	G 5
26	11/04/19 10:34	General View	Load 3P	G 5
27	11/04/19 10:34	General View	Load JP	G 5
28	11/04/19 10:34	General View	6 Load JP	G 5
29	11/04/19 10:34	General View	D Load 3P	-
30	11/04/19 10:34	General View	D Load 3P	G S
31	11/04/19 10:34	General View	Load JP	
32	11/04/19 10:34	General View	Load JP	
33.	11/04/19 10:34	General View	■ Load JP	
34	11/04/19 10:34	General View	■ Load 3P	- 40
35	11/04/19 10:34	General View	■ Load 3P	
36	11/04/19 10:34	General View	Load JP	
37	11/04/19 10:34	General View	■ Load 3P	
18	11/04/19 10:34	General View	Load JP	-
39	11/04/19 10:34	General View	■ Load 3P	-
40	11/04/19 10:34	General View	■ Load 3P	-
41	11/04/19 10:34	General View	■ Load 3P	-
42	11/04/19 10:34	General View	■ Load 3P	
43	11/04/19 10:34	General View	Load JP	-
44	11/04/19 10:36	Reinspection Photo	O Load 3P	
45	11/04/19 10:36	Reinspection Photo	D Load JP	-
46	11/04/19 10:36	Reinspection Photo	O Load JP	- 4
47	11/04/19 10:36	Reinspection Photo	D Load 3P	
48	11/04/19 10:36	Reinspection Photo	3 Load 3P	-
***		Reinspection Photo	B Load JP	-
49 50	11/04/19 10:36	Reinspection Photo	Load JP	
C1 1 14	11/04/19 10:36	Particular annual mana	O Load JP	
51	11/04/19 10:36	Reinspection Photo	F4V 59800	-
52	11/04/19 10:36	Reinspection Photo		-
53	11/04/19 10:36	Reinspection Photo		_
54	11/04/19 10:36	Reinspection Photo	O Load 3P	
55	11/04/19 10:36	Reinspection Photo	O Load 3P	-
56	11/04/19 10:36	Reinspection Photo	■ Load JP	-
57	11/04/19 10:36	Reinspection Photo	■ Load JP	_
58	11/04/19 10:36	Reinspection Photo	O Load 3P	_
59	11/04/19 10:36	Reinspection Photo	O Load 3P	
50	11/04/19 10:36	Reinspection Photo	€ Load 3P	
51	11/04/19 10:36	Reinspection Photo	1 Load 3P	_
62	11/04/19 10:36	Reinspection Photo	1 Load 3P	-
53	11/04/19 10:36	Reinspection Photo	€ Load 3P	-
64	11/04/19 10:36	Reinspection Photo	■ Load JP	
55	11/04/19 10:36	Reinspection Photo	■ Load JP	G E

Ass	essment Reports		1 per page 🔍	of .
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbna Load JPG	de de la facilitation de la constante
66	11/04/19 10:36	Reinspection Photo		1 131
67	11/04/19 10:36	Reinspection Photo	Load JPG	-
68	11/04/19 10:36	Reinspection Photo	1 Load JPG	_
69	11/04/19 10:36	Reinspection Photo	● Load JPG	-
70	11/04/19 10:36	Reinspection Photo	■ Load 3PG	-
71	11/04/19 10:36	Reinspection Photo	Load JPG	-
72	11/04/19 10:36	Reinspection Photo	■ Load JPG	
73	11/04/19 10:36	Reinspection Photo	Load 3PG	
74	11/04/19 10:36	Reinspection Photo	■ Load JPG	-
75	11/04/19 10:36	Reinspection Photo	1 Load JPG	1000
76	11/04/19 10:36	Reinspection Photo	■ Load 3PG	V
77	11/04/19 10:36	Reinspection Photo	Load JPG	V
78	11/04/19 10:36	Reinspection Photo	Load JPG	1
79	11/04/19 10:36	Reinspection Photo	■ Load JPG	V
80	11/04/19 10:36	Reinspection Photo	Load 3PG	V
81	11/04/19 10:36	Reinspection Photo	Load JPG	V
82	11/04/19 10:36	Reinspection Photo	■ Load JPG	150
83	11/04/19 10:36	Reinspection Photo	■ Load 3PG	V
84	11/04/19 10:36	Reinspection Photo	■ Load JPG	1
85	11/04/19 10:36	Reinspection Photo	Load 3PG	
86	11/04/19 10:36	Reinspection Photo	■ Load JPG	-
87	11/04/19 10:36	Reinspection Photo	Load 3PG	-
88	11/04/19 10:36	Reinspection Photo	Load JPG	1
89	11/04/19 10:36	Reinspection Photo	Load 3PG	_
90	11/04/19 10:36	Reinspection Photo	O Load 3PG	1-
91	11/04/19 10:36	Reinspection Photo	D Load JPG	-
			D Load JPG	-
92	11/04/19 10:36	Reinspection Photo	Load JPG Load JPG	1
93	11/04/19 10:36	Reinspection Photo		
94	11/04/19 10:36	Reinspection Photo	O Load JPG	_
95	11/04/19 10:36	Reinspection Photo	O Load 3PG	-
96	11/04/19 10:36	Reinspection Photo	1 Load JPG	-
97	11/04/19 10:36	Reinspection Photo	1 Load 3PG	-
98	11/04/19 10:36	Reinspection Photo	■ Load 3PG	-
99	11/04/19 10:37	Reinspection Photo	Load 3PG	_
100	11/04/19 10:37	Reinspection Photo	1 Load 3PG	
101	11/04/19 10:37	Reinspection Photo	Load 3PG	
102	11/04/19 10:37	Reinspection Photo	■ Load 3PG	-
103	11/04/19 10:37	Reinspection Photo	Load 3PG	-
104	11/04/19 10:37	Reinspection Photo	1 Load JPG	_
105	11/04/19 10:37	Reinspection Photo	1 Load JPG	
106	11/04/19 10:37	Reinspection Photo	1 Load JPG	-
107	11/04/19 10:37	Reinspection Photo	1 Load JPG	-
106	11/04/19 10:37	Reinspection Photo	■ Load JPG	1
109	11/04/19 10:37	Reinspection Photo	Load 3PG	-
110	11/04/19 10:37	Reinspection Photo	■ Load JPG	2
111	11/04/19 10:37	Reinspection Photo	■ Load 3PG	-
112	11/04/19 10:37	Reinspection Photo	■ Load 3PG	V
113	11/04/19 10:37	Reinspection Photo	■ Load 3PG	2
114	11/04/19 10:37	Reinspection Photo	1 Load JPG	V
115	11/04/19 10:37	Reinspection Photo	● Load 3PG	12

Merimen e-Claims Page 4 of 4



Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured,	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607 198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/SMO19002254/UVD3E2

Date:

24/04/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No:

D18MTPV01018425

Claimant Vehicle

SDS3338J

Insured Vehicle No : SLU2711R

No: Date of Loss:

04/02/2019

Nature of Claim:

TP

Claim No: CMTD1900746

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SDS3338J

Make & Model:

BMW 5281, 2.0 D/AB 2WD 4DR GAS/D NAV (A)

Engine No:

A2200840N20B20A

Reg. Date:

18/07/2014 (Man. Year. 2014) Grey

Chassis No: Odometer:

WBASZ620X0DZ35949 62015 km

Colour: Engine Capacity:

1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

245/45 R18

Rear Tyre Size:

275/40 R18

Front Left Side:

Pirelli 6 mm

Rear Left Side: Rear Right Side: Pirelli 6 mm Pirelli 6 mm

Front Right Side: Pirelli 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		27,646.76	14,096.12	13,550.64	49.01
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,120.00	2,020.00	2,100.00	50.97
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	31,766.76	16,116.12	15,650.64	49.27
	Approved Total (Overridden) (S\$)		12,800.00		
	Nett Amount (S\$)	31,766.76	12,800.00	18,966.76	59.71

INSPECTION

Date of Assignment:

08/02/2019

Date Inspected:

21/02/2019 Inspected At:

303 Alexandra Road, Sime Darby

Performance Centre

Singapore 159941

Repairer : CENTRE LINE CAR SPRAY

PAINTING

Estimated Period of Repair:

7.0 days

Adjuster: MARCUS CHUA

Manager:

VERON CHEN

Adjuster Report Page 2 of 5 NOTE. This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Referen	ce	
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2019)
Parts:	143	BMW 528I 2.0 D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted	, no print-code for SDS3338J)
Validity:		ates are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values	not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,562.10 FL	*1,362.10 FL
2	1		*FRONT BUMPER BMW LOGO	Necessary	85.58 FL	*71.25 FL
3	1		*FRONT BUMPER FOG LAMP - LH	Not Necessary	551.95 FL	*-FL
4	1		*FRONT BUMPER FOG LAMP GRILLE	Missing	89.65 FL	*68.90 FL
5	1		*FRONT BUMPER CHROME MOULDING - LH	Missing	120.35 FL	*55.65 FL
6	1		*FRONT BUMPER PDC SENSOR (2PCS)	Shorted-1PC ONLY	627,50 FL	*285.40 FL
7	1		*FRONT BUMPER SPRAY NOZZLE COVER	Not Necessary	62.15 FL	*-FL
8	1		*FRONT BUMPER TOP SEAL	Necessary	89.95 FL	*68.90 FL
9	1		*FRONT BUMPER SPONGE	Torn	130.95 FL	*130.95 FL
10	1		*FRONT BUMPER CARRIER	Not Necessary	785.50 FL	*-FL
11	1		*FRONT BUMPER SIDE BRACKET - LH	Cracked	89.60 FL	*89.60 FL
12	10		*FRONT BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
13	1		*FRONT BUMPER BOTTOM MOUNT	Not Necessary	164.65 FL	*-FL
14	1		*FRONT BUMPER BOTTOM DEFORMATION ELEMENT	Not Necessary	106,35 FL	*-FL
15	1		*FRONT FENDER - LH	Distorted	899.55 FL	*804.50 FL
16	1		*FRONT FENDER EMBLEM	Necessary	91.50 FL	*75.00 FL
17	1		*FRONT FENDER INNER SHIELD	Torn	142.63 FL	*106.35 FL
18	1		*FRONT FENDER INNER SHIELD EXTENSION	Torn	128.65 FL	*128.20 FL
19	15		*FRONT FENDER INNER SHIELD PLUG	Necessary	67.50 FL	*67.50 FL
20	1		*FRONT FENDER STAY	Not Necessary	86.50 FL	*-FL
21	6		*FRONT FENDER TOP COVER PLUG	Not Necessary	33.00 FL	*-FL
22	1		*FRONT HEADLAMP HID - LH	Cracked	4,556.90 FL	*4,203.70 FL
23	1		*FRONT HEADLAMP H.I.D CONTROL UNIT	Shorted	861.50 FL	*861.50 FL
24	1		*FRONT HEADLAMP H.I.D BULB	Not Necessary	481.90 FL	*-FL
25	1		*FRONT HEADLAMP L.E.D LIGHT	Not Necessary	560.90 FL	*-FL
26	1		*FRONT HEADLAMP L.E.D CONTROL	Shorted	767.30 FL	*767.30 FL
27	1		*FRONT HEADLAMP FRAME BRACKET	Cracked	189.60 FL	*189.60 FL
28	1		*FRONT HEADLAMP SPRAY NOZZLE PEN	Not Necessary	195.50 FL	*-FL
29	1		*FRONT HEADLAMP SPRAY NOZZLE HOSE	Not Necessary	162.60 FL	*-FL
30	1		*FRONT SPORT WHEEL - LH	Dented / Bent	1,560.50 FL	*1,308.60 FL
31	1		*FRONT SHOCK ABSORBER - LH	Bent	1,655.95 FL	*805.75 FL
32	1		*FRONT SHOCK ABSORBER TOP MOUNT	Not Necessary	215.20 FL	*-FL
33	1		*FRONT SHOCK ABSORBER STOPPER	Not Necessary	142.20 FL	*-FL
34	1		*FRONT WISHBONE - TOP	Bent	659.50 FL	*555.75 FL
35	1		*FRONT WISHBONE - LOWER	Bent	680.60 FL	*606.25 FL
36	1		*FRONT STABILIZER BAR	Not Necessary	481.90 FL	*-FL
37	1.		*FRONT STABILIZER BAR LINK	Not Necessary	141.30 FL	*-FL
			Report was unsubmitted during t	his print-put		

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*FRONT KNUCKLE ARM	Bent	1,265.50 FL	*1,105.00 FL
39	1		*FRONT WHEEL HUB BEARING	Damaged	581.90 FL	*503.00 FL
40	1		*FRONT ELECTRICAL STEERING RACK (LOCAL REPAIR)	Bent	4,570.12 FS	*200.00 FS
41	1		*FRONT TIE ROD - R/L	N/S Bent	723.50 FL	*361.75 FL
42	1		*FRONT AXLE CARRIER	Not Necessary	1,551.60 FL	*-FL
43	1	527	*FRONT TYRE	Serviceable	850.00 FS	*-FS
Fakro	nchise	part. S=5	SpcNett, L=ListItemDisc.	Sub Total (S\$)	28,816.58	14,827.50
			- List Item Discount on L I	tems 5.00/5.00% (S\$)	1,169.82	731.38
				Total Parts (S\$)	27 646 76	14,096.12

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOWING CHARGES	New	300.00	120.00
2	TO REMOVE, REFIX F/UNDERCARRIAGE	New	650.00	300.00
3	TO CHECK WHEEL ALIGNMENT	New	150.00	120.00
4	TO CHECKING F/ELECTRICAL WIRING	New	50.00	30.00
5	TO DIGNOS ERASE FAULT MEMORY AFTER REPAIR	New	450.00	100.00
6	TO RESPRAY UNDERCOATING	New	120.00	30.00
7	TO RESPRAY PAINTING AND ETC	New	1,200.00	800.00
8	PANEL BEATING, CUT, WELD, REMOVE AND REPLACING ABOVE PARTS	New	1,200.00	520.00
	Gross Labour Cost (S\$)		4,120.00	2,020.00
	Report was unsubmitted during	g this print-out.		

< END OF ESTIMATES >