

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 12 Feb 2019

**Preliminary Advice**

Insured Vehicle No	: FBD2420M	Accident Date	: 02/02/2019
TP Vehicle No	: SHD175M	Assignment Date	: 08/02/2019
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 2.00
Date of Inspection	: 11/02/2019		
Inspection At	: TRANS-CAB AUTO SERVICES PTE LTD (ANG MO KIO) 2, ANG MO KIO STREET 63 SINGAPORE 569111		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,853.26
Revised Amount	:S\$	900.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	900.00

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The above survey was conducted on a 'Without Prejudice' basis.