

2/03/2003

ASS. REC. BY:

REF:

CS/SM019002264/Ksd3

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Groh pauloong

of

SMO

Date/Time:

8/2/19 @ 11.25am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SHD 175M

Insured:

FRD 2420M

at Workshop m/s

Trans-Cab Auto

Tel:

62876666

of

No. 2 Amk st. 63

Policy No.:

D18MTMCO1007655

Claim No.:

CMTD1900757

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/02/2019

CA / REV / REP. / REV 24 HRS up

H.O.D. Endorsement:

Date/Time:

11:31am @ 8/2/19

Person Contacted:

Candy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 175M - CS / SM018023182 / Ksbn2

Don: 24/12/18

FRD 2420M - X

12/2/19

Send preli. revised via merimen

ASS. REC. BY:

REF:

Smo/

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / PWS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.:

Yes or No

Lum Sum:

20 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S140 175M

Yr Regn:

09, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude c.c.

1995

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

411852

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

V17 ABL 15 AUG 282198

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Mod:

N/A / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Giti

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

2/2/19

D.O.I.

11/2/19

Survey held at

Des. of Damages:

Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S bay

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 / File pass to  
B900

final Ag \$900 (Red, \$32953.26, 97.9%)

RECEIVED 14 FEB 2019

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

450

S - RS. SI

10

Fixtures

Others

TOTAL

460

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

900/ =

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 12 Feb 2019

**Preliminary Advice**

Insured Vehicle No : FBD2420M

TP Vehicle No : SHD175M

Accident Date : 02/02/2019

Make : RENAULT LATITUDE

Assignment Date : 08/02/2019

Date of Inspection : 11/02/2019

Est. Duration of Repair : 2.00

Inspection At : TRANS-CAB AUTO SERVICES PTE LTD (ANG MO KIO)  
2, ANG MO KIO STREET 63  
SINGAPORE 569111

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,853.26
Revised Amount	:S\$	900.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	900.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : The above survey was conducted on a 'Without Prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Feb 2019		08 Feb 2019 11:25 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TIO LAI HON, ID: S87770101		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD175M	Date of Loss:	02/02/2019 12:00 - :59
Claim Type:	TP / CMTD1900757	Policy/Cover Note No.:	D18MTMC01007655 (Thrd Party Only)
Vehicle Reg. No. (Insured):	FBD2420M	Policy No. (Claimant):	
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/02/2019]		
Adj Asg. Remarks:	-PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

**Vehicle Details**

Vehicle No.:	SHD175M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Feb 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002700
Chassis No.:	VF1ABL15AUC282198
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	10 Sep 2015
First Registration Date:	10 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Sep 2023
PARF Rebate Amount:	\$14,998.00

**Intended COE Rebate Details**

COE Expiry Date:	09 Sep 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$47,373.00
COE Rebate Amount:	\$27,173.00
<b>Total Rebate Amount:</b>	<b>\$42,171.00</b>

**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Feb 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/02/2019 13:44
Date Of Accident	02/02/2019 12:45
Exact Location Of Accident	PUNGGOL WALK SLIP ROAD TOWARDS PUNGGOL FIELD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD175M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	LEK THIANG NGUAN
NRIC No	S1648510A
Date Of Birth	16/08/1964
Occupation	OUTDOOR
Date Of Driving Pass	28/11/1983
Driving Experience	35 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91802864
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 243 SIMEI STREET 5 #08-20
Postcode	520243
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ZUHAI RI - 9195011 GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 02.02.2019 at about 1245hours, I was travelling straight along Punggol Walk slip Road towards Punggol Field when I slow down to check for the road clearance. While stationary, suddenly I felt an impact. Vehicle B (FBD2420M) hit onto my taxi's left side portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBD2420M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	TIO LAI HON
NRIC/Passport Number	G8288134X
Contact Number	90396262
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)



**SKETCH PLAN**


**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

plz see attach to A Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 175M****AAD1902-038***Not Notarised  
64 Sep 8900h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHD 175M**

VF1ABL15AUC282198

RENAULT

LATITUDE

2.2.2019

**SOMPO**

10/9/2015

**PART****LIST**

1	DOOR PANEL FRT LH	\$	<i>N</i> 2,844.66	}	<i>X</i>
1	DOOR HINGE UPPER LH	\$	<i>N</i> 261.28		
1	DOOR HINGE LOWER LH	\$	<i>N</i> 300.55		
1	DOOR CHECK FRT LH	\$	<i>Sn</i> 194.77		
1	DOOR LOCK FRT LH	\$	<i>N</i> 908.75		
1	DOOR CATCH FRT LH	\$	<i>Sn</i> 131.23		
1	DOOR HANDLE OUTER FRT LH	\$	<i>Sn</i> 477.76		
1	DOOR HANDLE COVER FRT LH	\$	<i>Sn</i> 13.22		
1	DOOR HANDLE MODULE FRT LH	\$	<i>Sn</i> 133.60		
1	DOOR REGULATOR FRT LH	\$	<i>Sn</i> 505.19		
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>Sn</i> 796.46		
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>Sn</i> 120.97		
1	DOOR PANEL REAR LH	\$	<i>N</i> 2,844.66		
1	DOOR GUIDE REAR LH	\$	<i>Sn</i> 176.82		
1	DOOR HINGE UPPER LH	\$	<i>N</i> 274.50		
1	DOOR HINGE LOWER LH	\$	<i>N</i> 300.55		
1	DOOR CHECK REAR LH	\$	<i>Sn</i> 203.06		
1	DOOR LOCK REAR LH	\$	<i>N</i> 908.75		
1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i> 126.49		
1	DOOR HANDLE CAP REAR LH	\$	<i>Sn</i> 35.52		
1	DOOR HANDLE SEAL REAR LH	\$	<i>Sn</i> 7.89		
1	DOOR HANDLE COVER REAR LH	\$	<i>Sn</i> 13.22		
1	DOOR HANDLE MODULE REAR LH	\$	<i>Sn</i> 133.60		
1	DOOR REGULATOR REAR LH	\$	<i>Sn</i> 1,135.10		
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>Sn</i> 893.75		

**Trans-cab Auto Services Pte Ltd****AAD1902-038**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 175M**

1	DOOR REGULATOR NUT REAR LH	\$	Sn 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	Sn 6.31
1	DOOR FINISHER REAR LH	\$	Sn 423.10
1	DOOR MOULDING REAR LH	\$	Sn 176.82
1	DOOR MOULDING CLIP L70Y	\$	nn 5.92
1	DOOR MOULDING SCREW L70Y	\$	Sn 6.91
1	DOOR CASING REAR LH	\$	Sn 1,509.06
1	DOOR WATER SHIELD REAR LH	\$	Sn 30.39
1	DOOR CASING CLIP	\$	nn 12.63
1	DOOR CASING LIGHT L70Y	\$	Sn 48.74
1	DOOR FINISHER INNER REAR LH	\$	Sn 323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 20.33
1	DOOR GRAB HANDLE REAR LH	\$	Sn 210.96
1	DOOR BLIND REAR LH	\$	Sn 741.80
1	DOOR WHEATHESTRIP REAR LH	\$	Sn 410.66
1	DOOR SEAL REAR LH	\$	Sn 162.02
1	DOOR GLASS RUNNER SEAL REAR LH	\$	Sn 229.31
1	DOOR WAIST SEAL OUTER REAR LH	\$	Sn 334.69
1	DOOR WAIST SEAL INNER REAR LH	\$	Sn 115.64
1	FENDER PANEL REAR LH	\$	n 3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	Sn 671.45
1	WHEELARCH REAR LH	\$	Sn 543.47
1	DOOR MIRROR ASSY LH	\$	Sn 1,483.40
1	ROCKER PANEL INNER GARNISH LH	\$	Sn 466.51
1	ROCKER PANEL INNER LH	\$	n 1,024.79
1	ROCKER PANEL CENTER LH	\$	n 990.25

	\$	27,090.14
10%	\$	2,709.01
	\$	24,381.13

**Trans-cab Auto Services Pte Ltd**

AAD1902-038

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 175M

**Special Nett**

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	}	X
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00		
1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	}	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00		
1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00		
1	REAR DOOR STICKER '6555 3333'	\$	nn	80.00	}	X
1	DOOR CHECK BOLT	\$	nn	22.69		
1	DOOR GUIDE SCREW	\$	nn	10.85		
1	DOOR HINGE BOLT	\$	nn	10.85	}	X
1	DOOR HINGE NUT RH	\$	nn	14.60		
1	DOOR CHECK BOLT	\$	nn	22.69		
1	DOOR CHECK NUT	\$	nn	3.75	}	X
1	DOOR LOCK SCREW L70Y	\$	nn	6.12		
1	DOOR CATCH SCREW L70Y	\$	nn	10.06		

<b>TOTAL</b>	<b>\$</b>	<b>462.13</b>
--------------	-----------	---------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>24,843.26</b>
--------------------	-----------	------------------

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	400
Putty and spray painting of the affected portion.	\$	3,000.00	4401
To rust-proofing of the affected areas.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X

**Trans-cab Auto Services Pte Ltd****AAD1902-038**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 175M**

To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	5 380.00	X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	5 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	5 170.00	X
To Check Electrical Lighting Concerned.	\$	5 170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	5 380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	5 380.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	5 380.00	X

**TOTAL \$ 9,010.00****Over All Total \$ 33,853.26****PART-BY-PART (REPAIR DAY)****10 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19002264/KSD3N2

Date: 14/02/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTMC01007655
Claimant Vehicle No :	SHD175M	Insured Vehicle No :	FBD2420M
Date of Loss:	02/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1900757

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHD175M	Engine No:	M9R8839C002700
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC282198
Reg. Date:	10/09/2015 (Man. Year: 2015)	Odometer:	411852 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 7 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,843.24	60.00	24,783.24	99.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,010.00	840.00	8,170.00	90.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>33,853.24</b>	<b>900.00</b>	<b>32,953.24</b>	<b>97.34</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>2,369.73</b>	<b>63.00</b>	<b>2,306.73</b>	<b>97.34</b>
<b>Nett Amount (\$\$)</b>	<b>36,222.97</b>	<b>963.00</b>	<b>35,259.97</b>	<b>97.34</b>

## INSPECTION

Date of Assignment:	08/02/2019	
Date Inspected:	11/02/2019	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 14 Feb 2019)
<b>Parts:</b> 143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHD175M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
2	1		*DOOR HINGE UPPER LH	Repair	261.28 FL	*- FL
3	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
4	1		*DOOR CHECK FRT LH	Serviceable	194.77 FL	*- FL
5	1		*DOOR LOCK FRT LH	Repair	908.75 FL	*- FL
6	1		*DOOR CATCH FRT LH	Serviceable	131.23 FL	*- FL
7	1		*DOOR HANDLE OUTER FRT LH	Serviceable	477.76 FL	*- FL
8	1		*DOOR HANDLE COVER FRT LH	Serviceable	13.22 FL	*- FL
9	1		*DOOR HANDLE MODULE FRT LH	Serviceable	133.60 FL	*- FL
10	1		*DOOR REGULATOR FRT LH	Serviceable	505.19 FL	*- FL
11	1		*DOOR REGULATOR MOTOR FRT LH	Serviceable	796.46 FL	*- FL
12	1		*DOOR REGULATOR GUIDE FRT LH	Serviceable	120.97 FL	*- FL
13	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
14	1		*DOOR GUIDE REAR LH	Serviceable	176.82 FL	*- FL
15	1		*DOOR HINGE UPPER LH	Repair	274.50 FL	*- FL
16	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
17	1		*DOOR CHECK REAR LH	Serviceable	203.06 FL	*- FL
18	1		*DOOR LOCK REAR LH	Repair	908.75 FL	*- FL
19	1		*DOOR HANDLE OUTER REAR LH	Serviceable	126.49 FL	*- FL
20	1		*DOOR HANDLE CAP REAR LH	Serviceable	35.52 FL	*- FL
21	1		*DOOR HANDLE SEAL REAR LH	Serviceable	7.89 FL	*- FL
22	1		*DOOR HANDLE COVER REAR LH	Serviceable	13.22 FL	*- FL
23	1		*DOOR HANDLE MODULE REAR LH	Serviceable	133.60 FL	*- FL
24	1		*DOOR REGULATOR REAR LH	Serviceable	1,135.10 FL	*- FL
25	1		*DOOR REGULATOR MOTOR REAR LH	Serviceable	893.75 FL	*- FL
26	1		*DOOR REGULATOR NUT REAR LH	Serviceable	12.43 FL	*- FL
27	1		*DOOR REGULATOR MOTOR SCREW REAR L70Y	Serviceable	6.31 FL	*- FL
28	1		*DOOR FINISHER REAR LH	Serviceable	423.10 FL	*- FL
29	1		*DOOR MOULDING REAR LH	Serviceable	176.82 FL	*- FL
30	1		*DOOR MOULDING CLIP L70Y	Not Necessary	5.92 FL	*- FL
31	1		*DOOR MOULDING SCREW L70Y	Serviceable	6.91 FL	*- FL
32	1		*DOOR CASING REAR LH	Serviceable	1,509.06 FL	*- FL
33	1		*DOOR WATER SHIELD REAR LH	Serviceable	30.39 FL	*- FL
34	1		*DOOR CASING CLIP	Not Necessary	12.63 FL	*- FL
35	1		*DOOR CASING LIGHT L70Y	Serviceable	48.74 FL	*- FL
36	1		*DOOR FINISHER INNER REAR LH	Serviceable	323.44 FL	*- FL
37	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	46.97 FL	*- FL
38	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL
39	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL
40	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL
41	1		*DOOR GRAB HANDLE REAR LH	Serviceable	210.96 FL	*- FL
42	1		*DOOR BLIND REAR LH	Serviceable	741.80 FL	*- FL
43	1		*DOOR WEATHERSTRIP REAR LH	Serviceable	410.66 FL	*- FL
44	1		*DOOR SEAL REAR LH	Serviceable	162.02 FL	*- FL

Report was unsubmitted during this print-out.



No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*DOOR GLASS RUNNER SEAL REAR LH	Serviceable	229.31 FL	*-FL
46	1	*DOOR WAIST SEAL OUTER REAR LH	Serviceable	334.69 FL	*-FL
47	1	*DOOR WAIST SEAL INNER REAR LH	Serviceable	115.64 FL	*-FL
48	1	*FENDER PANEL REAR LH	Repair	3,299.13 FL	*-FL
49	1	*FENDER PANEL INNER TRIM REAR	Serviceable	671.45 FL	*-FL
50	1	*WHEELARCH REAR LH	Serviceable	543.47 FL	*-FL
51	1	*DOOR MIRROR ASSY LH	Serviceable	1,483.40 FL	*-FL
52	1	*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	*-FL
53	1	*ROCKER PANEL INNER LH	Repair	1,024.79 FL	*-FL
54	1	*ROCKER PANEL CENTER LH	Repair	990.25 FL	*-FL
55	1	*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*-FS
56	2	*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*-FS
57	2	*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*-FS
58	1	*SET WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*-FS
59	1	*FRONT DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*-FS
60	1	*FRONT DOOR STICKER CLASSIS	Not Necessary	50.00 FS	*-FS
61	1	*REAR DOOR STICKER 65553333	Necessary	80.00 FS	*60.00 FS
62	1	*DOOR CHECK BOLT	Not Necessary	22.69 FS	*-FS
63	1	*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*-FS
64	1	*DOOR HINGE BOLT	Not Necessary	10.85 FS	*-FS
65	1	*DOOR HINGE NUT RH	Not Necessary	14.60 FS	*-FS
66	1	*DOOR CHECK BOLT	Not Necessary	22.69 FS	*-FS
67	1	*DOOR CHECK NUT	Not Necessary	3.75 FS	*-FS
68	1	*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	*-FS
69	1	*DOOR CATCH SCREW L70Y	Not Necessary	10.06 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>27,552.25</b>	<b>60.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>2,709.01</b>	<b>0.00</b>
<b>Total Parts (\$\$)</b>	<b>24,843.24</b>	<b>60.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,000.00	400.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
7	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
8	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
10	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
11	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
Gross Labour Cost (\$\$)			9,010.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >