

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CS/SMO19002264/KSD3N2  
**Date:** 27/05/2021

**REFERENCE**

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTMC01007655  
**Claimant Vehicle No :** SHD175M **Insured Vehicle No :** FBD2420M  
 Date of Loss: 02/02/2019 Nature of Claim: TP Claim No: CMTD1900757

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SHD175M**  
 Make & Model: RENAULT LATITUDE, 2.0 L (A) Engine No: M9R8839C002700  
 Reg. Date: 10/09/2015 (Man. Year: 2015) Chassis No: VF1ABL15AUC282198  
 Colour: Metallic White/Red Odometer: 411852 km  
 Engine Capacity: 1995 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16  
 Front Left Side: Giti 7 mm Rear Left Side: Giti 7 mm  
 Front Right Side: Giti 7 mm Rear Right Side: Giti 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	24,843.24	71.90	24,771.34	99.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,010.00	840.00	8,170.00	90.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>33,853.24</b>	<b>911.90</b>	<b>32,941.34</b>	<b>97.31</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>750.00</b>		
<b>(S\$)</b>	33,853.24	750.00	33,103.24	97.78
<b>+ GST 7.00/7.00% (S\$)</b>	2,369.73	52.50	2,317.23	97.78
<b>Nett Amount (S\$)</b>	<b>36,222.97</b>	<b>802.50</b>	<b>35,420.47</b>	<b>97.78</b>

**INSPECTION**

Date of Assignment: 08/02/2019  
 Date Inspected: 11/02/2019 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)  
 2, Ang Mo Kio Street 63  
 Singapore 569111  
 Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2021)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	<b>LKK Auto Consultants Pte Ltd/SHD175M/27/05/2021 16:08</b>	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
2	1		*DOOR HINGE UPPER LH	Repair	261.28 FL	*- FL
3	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
4	1		*DOOR CHECK FRT LH	Serviceable	194.77 FL	*- FL
5	1		*DOOR LOCK FRT LH	Repair	908.75 FL	*- FL
6	1		*DOOR CATCH FRT LH	Serviceable	131.23 FL	*- FL
7	1		*DOOR HANDLE OUTER FRT LH	Serviceable	477.76 FL	*- FL
8	1		*DOOR HANDLE COVER FRT LH	Missing	13.22 FL	*13.22 FL
9	1		*DOOR HANDLE MODULE FRT LH	Serviceable	133.60 FL	*- FL
10	1		*DOOR REGULATOR FRT LH	Serviceable	505.19 FL	*- FL
11	1		*DOOR REGULATOR MOTOR FRT LH	Serviceable	796.46 FL	*- FL
12	1		*DOOR REGULATOR GUIDE FRT LH	Serviceable	120.97 FL	*- FL
13	1		*DOOR PANEL REAR LH	Repair	2,844.66 FL	*- FL
14	1		*DOOR GUIDE REAR LH	Serviceable	176.82 FL	*- FL
15	1		*DOOR HINGE UPPER LH	Repair	274.50 FL	*- FL
16	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
17	1		*DOOR CHECK REAR LH	Serviceable	203.06 FL	*- FL
18	1		*DOOR LOCK REAR LH	Repair	908.75 FL	*- FL
19	1		*DOOR HANDLE OUTER REAR LH	Serviceable	126.49 FL	*- FL
20	1		*DOOR HANDLE CAP REAR LH	Serviceable	35.52 FL	*- FL
21	1		*DOOR HANDLE SEAL REAR LH	Serviceable	7.89 FL	*- FL
22	1		*DOOR HANDLE COVER REAR LH	Serviceable	13.22 FL	*- FL
23	1		*DOOR HANDLE MODULE REAR LH	Serviceable	133.60 FL	*- FL
24	1		*DOOR REGULATOR REAR LH	Serviceable	1,135.10 FL	*- FL
25	1		*DOOR REGULATOR MOTOR REAR LH	Serviceable	893.75 FL	*- FL
26	1		*DOOR REGULATOR NUT REAR LH	Serviceable	12.43 FL	*- FL
27	1		*DOOR REGULATOR MOTOR SCREW REAR L70Y	Serviceable	6.31 FL	*- FL
28	1		*DOOR FINISHER REAR LH	Serviceable	423.10 FL	*- FL
29	1		*DOOR MOULDING REAR LH	Serviceable	176.82 FL	*- FL
30	1		*DOOR MOULDING CLIP L70Y	Not Necessary	5.92 FL	*- FL
31	1		*DOOR MOULDING SCREW L70Y	Serviceable	6.91 FL	*- FL
32	1		*DOOR CASING REAR LH	Serviceable	1,509.06 FL	*- FL
33	1		*DOOR WATER SHIELD REAR LH	Serviceable	30.39 FL	*- FL
34	1		*DOOR CASING CLIP	Not Necessary	12.63 FL	*- FL
35	1		*DOOR CASING LIGHT L70Y	Serviceable	48.74 FL	*- FL
36	1		*DOOR FINISHER INNER REAR LH	Serviceable	323.44 FL	*- FL
37	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	46.97 FL	*- FL
38	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL
39	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL
40	1		*DOOR FINISHER BRACKET INNER REAR LH	Repair	20.33 FL	*- FL
41	1		*DOOR GRAB HANDLE REAR LH	Serviceable	210.96 FL	*- FL
42	1		*DOOR BLIND REAR LH	Serviceable	741.80 FL	*- FL
43	1		*DOOR WEATHERSTRIP REAR LH	Serviceable	410.66 FL	*- FL
44	1		*DOOR SEAL REAR LH	Serviceable	162.02 FL	*- FL
45	1		*DOOR GLASS RUNNER SEAL REAR LH	Serviceable	229.31 FL	*- FL
46	1		*DOOR WAIST SEAL OUTER REAR LH	Serviceable	334.69 FL	*- FL

LKK Auto Consultants Pte Ltd/SHD175M/27/05/2021 16:08. Not valid without Reference section.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*DOOR WAIST SEAL INNER REAR LH	Serviceable	115.64 FL	*- FL
48	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
49	1		*FENDER PANEL INNER TRIM REAR	Serviceable	671.45 FL	*- FL
50	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
51	1		*DOOR MIRROR ASSY LH	Serviceable	1,483.40 FL	*- FL
52	1		*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	*- FL
53	1		*ROCKER PANEL INNER LH	Repair	1,024.79 FL	*- FL
54	1		*ROCKER PANEL CENTER LH	Repair	990.25 FL	*- FL
55	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
56	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
57	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
58	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
59	1		*FRONT DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
60	1		*FRONT DOOR STICKER CLASSIS	Not Necessary	50.00 FS	*- FS
61	1		*REAR DOOR STICKER 65553333	Necessary	80.00 FS	*60.00 FS
62	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
63	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*- FS
64	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	*- FS
65	1		*DOOR HINGE NUT RH	Not Necessary	14.60 FS	*- FS
66	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
67	1		*DOOR CHECK NUT	Not Necessary	3.75 FS	*- FS
68	1		*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	*- FS
69	1		*DOOR CATCH SCREW L70Y	Not Necessary	10.06 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>27,552.25</b>	<b>73.22</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	2,709.01	1.32
<b>Total Parts (\$)</b>	<b>24,843.24</b>	<b>71.90</b>

LKK Auto Consultants Pte Ltd/SHD175M/27/05/2021 16:08. Not valid without Reference section.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,000.00	400.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
7	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
8	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
10	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
11	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>9,010.00</b>	<b>840.00</b>

LKK Auto Consultants Pte Ltd/SHD175M/27/05/2021 16:08. Not valid without Reference section.

< END OF ESTIMATES >