

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0158/2019/JE
Date : 4-Feb-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Dason Raj S/O Selva Raj
Address : 349A Joo Chiat Place
Singapore 428014
Telephone : (HP) 9693 6329
Type of Claim : Own Damage Claim
Policy No. : 1800035160
Vehicle No : **SLX 8613 K**
Model Code : Q7 2.0 TFSI Qu
Model / Year : 13/4/2018
Engine No : CYR 059826
Chassis No : WAUZZZ4M8JD034077
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 1-Feb-19
Place of Accident : Katong Shopping CTR CarPark Level 4

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLX 8613 K

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To remove and transfer aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,200.00 ✓
3	To dismantle front bumper, rhs front fender and headlight. Renew front lock carrier and align to position. Renew front bumper, rhs front fender and headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2500. 5,200.00
4	To remove and reinstall rhs front door board, to dismantle rhs side mirror assy to facilitate door respray.	S/N \$ 300 360.00 ✓
5	To respray front bumper, rhs front lower spoiler, rhs front fender and rhs front door. ✓	\$ 1650. 3,000.00
6	To renew rhs front tyre. Carry out wheel alignment. ✓	S/N \$ 280.00 ✓
7	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 10,712.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 8613 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,242.00	car ✓
2	FRONT BUMPER LOWER GRILLE GRILL	\$ 735.00	?
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 191.00	? car ✓
4	RADIATOR GRILLE	\$ 2,269.00	car ✓
5	FRONT BUMPER GRILLE ANTHRACITE - LOWER CENTRE	\$ 187.00	* ?
6	FRONT BUMPER FIXING PARTS	\$ 403.00	car ✓
7	FRONT AIR GUIDE - RHS	\$ 60.00	mis ✓
8	FRONT END CAP - RHS	\$ 32.00	car ✓
9	FRONT CLOSING ELEMENT - UPPER CENTRE	\$ 252.00	?
10	FRONT SPOILER ANTHRACITE - LH&RH	2 \$ 252.00	LH-X RH de ✓
11	FRONT SPOILER - RIGHT OUTER	\$ 40.00	art ✓
12	FRONT SPOILER - RH FRONT INNER	\$ 55.00	art ✓
13	AIR GUIDE GRILLE - CHROM - RH	\$ 31.00	?
14	FRONT SENSOR	2 \$ 462.00	X
15	SEAL RING	4 \$ 48.00	car ✓
16	FRONT BUMPER WIRING SET	\$ 582.00	X
17	FRONT FOAM FILLER	\$ 156.00	de ✓
18	FRONT BUMPER REINFORCEMENT	\$ 800.00	?
19	FRONT BUMPER SUPPORT - RH	\$ 33.00	X
20	FRONT BUMPER GUIDE SECTION - LH&RH	\$ 80.00	LH X, RH de ✓
SUB TOTAL PARTS CHARGES		\$ 8,910.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 8613 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER - RH	\$ 1,481.00	bt ✓
22	FRONT FENDER ATTACHMENT PARTS	\$ 69.00	X
23	FRONT FENDER REAR BRACKET - RH	\$ 56.00	ae ✓
24	FRONT FENDER CENTRE BRACKET - RH	\$ 59.00	ae ✓
25	FRONT FENDER BRACE - RH FRONT	\$ 94.00	bt ✓
26	WHEEL HOUSING LINER - RH	\$ 223.00	am ✓
27	WHEEL HOUSING LINER ATTACHEMENT PARTS	\$ 50.00	ae ✓
28	WHEEL HOUSING LINER - RH REAR	\$ 223.00	am ✓
29	WHEEL COVER - LH&RH FRONT	\$ 604.00	ae ✓
30	LED HEADLIGHT - RH	\$ 9,074.00	Cr 9 ✓
31	CONTROL UNIT LIGHT SYSTEM - RH	\$ 685.00	?
32	POWER MODULE - RH	\$ 716.00	?
33	HEADLIGHT FAN - RH	\$ 363.00	?
34	FRONT HORN - HIGH TONE RIGHT	\$ 206.00	X
35	FRONT HORN BRACKET	\$ 27.00	X
36	LOCK CARRIER WITH MOUNTING RADIATOR	\$ 1,100.00	ae ✓
37	FRONT HEADLIGHT MOUNTING - RH	\$ 107.00	ae ✓
38	FRONT AIR GUIDE - RH	\$ 25.00	?
39	FRONT AIR GUIDE - LOWER	\$ 37.00	?
40	FRONT TYRE " BRIDGESTONE "	\$ 1,358.00	
SUB TOTAL PARTS CHARGES		\$ 22,607.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLX 8613 K

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	FRONT NO PLATE	\$ 25.00	pe
42	SUNDIES	\$ 1,000.00	?
TOTAL PARTS CHARGES		:	\$ 32,542.00
TOTAL LABOUR CHARGES		:	\$ 10,712.00
GRAND TOTAL		:	\$ 43,254.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Tanpin 97495749
Ex : to be advise.
Revert. Not Authorise.
8/2/19 @ 3:50 pm
8 days
Resing before print

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd



Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant