LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building 51 Ubi Ave 1 #01-25
78 Shenton Way #08-16 Paya Ubi Industrial Park
Singapore 079120 Singapore 408933

Attn: Dally Amri, Mimi Zarina Date: 24 May 2019

Preliminary Advice

Vehicle No : SLX8613K **Accident Date** : 01/02/2019 Make : AUDI Q7 Policy No. : 1800035160 Assignment Date : 11/02/2019 **Excess** : S\$1,000.00 Est. Duration of Repair Date of Inspection : 08/02/2019 : 9.00

Inspection At : PREMIUM AUTOMOBILES PTE LTD (BENOI)

24 BENOI SECTOR SINGAPORE 629857

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,306.00 (inclusive supplementary)
Revised Amount	:S\$	22,981.16 (inclusive supplementary)
Check Items (Estimated)	·S\$	0.00

Check Items (Estimated) :S\$ 0.00
Total :S\$ 22,981.16

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value .5	New for Old Va	alue	:S\$
----------------------	----------------	------	------

 Pre-Accident Value
 :S\$
 235,000.00

 COE / PARF Rebate
 :S\$
 94,789.00

Salvage Value :S\$

Margin for Repair :S\$ 140,211.00

Remarks

(X)	The vehicle is repairable at our adjusted amount	. We have also co	onfirmed excess	and policy coverage.
	Kindly let us have your authorisation.			

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 761.20.