

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0146/2019/GW
Date : 01-Feb-19

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Bailey Cheryl Norma
Address : 21 Ridley Park Road
Singapore 248493
Telephone : 98395870
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No : **SKX 7748 Z**
Model Code : Audi Q3 1.4 TFSI
Model / Year : Dec-15
Engine No : CZD 216610
Chassis No : WAUZZZ8UXGR035706
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 27-Jan-19
Place of Accident : Lower Delta Road

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 7748 Z

<u>S/N</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper and lhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00 1000.
3	To respray front bumper, front bumper spoiler, lhs front fender and both front wheel arc covers.	\$ 3,200.00 1650.
4	To renew lhs front rim and carry out wheel alignment. ✓	S/N \$ 280.00 ✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 6,132.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 7748 Z

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,788.00	Rx
2	FRONT BUMPER FIXING PARTS	\$ 99.00	X
3	FRONT BUMPER AIR GUIDE GRILLE-LH	\$ 139.00	X
4	FRONT BUMPER SPOILER	\$ 527.00	X
5	FRONT FENDER -LH	\$ 824.00	bl ✓
6	FRONT FENDER ATTACHMENT PARTS-LH	\$ 63.00	hey ✓
7	FRONT WHEEL HOUSING LINER-LH	\$ 223.00	X
8	FRONT WHEEL HOUSING ATTACHMENT PARTS	\$ 139.00	X
9	FRONT WHEEL SPOILER-LH	\$ 66.00	X
11	FRONT WHEEL COVER-LH/RH	2 \$ 964.00	LH-at ✓, RH-hey ✓
12	FRONT ALUMINIUM-RH	\$ 694.00	X
13	RUBBER VALVE	\$ 4.00	X
14	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS		\$ 5,830.00	
TOTAL LABOUR CHARGES		\$ 6,132.00	
GRAND TOTAL		\$ 11,962.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tanpin 97495449
8/2/19 @ 4pm
Resing before paint
surellkhanta.com.
5 days
Not Authorise, Revert
Exp! to be advise.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd



Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant