

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

09 FEB 2019

Estimate No. : b1 50049
Date Estimated : 09/02/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Ngan Ka Lun, Karen (Yan JiaLun, Kare
1D CANTONMENT ROAD
#23-45

Singapore 085401

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLA4760R	K497879	01/03/2016	318iA/4Dr	0

DESCRIPTIONVALUE

Replacing front bumper panel and attachments, etc to knock
out dents caused by the accident

850 1,700.00

Spray front bumper

934 1,038.00

To replace right headlight.

481.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 177.00

Sundries

? 80.00

Total Labour 1: 3,476.00

DESCRIPTIONQTYPRICVALUE

FRT LH TOP SUPPORT SIDE PANEL

1

19.20

x 19.20

FRT RH TOP SUPPORT SIDE PANEL

1

19.20

? 19.20

FRT LH BOTTOM MOUNTING SIDE PANEL

1

19.20

x 19.20

FRT RH BOTTOM MOUNTING SIDE PANEL

1

19.20

? 19.20

FRT SHOCK ABSORBER ECE

1

54.50

? 54.50

FRT BUMPER PANEL PRIMED (BASIS)

1

978.35

de 978.35

GROMMET

2

0.75

ne 1.50

PLAQUE 82MM

1

71.25

ne 71.25

RH HEADLIGHT LED TECHNOLOGY

1

3,068.40

cna 3,068.40

Total Parts : 4,250.80