



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24  
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com  
Tel: 6286 6060 , FAX: 6286 7060

VEHICLE NUM: SJR 490 E  
MAKE & MODEL: TOYOTA RUSH  
MILEAGE:  
TYRE:  
CHASSIS NUM:

MP Allowed  
NKK  
4/5 @ 4000/  
11/2/19  
Tel: phs. Akharyp

10 day.

NO.	DESCRIPTION - PARTS	QTY	PRICE
1	REAR WINDSCREEN MOULDING 115.	1	\$ 190.00
2	TAILGATE	1	\$ 1,540.85
4	TAILGATE HINGE	2	\$ 248.80
5	TAILGATE LOCK	1	\$ 415.95
6	TAILGATE OUTER HANDLE	1	\$ 85.90
7	TAILGATE WEATHER STRIP	1	\$ 259.50
10	TAILGATE WIPER BLADE	1	\$ 68.90
11	TAILGATE WIPER MOTOR	1	\$ 831.50
12	TAILGATE WIPER ARM	1	\$ 134.50
13	TAILGATE INNER BOARD	1	\$ 793.20
14	TAILGATE LOCK GUIDE	1	\$ 241.95
15	TAILGATE CHECK	1	\$ 121.55
16	SPARE TYRE BRACKET	1	\$ 289.50
18	SPARE TYRE BASE	1	\$ 419.50
19	TAILLAMP	2	\$ 779.00
20	TAILLAMP COVER CHROME	2	\$ 200.00
21	TAILLAMP PANEL	2	\$ 269.80
22	REAR BUMPER	1	\$ 1,077.60
23	REAR BUMPER RETAINER	2	\$ 171.80
24	REAR BUMPER TOW HOOK COVER	1	\$ 65.90
25	REAR BUMPER REFLECTOR	2	\$ 171.80
26	REAR END PANEL OUTER	1	\$ 341.90
27	REAR END PANEL INNER	1	\$ 321.50
28	REAR END PANEL TOP GARNISH 241.10	1	\$ 381.80
29	REAR FLOOR PANEL	1	\$ 1,355.90
30	REAR FLOOR PANEL TOP BOARD	1	\$ 389.50
31	REAR FENDER	2	\$ 3,091.80
32	REAR FENDER INNER TRIM	2	\$ 1,551.80
33	REAR FENDER INNER SHIELD RH	1	\$ 151.90
34	REAR NO. PLATE LAMP	2	\$ 136.00
35	BONNET	1	\$ 1,195.90
36	BONNET LOCK	1	\$ 85.90
37	BONNET GRILLE	1	\$ 415.90
38	BONNET GRILLE LOGO	1	\$ 65.90
39	HEADLAMP L+R 871.10	1	\$ 2,578.01
40	FRONT BUMPER	1	\$ 995.45
41	FRONT BUMPER SIDE RETAINER L+R	1	\$ 131.80
42	FRONT BUMPER FOG LAMP L+R	1	\$ 645.00
43	FRONT BUMPER TOW HOOK COVER	1	\$ 48.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

6231.50

