

INS CASE OWNER:

CC 4, AIG 1900 2333, 11

LKK: IDAC:

Assignment: mTH DOI: 12/2/19 Date/Time: 4/2/19 Registered in Merimen: 11/2/19

Pre-assign / CCU / FTE

Insured Vehicle No.: SLL2576L Name of Insured: Christine Aguiar Can Claim No.: Policy No.: Insured Tel No.: HP: Make / Model: Excess Sec II :SS D.O.A.: 26/01/19 Place of Accident: Is driver the owner? (YES / NO) Nature of Accident: If NO, Driver Name / Age: Driver Tel No.: (V/L: YES / NO) OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO Insured Liability: % Final ? Yes / No

INSRS: WSP: Tel: Liability: RMKS: System motor trading

Table with columns: Date/Time, Description, STAGE, DATE / PIC. Includes entries for 4/1/19, 4/2/19, and 6/6/19 with descriptions like 'OI note on memo' and 'File -> MR to close'.

PRELIMINARY ADVICE, FINALIZATION, FINAL SETTLEMENT, FINAL PAYMENT sections. Includes fields for Date/Time, Confirm with, Repair Cost, Final Liability, Loss of Rental (LOR), Loss of Use (LOU), Loss of Income (LOI), Total, and Global Sum SS.

Tanpikha

REP

ALG

WE 2026 June

206 Jly

Form: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Loss: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Country (Vehicle ID): \_\_\_\_\_

Stock No: \_\_\_\_\_

Brand: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Client's Record: \_\_\_\_\_

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NIS	O/S
	X

Val or Market Value: 940k

ODAC: Accident Report Consistent? Yes or No

QA / PP: Seen Consistent? Yes or No

Est. Repair: 05 days Res: Yes or No

Loss sum: 20% 3 Val: Yes or No

CA / REV / REP / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time: \_\_\_\_\_ Action / Instruction: \_\_\_\_\_

Vehicle No: SCR 384L

Type:  Car /  Cycle /  Bus /  Van /  Lorry /  Truck /  Trailer or  Power Mower /  Truck /  Trailer or

Make: Mahindra Vios No: 1497

Colour: Maroon Insured / Stl / NI / NA

Sp Reading: 23295 Trade: Insured / Stl / NI / NA

Eng No: 1

C/Nr: MK053HY4704192909

Gen Cond:  Good /  Fair /  Poor /  Burnt

Steering:  In order /  Jammed /  Leaked /  Burnt or

Brake:  In order /  Jammed /  Leaked /  Burnt or

Mod:  Nil /  ABS /  STD A/Rim or

Tyre Size: F: 195/50R15  
R: ~ ~

BS / DUN / ESTIVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUM / TOYO / YOKO

Front		Rear
R/Bal	6 mm	R/Bal 6 mm
L/Bal	6 mm	L/Bal 6 mm

D.O.A: \_\_\_\_\_ D.O.I: 12/2/19 erwesp

Survey held at: System Motor Trading

Des. of Damages: Rear o/s  
Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Rebate: 934, 285.

US \$ 1500 (Red) \$ 2025-95/5797

File/Date: File Name:  - Prelim. Report  - Final Report

Days Of Repair: \_\_\_\_\_ Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  Site Insp: 15  Witness: 15  Fuel: 15  Discount: 15

Survey Fee: \_\_\_\_\_

Exp. of Normal: \_\_\_\_\_

Lamp Sign (T.B.T.): \_\_\_\_\_

**SYSTEM MOTOR TRADING**  
 Block 1002 Bukit Merah Lane 3 #01-73 Singapore 159719  
 Tel: 6274 2861

Date: 31 January 2019

**AIG Asia Pacific Insurance Pte. Ltd.**  
 78 Shenton Way  
 #07-16 AIG Building  
 Singapore 079120

Email: aigsgp\_claimssurvey@aig.com

98217725  
 My Lim  
 jillianyeo22@gmail.com

Dear Sir,

**RE: PRE- REPAIR ESTIMATE COST OF VEH. NO. SCR384L – (TOYOTA VIOS) -  
 ACCIDENT BETWEEN SCR384L & SLL2576L DATED 26/01/2019**


	<u>Parts</u>	<u>Unit Price</u>	<u>Total</u>
1pc	tail lamp RH	189.40	189.40 <i>my</i>
1pc	rear bumper	318.15	318.15 <i>de</i>
1pc	rear bumper retainer	32.00	32.00 <i>re</i>
1pc	rear fender RH	598.40	598.40 <i>cy</i>
1set	rear windscreen gum	80.00	80.00 <i>X ny</i>
1pc	windscreen inner seal	28.00	28.00 <i>X ny</i>
Total:			\$ 1,245.95
			539.55
			25% 404.66

**Labour Charges**

1.	To remove and re-fixing rear windscreen to facilitate repair etc.	150.00	<i>X ny</i>
2.	To repair rear accident area. To cut and replace rear RH fender and rear bumper and to repair rear panel and realign body parts and to change above necessary parts etc.	1,200.00	<i>700</i>
3.	To putty and re-spray rear accident repair effected necessary areas.	850.00	<i>700</i>
4.	To re-spray antirust under coating to repair and necessary parts.	80.00	<i>30</i>
		<u>\$ 3,525.95</u>	<i>1430</i>
			<i>1834.66</i>
			<i>4571500</i>

**NOTE: KINDLY CONTACT US AT 6274 2861 (JIMMY YEO) ARRANGE FOR YOUR SURVEYOR TO CONDUCT A PRE-REPAIR VEHICLE TO ENABLE FOR US TO PROCEED THE REPAIR**

Yours faithfully

  
 System Motor Trading

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Tanpin 97495709  
 'ur'  
 12/2/19 @ 1245  
 Resurvey after repair  
 sue@lkkauto.com  
 65 days





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG19002333/T1pa3

12 MARCH 2019

**CHRISTINE ANGELINEA LAU**  
BLK 164 GANGSA ROAD  
#23-82  
SINGAPORE 670164

Dear Sir/Madam,

**ACCIDENT INVOLVING SLL 2576L & SCR 384L ALONG/AT COMMONWEALTH AVE WEST ON 26/01/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SCR 384L against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as it is head-to-rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG  
Case Handler  
DID: 6742 3197  
FAX: 6741 4108  
Email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

## LETTER OF AUTHORISATION

Date: 30/01/2019

System Motor Trading  
Block 1002 Bukit Merah Lane 3  
#01-73  
Singapore 159719

Dear Sirs,

ACCIDENT ON 26/01/2019  
INVOLVING VEHICLE NO. SCR 384L & SLL 2576L  
ALONG Commonwealth Avenue West Towards Ghai Moh Road

I/We the registered owner/driver of vehicle registration No. SCR 384L have involved in the above accident. M/s System Motor Trading have my authority to proceed a claim against the insurance company AIG Asia Pacific Ins. Pte. Ltd arising from the accident occurred on 26/01/2019. I hereby authorise you to proceed with the repair on my vehicle.

Your kind co-operation in this matter will be much appreciated.

Yours faithfully,

Yap Yap Yoon Chiang.  
57587692 J.

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, SYSTEM MOTOR TRADING ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$1,500.00 (Repair Cost), S\$300.00 (Loss of Use/Rental), S\$ - (Disbursement) for vehicle no. SCR 384L that was damaged pursuant to the accident which occurred on 26/01/2019 (date) along COMMONWEALTH AVE WEST TOWARDS GHIM MOH ROAD (location) involving vehicle no/s SLL 2576L. This is pursuant to the inspection conducted on 12/02/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner YAP YOON CHIANG (the third party claimant") of vehicle no. SCR 384L make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SCR 384L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 11 (day) of Jun (month) 2019 (year)



Signed by appointed surveyor

**SYSTEM MOTOR TRADING**  
BLOCK 1002 BT. MERAH LANE 3  
#01-73  
SINGAPORE 159719  
DID : 6274 2861 W/SHOP : 6271 8621

Signed by "the workshop" (with chop)

## SYSTEM MOTOR TRADING

Block 1002 Bukit Merah Lane 3 #01-73 Singapore 159719  
Tel: 6274 2861

Date: 23 May 2019

AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079210

INV No. 1900910


Dear Sir,

**VEH. NO. SCR384L - TOYOTA VIOS - ACCIDENT BETWEEN SCR384L &  
SLL2576L DATED 26/01/2019**

Lump Sum recommended

\$1,500.00

Dollars: One thousand five hundred only.



System Motor Trading

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jan 2019 <a href="#">Edit Reg</a>		04 Feb 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$1,500.00</b> <a href="#">Edit Estimates</a>	<b>\$1,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>CHRISTINE ANGELINEA LAU</b> , ID: 574142322								
Main Claimant:	<b>YAP YOON CHIANG</b> , ID: S7587692J								
Vehicle Reg. No.:	<b>SCR384L</b>	Date of Loss:	26/01/2019 13:00 - :59 [150 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 5836256985SG</b>	Policy/Cover Note No.:	1800019036 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SLL2576L</b>	Policy No. (Claimant):	5I18V07384/VPE/R02						
		Excess:							
Repairer:	<b>System Motor Trading (HQ)</b> Blk 1002 Bukit Merah Lane 3, #01-73 ALEXANDRA VILLAGE INDUSTRIAL ESTATE, 159719 Bukit Merah - Tel: 6274-2861								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Kesaval, Jaclyn-M</b> ] Jaclyn-M.Kesaval@aig.com								
Claimant's Insurer:	<b>Liberty Insurance Pte Ltd (HQ)</b> - Tel: (65) 6221 8611								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 20/02/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SCR384L (5836256985SG)**  
**[SLL2576L]**  
**TP**  
**YAP YOON CHIANG**  
**Jan 26 2019 1:00PM**  
**[CHRISTINE ANGELINEA LAU]**  
**System Motor Trading**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <span style="float: right;">View in Browser</span>					
<b>Video</b>															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)									Thumbnail			Print						
1	08/04/19 18:08	<b>Video - Accident</b> <small>From:DD - Reg. No: SLL2576L, Claimant: CHRISTINE ANGELINEA LAU</small>									1 Load MP4									
<b>Letters/Correspondences</b>															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail			Print						
1	(Draft)	<b>Third Party Express Settlement - Payment Breakdown</b>									1 Edit									
<b>Photos/Images</b>															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail			Print						
1	11/03/19 16:25	<b>Odometer Reading</b>									1 Load JPG			<input checked="" type="checkbox"/>						
2	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
3	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
4	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
5	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
6	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
7	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
8	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
9	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
10	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
11	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
12	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
13	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
14	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
15	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
16	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
17	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
18	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
19	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
20	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
21	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
22	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
23	11/03/19 16:25	<b>General View</b>									1 Load JPG			<input checked="" type="checkbox"/>						
<b>Documentation</b>															1 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail			Print						
1	11/02/19 12:54	<b>ACKNOWLEDGEMENT EMAIL TO AIG DD 11.02.2019</b>									1 Load PDF									
2	11/02/19 12:54	<b>EMAIL FROM AIG DD 04.02.2019</b>									1 Load PDF									
3	11/02/19 12:54	<b>TP ESTIMATE + TP GIA REPORT</b>									1 Load PDF									
4	16/02/19 17:39	<b>TP ESTIMATE - MARKED</b>									1 Load PDF									
5	17/06/19 09:42	<b>WORKSHOP INVOICE</b>									1 Load PDF									

Video			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
6	17/06/19 09:42	<b>AUTHORISATION TO ACT FORM</b>		Load PDF	
7	17/06/19 09:42	<b>Release Voucher</b>		Load PDF	
8	17/06/19 09:42	<b>LETTER TO OI</b>		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	13/02/19 15:43	<b>OI GIA REPORT</b>		Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SLL2576L (Insd veh)	Model:	TOYOTA VIOS 1.5 E (M)
	SCR384L (TP veh)		
Date of Accident:	26/01/2019		

Global Sum Settlement	:	[ ] Yes	[ X ] No	
Repair Estimate	:	\$	3,525.95	
Final Repair Cost	:	\$	1,500.00	
Loss of Use	:	\$	300.00	5.00 days at \$60.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	0.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	1,800.00	
<b>Is Third Party Workshop GIA Registered?</b> [ ] YES [ X ] NO (Kindly indicate below)				
<b>A) For Non GIA Registered Workshop:</b>		Agreed Liability ____ 100 ____ (%)		
<b>B) For GIA Registered Workshop:</b>		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	System Motor Trading	:	\$ 1,800.00
2)		:	\$

\_\_\_\_\_  
JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

17 Jun  
2019

\_\_\_\_\_  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19002333/T1PA3Q2  
Date: 17/06/2019

## REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800019038
Claimant Vehicle No :	SCR384L	Insured Vehicle No :	SLL2576L
Date of Loss:	26/01/2019	Nature of Claim:	TP
		Claim No:	5836256985SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SCR384L	Engine No:	1NZX444806
Make & Model:	TOYOTA VIOS, 1.5 E (M)	Chassis No:	MR053HY4204192909
Reg. Date:	03/07/2006 (Man. Year: 2006)	Odometer:	23295 km
Colour:	Maroon		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,245.95	404.66	841.29	67.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,430.00	850.00	37.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,525.95</b>	<b>1,834.66</b>	<b>1,691.29</b>	<b>47.97</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>3,525.95</b>	<b>1,500.00</b>	<b>2,025.95</b>	<b>57.46</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>		<b>300.00</b>		
<b>Nett Liability (S\$)</b>		<b>1,800.00</b>		

## INSPECTION

Date of Assignment:	04/02/2019	
Date Inspected:	12/02/2019 Inspected At:	System Motor Trading (HQ) Blk 1002 Bukit Merah Lane 3, #01-73 ALEXANDRA VILLAGE INDUSTRIAL ESTATE Singapore 159719

Estimated Period of Repair: 5.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP RH	Cracked	189.40 F	*189.40 FL
2	1		*REAR BUMPER	Deformed	318.15 F	*318.15 FL
3	1		*REAR BUMPER RETAINER	Necessary	32.00 F	*32.00 FL
4	1		*REAR FENDER RH	Repair	598.40 F	*- FL
5	1		*SET REAR WINDSCREEN GUM	Not Necessary	80.00 F	*- FL
6	1		*WINDSCREEN INNER SEAL	Not Necessary	28.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,245.95</b>	<b>539.55</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00</b>	<b>134.89</b>
<b>Total Parts (\$\$)</b>	<b>1,245.95</b>	<b>404.66</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND RE-FIXING REAR WINDSCREEN TO FACILITATE REPAIR ETC	New	150.00	0.00
2	TO REPAIR REAR ACCIDENT AREA.TO CUT AND REPLACE REAR RH FENDER AND REAR BUMPER AND TO REPAIR REAR PANEL AND REALIGN BODY PARTS AND TO CHARGE ABOVE NECESSARY PARTS ETC	New	1,200.00	700.00
3	TO PUTTY AND RE-SPRAY REAR ACCIDENT REPAIR EFFECTED NECESSARY AREAS	New	850.00	700.00
4	TO RE-SPRAY ANTIRUST UNDER COATING TO REPAIR AND NECESSARY PARTS	New	80.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,280.00</b>	<b>1,430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >