

SYSTEM MOTOR TRADING

Block 1002 Bukit Merah Lane 3 #01-73 Singapore 159719
Tel: 6274 2861

Date: 31 January 2019

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Email: aigsgp_claimssurvey@aig.com

Dear Sir,

**RE: PRE-REPAIR ESTIMATE COST OF VEH. NO. SCR384L – (TOYOTA VIOS) -
ACCIDENT BETWEEN SCR384L & SLL2576L DATED 26/01/2019**


	<u>Parts</u>	<u>Unit Price</u>	<u>Total</u>
1pc	tail lamp RH	189.40	189.40 <i>my</i>
1pc	rear bumper	318.15	318.15 <i>de</i>
1pc	rear bumper retainer	32.00	32.00 <i>re</i>
1pc	rear fender RH	598.40	598.40 <i>roy</i>
1set	rear windscreen gum	80.00	80.00 <i>X ny</i>
1pc	windscreen inner seal	28.00	28.00 <i>X ny</i>
Total:			\$ 1,245.95
			<i>539.55</i>
			<i>25% 404.66</i>

Labour Charges

1.	To remove and re-fixing rear windscreen to facilitate repair etc.	150.00 <i>X ny</i>
2.	To repair rear accident area. To cut and replace rear RH fender and rear bumper and to repair rear panel and realign body parts and to change above necessary parts etc.	1,200.00 <i>700</i>
3.	To putty and re-spray rear accident repair effected necessary areas.	850.00 <i>600</i>
4.	To re-spray antirust under coating to repair and necessary parts.	80.00 <i>30</i>
		<i>1330</i>
		<u>\$ 3,525.95</u>
		<i>1734.66</i>

NOTE: KINDLY CONTACT US AT 6274 2861 (JIMMY YEO) ARRANGE FOR YOUR SURVEYOR TO CONDUCT A PRE-REPAIR VEHICLE TO ENABLE FOR US TO PROCEED THE REPAIR

Yours faithfully



System Motor Trading

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495709
'up'
12/2/19 @ 1245
Resy after repair
sur @ lkkauto.com
65 days

4581400#