

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

*Not Authorized
11 Days @?
Resony After Point
6 days*

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 02.02.2019

Accident Date : 01.02.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Chevrolet Cruze" Reg. No. SJT530M Claiming Against Your Insured Reg. No. SLQ1813H			
1pc	Boot		<i>By</i> 1,289.00 ✓
1pc	Boot Emblem		<i>M</i> 59.00 ✓
1pc	Boot Badge Chevrolet		<i>M</i> 27.00 ✓
1pc	Boot Badge Cruze		<i>M</i> 27.00 ✓
2pcs	Boot Lamps	205.00	<i>CM</i> 410.00 ✓
1pc	Boot Lock		<i>M</i> 94.50 ✓
1pc	Boot Lock Catch		<i>R</i> 28.00 X
1pc	Boot Weatherstrip		<i>Dis M</i> <i>Sea</i> 126.00 <i>R500in</i>
1pc	Boot Trim Board		<i>CM</i> <i>M</i> 110.00 ✓
9pcs	Boot Trim Board Clips	2.00	<i>M</i> 18.00 ✓
1pc	Boot Stopper RH		<i>M</i> 4.00 ✓
1pc	Boot Lock Cover		<i>Ad</i> 16.00 ✓
1pc	Rear Bumper		<i>By CM</i> 1,206.00 ✓
10pcs	Rear Bumper Clips	2.00	<i>M</i> 20.00 ✓
2pcs	Rear Bumper Brackets	85.00	170.00 ✓
2pcs	Rear Bumper Top Retainers	75.00	150.00 ✓
2pcs	Rear Bumper Reinforcement		<i>R</i> 595.00 ✓
2pcs	Rear Bumper Reverse Sensors	225.00	<i>Short</i> 450.00 ✓
4pcs	Rear Bumper Reverse Sensor Holders	15.00	60.00 ✓
2pcs	Rear Bumper Corner Retainers	73.00	<i>GRS D-1</i> 146.00 ✓
1pc	Rear Bumper Sensor Wiring Harness		196.00 ✓
1pc	End Panel		860.00 ✓
1pc	End Panel Garnish		<i>mjcm</i> 59.00 ✓
1pc	Spare Tyre Top Board		<i>CM</i> 312.00 ✓
1pc	Rear Fender Trim Board RH		<i>Sea</i> 253.00 X
2pcs	Taillamps Assy	635.00	<i>WT</i> 1,270.00 ✓
2pcs	Taillamps Assy Gaskets	18.00	<i>M</i> 36.00 ✓
			7,991.50
	Less 10%		799.15
			7,192.35
	To Conduct Electrical Check, Replace Reverse Sensors, Module, Rewiring, Reprogram PDC		<i>Fol</i> 120.00
	To Dismantle / Refit Tailgate Fittings / Ancillary Accessories		80.00 <i>501</i>
		C/F	7,392.35

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 02.02.2019

Accident Date : 01.02.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Chevrolet Cruze" Reg. No. SJT530M Claiming Against Your Insured Reg. No. SLQ1813H		
		B/F	7,392.35
	To Dismantle / Transfer Rear Spare Tyre Panel Inner Trims Boards / Garnish and Rear Fenders Inner Trims Boards / Garnish to Facilitate Repair		80.00 601
	To Supply End Panel Joint Sealant		60.00 301
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 601
	Labour Charge - Panel Beating, Repairing Of Rear Chassis Member, Inner Panel, Spare Tyre Panel, Floor Panel, Rear O/S Fender Etc. Cnt, Weld End Panel and Parts Replacement		1,000.00 6001
	To Respray Affected Areas		1,000.00 8001
		Total :	<u>9,632.35</u>

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: