

Steve (LKK)  
12/21/19  
P/P  
5 hrs

Ben

# Allswell Motor Traders

25 Defu Lane 9, Singapore 539266  
Tel : +65 6679 1146 email:ben@allswellmotor.com.sg

(3rd party claim against AXA Inamed SLQ612C )

**Estimate repair**

Vehicle No. : SKZ3370U Submitted by : Ben  
 Make & Model : Toyota Auris 1.6 CVT COE expiry : 18-01-2028  
 Chassis No. : \_\_\_\_\_ Engine No. : \_\_\_\_\_  
 Date of survey : \_\_\_\_\_

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01A	RH / LH fender (rear) x R	04/01	\$1,200.00		x Repair
01	Rear bumper / 00	01	\$1,027.00		
02	Rear sensor #150x2 ps. / 0R	01	\$300.00		
03	End panel / 00	01	\$525.00		
04	Rear boot x R	01	\$986.00		
05	Boot lock c/w casing / 0T	01	\$379.00		
06	Rear bumper / 0R	01	\$1,171.00		
07	Front chrome grille / 0R	01	\$515.00		
08	LH rear retainer / 0R	01	\$62.00		
09	RH rear retainer / 0R	01	\$62.00		
	Special net				
01	Clips / retainer studs for front / rear bumper @ \$72 / pkt NEC	01	\$72.00		
	Labour Description				
01	Dismantle / Assembly of all affected parts	01	\$800.00	x	
02	Panel beating / welding / repair / replace end panel & 02 fenders	01	\$1,200.00	/ 900	
03	Respray including putty, sandpaper, polish & wash of all affected parts	01	\$1,800.00	/ 1000	
	Supplementary				
01	License plate c/w casing CRU	01	\$65.00	35 /	
02	front bonnet 00	01	\$1,001.00	/	

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.