

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8828R

DATE 8/2/2019 10:24

MAKE :

MODEL : HYUNDAI i40

AVA
PIP

Chang

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille			\$ 1,110.10	✓CRIC
	Front Bumper Cover			\$ 1,052.20	✓R
	Front Bumper Sponge			\$ 99.20	✓SVC
	Front Bumper Reinforcement			\$ 402.10	✓SVC
	Front Bumper Bracket Top (LH/RH)		\$ 22.40	\$ 44.80	?
	Front Bumper Bracket (LH/RH)		\$ 24.60	\$ 49.20	?
	SUB TOTAL			\$ 2,757.60	
	LESS 20%			\$ 551.52	
	DISCOUNTED TOTAL			\$ 2,206.08	
	Labour Charge				
	Panel Beating			\$ 400.00	200
	Spray Painting Charge			\$ 300.00	200
	TOTAL LABOUR			\$ 700.00	
	ESTIMATE TOTAL			\$ 2,906.08	

NAZ LKIL
8/2/19 1215
PIP
2 DAYS
CHECK ITEMS (HOTO)
AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.