

AXA - JU
P/P

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7720S

DATE 8/2/2019 9:17

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 459.40 ?
	Rear Bumper Reinforcement			\$ 294.80 XSVL
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 138.10	\$ 276.20 XSVL
	Rear Bumper Centre Moulding Assy			\$ 451.25 ?
	Rear Bumper Lower Centre Moulding Assy			\$ 47.50 ?
	Rear Bumper Side Bracket (LH/RH)		\$ 33.10	\$ 66.20 ?
	Rear Bumper Cover Clips			\$ 22.00 ?
	SUB TOTAL			\$ 1,617.35
	LESS 20%			\$ 323.47
	DISCOUNTED TOTAL			\$ 1,293.88
	Rear Bumper Reverse Sensor			\$ 135.70 Nett XSVL
	Labour Charge			
	Panel Beating			\$ 400.00 200
	Spray Painting Charge			\$ 300.00 200
	Wiring Charge			\$ 30.00 XSVL
	Remove/Refix Reverse Sensor			\$ 120.00 30
	TOTAL LABOUR			\$ 850.00
	ESTIMATE TOTAL			\$ 2,279.58
<p>NAZ LKK 812119 1545 P/P 2 Days CHECK ITEMS (Photos) BEFORE PAINT PHOTOS</p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

LKK Auto Consultants hence notify the Repairer of the following:

- To re-survey after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No compensation(s) is allowed
- Supplemental item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: