

INS. CASE OWNER:

CC 4 / Asm 1900

LKK: 97606
IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L/YES/NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI: (VIA)

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

8185.50

DID ROLL BACK AND HIT TP.

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

800.00

(\$80 x 10 days)

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

8.00

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost

S\$

-

Total:

S\$

8993.50

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

S\$

8993.50

Name 1:

Cheng Hue Motor pte ltd

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

GIA

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.00

ASS. REC. BY:

REF:

AAI

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 859k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / RRP / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SOA 1818Z Yr Regn: 03, 09Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: NIS Tean c.c. 2498Colour: N. Maroon A/C: Insured / Std / NI / NASp. Reading: 165103 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1BBUT3280001254Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 8/2/19 D.O.I. 11/2/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

/ File pass to

L1Pm 876506 back calculation

Lous
(8+3 x 80)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	9602F

Vehicle Details

Vehicle No.:	SDA1818Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Feb 2019
Vehicle Make:	NISSAN
Vehicle Model:	TEANA 2.5 CVT ABS D/AB HID 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2008
Engine No.:	VQ25408055A
Chassis No.:	JN1BBUJ32Z0001254
Maximum Power Output:	134.0 kW (179 bhp)
Open Market Value:	\$33,481.00
Original Registration Date:	26 Mar 2009
First Registration Date:	26 Mar 2009
Transfer Count:	4
Actual ARF Paid:	\$33,481.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Mar 2019
PARF Rebate Amount:	\$16,740.00

Intended COE Rebate Details

COE Expiry Date:	31 Jan 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$31,335.00
COE Rebate Amount:	\$31,242.00
Total Rebate Amount:	\$47,982.00

The information contained herein is correct as at 11 Feb 2019

OK

SDA1818Z (NISSAN TEANA)

1 pr rear bumper Br-
 _____ centre top chrome protector nc-
 2 pr _____ side lower moulding nc-
 1 pr _____ 4th side retainer disc-
 6 pr _____ clips nc-

1 pr rear boot Br-
 _____ logo nc-
 _____ emblem TEANA nc-
 _____ emblem 250 XV nc-
 _____ emblem V6 nc-
 _____ inner lock disc-
 _____ inner rubber disc/wr 508mm
 _____ centre moulding cm-
 _____ top spoiler cm-
 2 pr _____ hinges Br-
 1 pr _____ BH damper Br-
 1 pr _____ inner cushion return-

~~1 pr radiator fan blade~~
 6 pr rear boot inner cushion clips nc-
 2 pr tail lamps. cm-
 2 pr _____ side garnish. n/s Br & t

50A 1818 Z

1 pc rear end panel BTL

inner top garnish. cm

2 pc tail lamp panels N/S BTL

2 pc rear fender inner garnish. Return

8 u ~~inner~~ clips

1 pc rear spare compartment top tool box ?

1 pc smart key sensor ?

2 pc tail ~~gate~~ ^{lamp} chrome moulding - \$80 x 2 = 160

1 set reverse camera - \$380 ?

1 set reverse sensor

\$200 / set ?

CHENG HOE MOTOR PTE LTD
Blk 1019, Yishun Ind. Park A
#01-374, Singapore 768761
Tel: 6755 6142 Fax: 6755 7719
Email: chmotor@singnet.com.sg

CHENG HOE
6755 7719

SOA 1818 Z

- ① RAR rear bumper assy, tail lamps,
rear boot and attachment, spoiler,
lower skirt, To cutty, welding and renew
rear panel, tail lamp panels,
To KAR rear both fenders, rear
spare tyre compartment and sealing
the same 9501
\$1100/ ✓ ✓
- ② RAR rear garnish, seat, car-pet etc \$80/ ✓ ✓
- ③ Putty & respray on rear spoiler, boot,
hinges, seat both fenders, rear panel,
rear spare tyre compartment, compartment,
rear bumper, lower skirt and rear
affected area 10001
\$1100/ ✓ ✓
- ④ RAR ~~rear~~ reverse sensor and
reset system \$40/ ~~\$40~~ ✓ ✓
- ⑤ Subtotal \$60/ ✓ ✓
-
- \$261.18

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SDA 1818Z
TP/AXA

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 68804739
ATTN: Motor Claim Department

WS Ref: TP/AXA/YS
Claim Type: Third Party
Accident Date: 08/02/2019
TP Veh Reg No: XD5639U

Estimate No: ES1991131/YISHUN
Date: 11 Feb 2019
Policy No: D17MTPV01012957
Veh Reg No: SDA1818Z.2
Make/Model: NISSAN TEANA 2.5 CVT
ABS D/AB HID 2WD 4DR
Chassis No: JN1BBUJ32Z0001254
Engine No: VQ25408055A
Reg. Date: 26/03/2009

Estimate Repair Cost to Vehicle No :SDA1818Z.2

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REAR BUMPER	840.00	1 PC	Bu 840.00	✓
2 REAR BUMPER CENTRE TOP CHROME PROTECTOR	252.80	1 PC	CM 252.80	✓
3 REAR BUMPER SIDE LOWER MOULDINGS	145.50	2 PCS	ma 291.00	✓
4 REAR BUMPER LH SIDE RETAINER	36.30	1 PC	Di 36.30	✓
5 REAR BUMPER CLIPS	5.00	6 PCS	ma 30.00	✓
6 REAR BOOT	1,000.80	1 PC	Ry 1,000.80	✓
7 REAR BOOT LOGO	46.10	1 PC	ma 46.10	✓
8 REAR BOOT EMBLEM (TEANA)	95.50	1 PC	ma 95.50	✓
9 REAR BOOT EMBLEM (250 XV & V6)	80.90	1 PC	ma 80.90	✓
10 REAR BOOT INNER LOCK	123.70	1 PC	Di 123.70	✓
11 REAR BOOT INNER RUBBER	156.80	1 PC	Di 156.80	50pin 78.40SA
12 REAR BOOT CENTER MOULDING	369.10	1 PC	CM 369.10	✓
13 REAR BOOT HINGES	171.20	2 PCS	Ry 342.40	✓
14 REAR BOOT RH DAMPER	95.20	1 PC	pu 95.20	✓
15 REAR BOOT INNER CUSHION	139.10	1 PC	Return 139.10	✓
16 REAR BOOT INNER CUSHION CLIPS	5.00	6 PCS	ma 30.00	✓
17 TAILLAMP	521.00	2 PCS	CM 1,042.00	✓
18 TAILLAMP SIDE GARNISH	38.00	2 PCS	ma 76.00	✓
19 REAR END PANEL	550.20	1 PC	Ry 550.20	✓
20 REAR END PANEL INNER TOP GARNISH	105.30	1 PC	CM 105.30	✓
21 TAILLAMP PANELS	138.60	2 PCS	ma 277.20	✓
22 REAR FENDER INNER GARNISHS	245.90	2 PCS	ma 491.80	✓
23 REAR FENDER INNER GARNISH CLIPS	5.00	8 PCS	ma 40.00	✓
24 REAR SPARE COMPARTMENT TOOL BOX	462.00	1 PC	Return 462.00	✓
25 REAR SPARE TYRE TOP BOARD	401.80	1 PC	Di 401.80	✓
			7,376.00	
Less 10%			737.60	6,638.40
Special Net				
26 REAR BOOT TOP SPOILER	390.00	1 PC	CM 390.00	✓
27 SMART KEY SENSOR	64.40	1 PC	CM 64.40	✓
28 TAILLAMP CHROME MOULDINGS	80.00	2 PCS	ma 160.00	✓
29 REVERSE CAMERA	380.00	1 SET	shcm 380.00	✓
30 REVERSE SENSOR	200.00	1 SET	pu 200.00	✓
			1,194.40	1,194.40

Not Authorised
11 Emp @ 76506
Return After Paint 8 days

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 68804739
ATTN: Motor Claim Department

WS Ref: TP/AXA/YS
Claim Type: Third Party
Accident Date: 08/02/2019
TP Veh Reg No: XD5639U

Estimate No: ES1991131/YISHUN
Date: 11 Feb 2019
Policy No: D17MTPV01012957
Veh Reg No: SDA1818Z.2
Make/Model: NISSAN TEANA 2.5 CVT
ABS D/AB HID 2WD 4DR
Chassis No: JN1BBUJ32Z0001254
Engine No: VQ25408055A
Reg. Date: 26/03/2009

Estimate Repair Cost to Vehicle No :SDA1818Z.2

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Labour				
31 TOWING	50.00	1 LA	50.00	✓
32 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT ATTACHMENT, SPOILER, LOWER SKIRT, CUT, WELD & RENEW REAR PANEL, TAILLAMP PANELS, KNOCK & REPAIR REAR BOTH FENDERS, REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME	1,100.00	1 LA	1,100.00	1000/
33 REMOVE & REFIX REAR GARNISH, SEAT, CARPET, ETC	80.00	1 LA	80.00	✓
34 PUTTY & RESPRAY ON REAR SPOILER, BOOT, HINGES, REAR BOTH FENDERS, REAR PANEL, REAR SPARE TYRE COMPARTMENT, REAR BUMPER, LOWER SKIRT & REAR AFFECTED AREAS	1,100.00	1 LA	1,100.00	1000/
35 REMOVE & REFIX REVERSE SENSOR & RESET SYSTEM	40.00	1 LA	40.00	✓
36 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,430.00	2,430.00
Total			SS 10,262.80 ₉₉	
Add GST @ 7%				718.40
Total Amount Payable				SS 10,981.20

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



TP MANDATE IA-S9M01DBG

Type

 Question

Message

Dear Jas, We refer to the above matter Liability(TP) 100% Proposed repair cost \$8,185.50 Loss of use \$880.00 no. of days 11days x\$ 80.00 Loss of rental no. of days Loss of income no. of days LTA search fees \$8.00 Others Proposed Total 9,073.50 Thank you Vivian Lau (15/08/2019)

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 15/8/2019

Survey Details:

Date of loss	8-Feb-19
Date of appointment	11-Feb-19
Date of survey	11-Feb-19
Location of survey	CHENG HOE MOTOR PL

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SDA 1818Z
Make and Model	NISSAN TEANA 2.5 CVT ABS
Date of registration	26-Mar-09
Parf Rebate	
Market Value	\$ 59,000.00
Parf Rebate	\$ 47,982.00
Nett Loss	\$ 11,018.00

Repair details:

Initial Estimate	\$ 10,262.80
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 7,389.83
Check items (estimate)	
Labour	\$ 2,230.00
Total	\$ 9,619.83
Lump Sum(if applicable)	\$ 7,650.00

Number of days for repair	8 days
---------------------------	--------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

OID rolled back hit TP

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	8,185.50	✓
Loss of use	\$	880.00	no. of days 11days x\$ 80.00
Loss of rental			no. of days
Loss of income			no. of days
LTA search fees	\$	8.00	
Others			
Proposed Total		9,073.50	

AVA

✓
8-10 days.



Re:TP MANDATE IA-S9M01DBG

Type

🔗 Question

Message

hi, please offer 8-10 days for LOU.thanks.

Reply

Hsiao Tong (LKKAUTO)

From: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>
Sent: Saturday, 23 November 2019 3:11 PM
To: Hsiao Tong (LKKAUTO)
Subject: ACCEPTANCE - -our Ref: SDA1818Z *Our Ref: CC4/ASM19002354/Kpa3 [ACCIDENT INVOLVING XD 5639U(AXA) AND SDA 1818Z ON 08/02/2019]

Hi Ji Le,

Your offer of S\$ 8993.50 is accepted.

Pls assist to process payment to be made payable to **"CHENG HOE MOTOR PTE LTD"**

Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, November 02, 2019 9:53 AM
To: Cheng Hoe Motor Pte Ltd (Yishun-June)
Subject: RE: APPEAL (1) -our Ref: SDA1818Z *Our Ref: CC4/ASM19002354/Kpa3 [ACCIDENT INVOLVING XD 5639U(AXA) AND SDA 1818Z ON 08/02/2019]

Without Prejudice

Dear Sirs/Mdm,

We have our principal instruction to improve offer as follows: -

1. Cost of Repair (w/GST)	\$ 8,185.50
2. Loss of Use (10days x \$80.00)	\$ 800.00
3. LTA/GIA Search Fee	\$ 8.00
Total	\$ 8,993.50

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

From: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>
Sent: Friday, 25 October 2019 8:05 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: APPEAL (1) -our Ref: SDA1818Z *Our Ref: CC4/ASM19002354/Kpa3 [ACCIDENT INVOLVING XD 5639U(AXA) AND SDA 1818Z ON 08/02/2019]

Hi Hsiao Tong,

Due to Sat/ Sun, pls reconsider to settle 11days LOU (i.e. \$880.00)

Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, October 09, 2019 9:05 AM
To: <mailto:chmotor@singnet.com.sg>
Subject: Your Ref: SDA1818Z *Our Ref: CC4/ASM19002354/Kpa3 [ACCIDENT INVOLVING XD 5639U(AXA) AND SDA 1818Z ON 08/02/2019]

Your Ref: **SDA1818Z** Without Prejudice
Our Ref: CC4/ASM19002354/Kpa3

Dear Sirs/Mdm,

ACCIDENT INVOLVING XD 5639U(AXA) AND SDA 1818Z ON 08/02/2019

We refer to the above matter.

We have our principal instruction to offer as follows: -

1. Cost of Repair (w/GST)	\$ 8,185.50
2. Loss of Use (8days x \$80.00)	\$ 640.00
3. LTA/GIA Search Fee	\$ 8.00
Total	\$ 8,833.50

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Date: 01 OCT 2019

AXA Insurance (S) Pte Ltd
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. SDA1818Z.2 & XD5639U ON 08/02/2019
LENGKOK MARIAM.**

We are authorized by SDA1818Z.2 for their above matter.

Record reveals that you are the insurer of XD5639U. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 8185.50
2. Loss of Use (8 + SAT + Sun x 2 @ 480/day)	S\$ 880.00
3. Hire of Vehicle	S\$ 0.00
4. LTA Search Fee/GIA Reports	S\$ 8.00
TOTAL	S\$ 9073.50

Please let us have your reply soonest possible.

Thank you.

Yours faithfully

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

NO: **CL8190875**
Date: 21 Aug 2019
Policy No: D17MTPV01012957
Veh Reg No: **SDA1818Z.2**
Make/Model: NISSAN TEANA 2.5
CVT ABS D/AB HID
2WD 4DR
Job No: JC1600342

WS Ref: TP/AXA/YS
Claim Type: Third Party
Accident Date: 08/02/2019
TP Veh Reg No: XD5639U

PAGE:1

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	S\$ 7,650.00	S\$ 7,650.00

Total	S\$ 7,650.00
Add GST @ 7%	535.50
Total Amount payable	<u>S\$ 8,185.50</u>

For Cheng Hoe Motor Pte Ltd



E. & O. E.

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19002354/Kpa3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 10-12-2019



ATTN: JAS TAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 5639U	Veh. Inspected	SDA 1818Z
Policy No.	P2142884	Coverage (\$)	0.00
Claim No.	S9M01DBG	Excess (\$)	0.00
Assign From	JAS TAN	Assign Date	11/02/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN TEANA (A)	c.c	2496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JN1BBUJ32Z0001254	Colour	METALLIC MAROON
Odometer	165105	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	DAYTON	6 mm
L/H Front Tyre	215/55 R17	DAYTON	6 mm
R/H Rear Tyre	215/55 R17	DAYTON	6 mm
L/H Rear Tyre	215/55 R17	DAYTON	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/02/2019	Inspection Date	11/02/2019
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDA 1818Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (N) (CONSISTENT)	BUCKLED	840.00	840.00
1	REAR BUMPER CENTRE TOP CHROME RPOTECTOR (N) (CONSISTENT)	CRACKED	252.80	252.80
2	REAR BUMPER SIDE LOWER MOULDINGS @ \$145.50 (N) (CONSISTENT)	NECESSARY	291.00	291.00
1	REAR BUMPER LH SIDE RETAINER (N) (CONSISTENT)	DISTORTED	36.30	36.30
6	REAR BUMPER CLIPS @ \$5.00 (N) (CONSISTENT)	NECESSARY	30.00	30.00
1	REAR BOOT (N) (CONSISTENT)	BENT	1,000.80	1,000.80
1	REAR BOOT LOGO (N) (CONSISTENT)	NECESSARY	46.10	46.10
1	REAR BOOT EMBLEM (TEANA) (N) (CONSISTENT)	NECESSARY	95.50	95.50
1	REAR BOOT EMBLEM (250 XV & V6) (N) (CONSISTENT)	NECESSARY	80.90	80.90
1	REAR BOOT INNER LOCK (N) (CONSISTENT)	DISTORTED	123.70	123.70
1	REAR BOOT CENTER MOULDING (N) (CONSISTENT)	CRACKED	369.10	369.10
2	REAR BOOT HINGES @ \$171.20 (N) (CONSISTENT)	BENT	342.40	342.40
1	REAR BOOT RH DAMPER (N) (CONSISTENT)	PUNCTURE	95.20	95.20
1	REAR BOOT INNER CUSHION (N) (CONSISTENT)	DEFORMED	139.10	139.10
6	REAR BOOT INNER CUSHION CLIPS @ \$5.00 (N) (CONSISTENT)	NECESSARY	30.00	30.00
2	TAILLAMPS @ \$521.00 (N) (CONSISTENT)	CRACKED	1,042.00	1,042.00
2	TAILLAMP SIDE GARNISH @ \$38.00 (N) (CONSISTENT)	N/S BUCKLED	76.00	38.00
1	REAR END PANEL (N) (CONSISTENT)	BENT	550.20	550.20
1	REAR END PANEL INNER TOP GARNISH (N) (CONSISTENT)	CRACKED	105.30	105.30
2	TAILLAMPS PANELS @ \$138.60 (N) (CONSISTENT)	N/S BENT	277.20	138.60
2	REAR FENDER INNER GARNISHS @ \$245.90 (N) (CONSISTENT)	N/S DEFORMED	491.80	245.90
8	REAR FENDER INNER GARNISH CLIPS @ \$5.00 (N) (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR SPARE COMPARTMENT TOOL BOX (N) (CONSISTENT)	DEFORMED	462.00	462.00
1	REAR SPARE TYRE TOP BOARD (N) (CONSISTENT)	DISTORTED	401.80	401.80
	LESS 10% DISCOUNT		-721.92	-679.67
			6,497.28	6,117.03

Report Ref No. CC4/ASM19002354/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT INNER RUBBER (50%) (SN) (CONSISTENT)	DISTORTED / DENTED	156.80	78.40
	LESS 10% DISCOUNT		-15.68	-
			141.12	78.40
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOOT TOP SPOILER (SN) (CONSISTENT)	CRACKED	390.00	390.00
1	SMART KEY SENSOR (SN) (CONSISTENT)	CRACKED	64.40	64.40
2	TAILLAMP CHROME MOULDING @ \$80.00 (SN) (CONSISTENT)	NECESSARY	160.00	160.00
1	SET REVERSE CAMERA (SN) (CONSISTENT)	SHORTED	380.00	380.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	DENTED	200.00	200.00
			1,194.40	1,194.40
	<u>LABOUR</u>			
	TOWING.		50.00	50.00
	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT ATTACHMENT, SPOILER, LOWER SKIRT, CUT, WELD & RENEW REAR PANEL, TAILLAMP PANELS, KNOCK & REPAIR REAR BOTH FENDERS, REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME.		1,100.00	1,000.00
	REMOVE & REFIX REAR GARNISH, SEAT, CARPET, ETC.		80.00	80.00
	PUTTY & RESPRAY ON REAR SPOILER, BOOT, HINGES, REAR BOTH FENDERS, REAR PANEL, REAR SPARE TYRE COMPATMENT, REAR BUMPER, LOWER SKIRT & REAR AFFECTED AREAS.		1,100.00	1,000.00
	REMOVE & REFIX REVERSE SENSOR & RESET SYSTEM.		40.00	40.00
	RUSTPROOFING.		60.00	60.00
			2,430.00	2,230.00
GRAND TOTAL			10,262.80	9,619.83
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,650.00

Report Ref No. CC4/ASM19002354/Kpa3s2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.