

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SDA 1818Z
 TP/AXA

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 08/02/2019

TP Veh Reg No: XD5639U

Estimate No: ES1991131/YISHUN

Date: 11 Feb 2019

Policy No: D17MTPV01012957

Veh Reg No: SDA1818Z.2

Make/Model: NISSAN TEANA 2.5 CVT
 ABS D/AB HID 2WD 4DR

Chassis No: JN1BBUJ32Z0001254

Engine No: VQ25408055A

Reg. Date: 26/03/2009

Not Authorized

11 Lmp @ 7

Running After Paint 8 days

Estimate Repair Cost to Vehicle No :SDA1818Z.2

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 REAR BUMPER	840.00	1 PC	Bu 840.00	✓
2 REAR BUMPER CENTRE TOP CHROME PROTECTOR	252.80	1 PC	CM 252.80	✓
3 REAR BUMPER SIDE LOWER MOULDINGS	145.50	2 PCS	me 291.00	✓
4 REAR BUMPER LH SIDE RETAINER	36.30	1 PC	Di 36.30	✓
5 REAR BUMPER CLIPS	5.00	6 PCS	me 30.00	✓
6 REAR BOOT	1,000.80	1 PC	Bu 1,000.80	✓
7 REAR BOOT LOGO	46.10	1 PC	me 46.10	✓
8 REAR BOOT EMBLEM (TEANA)	95.50	1 PC	me 95.50	✓
9 REAR BOOT EMBLEM (250 XV & V6)	80.90	1 PC	me 80.90	✓
10 REAR BOOT INNER LOCK	123.70	1 PC	Di 123.70	✓
11 REAR BOOT INNER RUBBER	156.80	1 PC	Di 156.80	50pin
12 REAR BOOT CENTER MOULDING	369.10	1 PC	CM 369.10	✓
13 REAR BOOT HINGES	171.20	2 PCS	Bu 342.40	✓
14 REAR BOOT RH DAMPER	95.20	1 PC	me 95.20	?
15 REAR BOOT INNER CUSHION	139.10	1 PC	Return 139.10	✓
16 REAR BOOT INNER CUSHION CLIPS	5.00	6 PCS	me 30.00	✓
17 TAILLAMPS	521.00	2 PCS	CM 1,042.00	✓
18 TAILLAMP SIDE GARNISH	38.00	2 PCS	NIS Bu 76.00	✓
19 REAR END PANEL	550.20	1 PC	Bu 550.20	✓
20 REAR END PANEL INNER TOP GARNISH	105.30	1 PC	CM 105.30	✓
21 TAILLAMP PANELS	138.60	2 PCS	NIS Bu 277.20	✓
22 REAR FENDER INNER GARNISHS	245.90	2 PCS	NIS Return 491.80	✓
23 REAR FENDER INNER GARNISH CLIPS	5.00	8 PCS	me 40.00	✓
24 REAR SPARE COMPARTMENT TOOL BOX	462.00	1 PC	me 462.00	?
25 REAR SPARE TYRE TOP BOARD	401.80	1 PC	Di 401.80	✓
			7,376.00	
		Less 10%	737.60	6,638.40
Special Net				
26 REAR BOOT TOP SPOILER	390.00	1 PC	CM 390.00	✓
27 SMART KEY SENSOR	64.40	1 PC	me 64.40	?
28 TAILLAMP CHROME MOULDINGS	80.00	2 PCS	me 160.00	✓
29 REVERSE CAMERA	380.00	1 SET	me 380.00	?
30 REVERSE SENSOR	200.00	1 SET	me 200.00	✓
			1,194.40	1,194.40

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 68804739
ATTN: Motor Claim Department

WS Ref: TP/AXA/YS
Claim Type: Third Party
Accident Date: 08/02/2019
TP Veh Reg No: XD5639U

Estimate No: ES1991131/YISHUN
Date: 11 Feb 2019
Policy No: D17MTPV01012957
Veh Reg No: SDA1818Z.2
Make/Model: NISSAN TEANA 2.5 CVT
ABS D/AB HID 2WD 4DR
Chassis No: JN1BBUJ32Z0001254
Engine No: VQ25408055A
Reg. Date: 26/03/2009

Estimate Repair Cost to Vehicle No :SDA1818Z.2

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
31 TOWING	50.00	1 LA	50.00	✓
32 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT ATTACHMENT, SPOILER, LOWER SKIRT, CUT, WELD & RENEW REAR PANEL, TAILLAMP PANELS, KNOCK & REPAIR REAR BOTH FENDERS, REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME	1,100.00	1 LA	1,100.00	1000/
33 REMOVE & REFIX REAR GARNSIH, SEAT, CARPET, ETC	80.00	1 LA	80.00	✓
34 PUTTY & RESPRAY ON REAR SPOILER, BOOT, HINGES, REAR BOTH FENDERS, REAR PANEL, REAR SPARE TYRE COMPARTMENT, REAR BUMPER, LOWER SKIRT & REAR AFFECTED AREAS	1,100.00	1 LA	1,100.00	1000/
35 REMOVE & REFIX REVERSE SENSOR & RESET SYSTEM	40.00	1 LA	40.00	✓
36 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,430.00	2,430.00
Total				S\$ 10,262.80
Add GST @ 7%				718.40
Total Amount Payable				<u>S\$ 10,981.20</u>

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: