

ASS. REC. BY:

REF: C8/CT119002356/Atd301 Special Instruction:

Surveyor: Adrean

ASSIGNMENT (Office)

From (Person): Chong Baan Sen of CTI Date/Time: 11/2/19 @ 9.30am

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 9LW 4114R Insured: GB4 5760R

at Workshop m/s Dynamic Autowork Tel: 9856 4815

of 8 Kaki Bkt Ave 4 # 08-09

Policy No: Dm CVSN18218 + 18000 Claim No: SNM19D20074502

Sum Insured: Excess:

Make of Veh: D.O.A. 05/02/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS lyp

H.O.D. Endorsement:

Date/Time: 10.22am @ 11/2/19 Person Contacted: Michelle Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	9LW 4114R - X
	GB4 5760R - X
	Lump Sum \$9100 (Red: 9482.72, 51%)

CTI

SINGAPORE

Ex-Ins: Date: 11/2/19

Estimated Cost:

OP: ☒ WS / TP RES / CO RES / EVA / INV / MV

Transported Vehicle No: SLW 4114R

At Workshop: Dynamic Autowork

at: 8 Kaki Bkt Ave 4 # 08-09 Premier

Insured:

Policy No:

Claim No:

Sum Insured:

(Client's Record)

Make of Veh:



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. of Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PH Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Est. Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date: Person Contacted:

Vehicle: IN / OUT

Sub No: SLW 4114R. at Page: 2018 Feb.

Type: ☒ Car / ☐ M. Cycle / ☐ Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel ex: 1496

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 2163 T/Audio: Insured / Std / NI / NA

Eng No: Ru1230524

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inoper / Jammed / Leaked / Burnt or

Brake: ☒ Inoper / Jammed / Leaked / Burnt or

Mod: Nil / ☒ STD A/Rim or

Tyre Size: F: 215/60R16
R: 215/60R16.

BS / ☒ PUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: R/Bal: 06 mm L/Bal: 06 mm D.O.A. 11/02/19

Survey held at: Dynamic

Des. of Damage: ☒ Frt / ☐ Rear / ☐ Q/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction: TP China.

RECEIVED 10 APR 2019

Date/Time: File Days In: ☐ Pref. Report

10/4 Typist ☒ Final Report

Date/Time: File Return In:

TP

Report Format

Ump: ☒ Sum / LB 115

TP
91001

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp: 15

☐ Interview: 15

☐ Test: 15

☐ Workshop: 15

Survey Fee:

Transportation:

1. 10.00 15

1. Photo:

1. Other:

1. Total:

10.00

320

320

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Monday, 11 February 2019 9:38 AM
To: assignments
Subject: FW: SLW4114R (Pre-inspection) / Your vehicle : GBH5760R

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 11 February 2019 9:36 AM
To: Dynamic Autowork <dynamicautowork@gmail.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: SLW4114R (Pre-inspection) / Your vehicle : GBH5760R

Without Prejudice

Dear Sir,

We will appoint LKK accordingly.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Dynamic Autowork [<mailto:dynamicautowork@gmail.com>]
Sent: Monday, 11 February, 2019 9:24 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: SLW4114R (Pre-inspection) / Your vehicle : GBH5760R

Morning Boon Sen,

Please arrange below surveyor to survey the above vehicle.

ADRIAN LING

**** PLEASE ADVISE LIABILITY ****

--

Thank You.

Yours Sincerely,

Michelle
HP : 9856 4815

8 Kaki Bukit Avenue 4
#08-09Premier @ Kaki Bukit
Singapore (415875)
Tel : 6341 6789
Fax : 6341 6778

On Mon, Feb 11, 2019 at 9:03 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Insured yet to report meanwhile and unable advise on liability.

Thank you.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Dynamic Autowork [<mailto:dynamicautowork@gmail.com>]

Sent: Friday, 8 February, 2019 7:02 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>; Angie Foo <angie.foo@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: SLW4114R (Pre-inspection) / Your vehicle : GBH5760R

Dear All,

Attach my client GIA report for your record

Thank You.

Yours Sincerely,

Michelle

HP : 9856 4815

8 Kaki Bukit Avenue 4

#08-09Premier @ Kaki Bukit

Singapore (415875)

Tel : 6341 6789

Fax : 6341 6778

On Fri, Feb 8, 2019 at 2:47 PM Dynamic Autowork <dynamicautowork@gmail.com> wrote:

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

Hope we can do Direct Settle and please provide the surveyor firm or surveyor name list to conduct the joint pre-repair survey as a single joint expert

**** PLEASE ADVISE LIABILITY****

**** GIA REPORT WILL E-MAIL TO YOUR ONCE RECEIVE FROM MY CLIENT ****

--

Thank You.

Yours Sincerely,

Michelle

HP : 9856 4815

8 Kaki Bukit Avenue 4

#08-09Premier @ Kaki Bukit

Singapore (415875)

Tel : 6341 6789

Fax : 6341 6778

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	08/02/2019 16:26
Date Of Accident	05/02/2019 14:45
Exact Location Of Accident	JALAN BOON LAY TWDS AYE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLW4114R
Insured/Policyholder	
Name Of Registered Owner	LOO CHOON JIN
NRIC No	S1409917D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98312251
Alternative Phone No	OFFICE-60000000
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00110800
Cover Note Number	
Driver	
Name of Driver	LOO CHOON JIN
NRIC No	S1409917D
Date Of Birth	12/03/1960
Occupation	INDOOR
Date Of Driving Pass	21/01/1980
Driving Experience	39 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98312251
Fax Number	
Contact Number	OFFICE-60000000
Email Address	NOEMAIL

Address	BLK 441 CHOA CHU KANG AVE 4 #03-429
Postcode	680441
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : JULIA LOO JI JI GENDER: : FEMALE
Passenger 2	NAME: : JEWEL LOO JI XIAN GENDER: : FEMALE
Passenger 3	NAME: : KOH CHIEW YEW GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	T/20190205/2043
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Report please refer to Police report

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	GET FROM WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH5760R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the signing of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

3. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer [collectively the "Personal Information"] and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulation, law or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name
NOC/TIN No.:

Sketch Plan #2

SKETCH PLAN



A = SLWA114R

B = GBH5760R

Jalan Boon day
towards
AYE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report
Report No. T/20190205/2043

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
If driver is not the policyholder
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7928999



T/20190205/2043

1 of 4

Report No: T/20190205/2043

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
05/02/2019 16:30

Vide Report No.:

Station Diary No:
46

Informant's Particulars

Name of Informant:
LOO CHOON JIN

Address:
APT BLK 441 CHOA CHU KANG AVENUE 4 #03-429
SINGAPORE 680441

ID Type / ID No.:
NRIC NO / S1409917D

Contact No.:
Home/Office: Mobile: 98312251

Nationality:
SINGAPORE CITIZEN

Email:

Sex: Male Age: 58 Date of Birth: 12/03/1960

Type of Informant:
Driver

Race:
Chinese

Language:
English

Institution / School Name:

Occupation:
SENIOR TECHNICIAN

Driving Licence Information:
Class: 2B 2A, 2, 3, 4, 5

Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 05/02/2019 14:45	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 JALAN BOON LAY BOON LAY WAY				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow:	Traffic Control:	Traffic Volume:		
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBH5760R	Lorry				Slightly Damaged	3
SLW4114R	Car	HONDA	VEZEL	Red	Slightly Damaged	3

Details of Person Involved

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999



T/20190205/2043

2 of 4

Report No: T/20190205/2043

CONTINUATION OF REPORT

Driver			
Name	UTHIRAPATHI HONESTRAJ	ID No.	G2302298U
Related Vehicle	GBH5760R (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	JULIA LOO SI SI	ID No.	S9445266Z
Related Vehicle	SLW4114R (Car)	Contact No.	97242475
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LOO CHOON JIN	ID No.	S1409917D
Related Vehicle	SLW4114R (Car)	Contact No.	98312251
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Passenger			
Name	JEWEL LOO SI XIAN	ID No.	S9346071E
Related Vehicle	SLW4114R (Car)	Contact No.	98521246
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Police Report


**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999



T/20190205/2043

3 of 4

Report No. T/20190205/2043

CONTINUATION OF REPORT

Passenger:			
Name	KOH CHIEW YEN	ID No.	S1807067G
Related Vehicle	SLW4114R (Car)	Contact No.	98152152
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 05/02/2019 at about 1445hrs, I was driving my car, with three other passengers, along Jalan Boon Lay towards AYE. When I was at the junction of Jalan Boon Lay and Boon Lay Way, the traffic light was red. As such, I came to a stop. When the light turned green, I drove forward towards AYE. All of a sudden, a lorry that was travelling from Boon Lay Way drove across the junction towards Upper Jurong Road. I tried to brake however could not stop in time. As a result, the front of my car had collided into the rear right side of the lorry. The lorry however continued driving and showed no sign of stopping.

I gave chase and eventually managed to stop the lorry further down Boon Lay Way, outside Safra. When confronted, the driver of the said lorry admitted that he was in the wrong and requested for private settlement however I declined. I wish to state that at this point of time, neither my passengers nor I are injured. Due to the accident, the front bumper of my car and number plate had fallen off and the bonnet was dented. I then decided to lodge a police report.

Police Report

**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999



T20190205/2543

4 of 4

Report No: T20190205/2543

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /
Sr Staff Sgt MUHAMMAD FAZLI BIN
MOHAMED KEFLI

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / HRT /
SI KALESWARI PALANI
Contact No.: 65476802

Signature Of Informant:

Date/Time:
05/02/2019 16:30

Classification Of Case:

Authentication Stamp

SN 127



Signature: _____

Singapore Police Force

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 08.02.19

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SLW4114R
MODEL : HONDA VEZEL *Denise*
DATE OF ACCIDENT : 05.02.19
TIME OF ACCIDENT : 14:45HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distorted</i>	1	\$ 927.50	\$ 927.50
2	FRONT BUMPER LOWER LIP <i>new</i>	1	\$ 351.00	\$ 351.00
3	FRONT BUMPER FOGLAMP <i>3 new</i>	2	\$ 327.70	\$ 655.40
4	FRONT BUMPER FOGLAMP COVER <i>2 new</i>	2	\$ 49.00	\$ 98.00
5	FRONT BUMPER LOWER GRILLE <i>crushed</i>	1	\$ 189.00	\$ 189.00
6	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 23.00	\$ 46.00
7	FRONT BUMPER REINFORCEMENT TOP GARNISH <i>new</i>	2	\$ 95.00	\$ 190.00
8	FRONT BUMPER REINFORCEMENT <i>Best</i>	1	\$ 479.00	\$ 479.00
9	FRONT BUMPER TOWING COVER <i>new</i>	1	\$ 34.10	\$ 34.10
10	FRONT COLLISION BRAKING SENSOR <i>crushed</i>	1	\$ 895.00	\$ 895.00
11	FRONT COLLISION BRAKING SENSOR BRACKET <i>new</i>	1	\$ 135.00	\$ 135.00
12	FRONT FENDER <i>stem RH Buckled</i>	2	\$ 580.00	\$ 1,160.00
13	FRONT FENDER INNER COWLING <i>3 new</i>	2	\$ 130.00	\$ 260.00
14	FRONT FENDER ARCD GARNISH	2	\$ 153.00	\$ 306.00
15	CENTRE GRILLE <i>3 smashed</i>	1	\$ 398.00	\$ 398.00
16	CENTRE GRILLE (CHROME)	2	\$ 89.00	\$ 178.00
17	GRILLE LOGO <i>new</i>	1	\$ 38.00	\$ 38.00
18	GRILLE CENTRE SUPPORT BRACKET <i>2 new</i>	1	\$ 217.00	\$ 217.00
19	HEADLAMP (LED) <i>crushed</i>	2	\$ 1,859.40	\$ 3,718.80
20	HEADLAMP LOWER BRACKET <i>crushed</i>	2	\$ 64.00	\$ 128.00
21	HEAD LAMP SIDE BRACKET <i>new</i>	2	\$ 40.00	\$ 80.00
22	BONNET <i>Distorted</i>	1	\$ 1,026.00	\$ 1,026.00
23	BONNET LOCK <i>2 new</i>	1	\$ 178.00	\$ 178.00
24	BONNET INNER RUBBER (FRONT) <i>2 new</i>	2	\$ 37.00	\$ 74.00
25	BONNET INNER RUBBER (SIDE) <i>2 new</i>	2	\$ 29.00	\$ 58.00
26	BONNET INSULATOR <i>crushed</i>	1	\$ 247.00	\$ 247.00
27	BONNET STOPPER <i>new</i>	2	\$ 19.50	\$ 39.00
28	BONNET HINGE <i>2 new</i>	2	\$ 45.00	\$ 90.00
29	FRONT SUPPORT PANEL <i>2 new</i>	1	\$ 796.00	\$ 796.00

325

580

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SLW4114R
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 05.02.19
 TIME OF ACCIDENT : 14:45HRS

30	FRONT SUPPORT PANEL TOP GARNISH <i>Replaced</i>	1	\$ 185.00	\$ 185.00	✓
31	RADIATOR <i>Confirmed</i>	1	\$ 1,250.60	\$ 1,250.60	✓
32	RADIATOR CAP <i>Replaced</i>	1	\$ 27.70	\$ 27.70	+
33	RADIATOR CAP HOSE <i>Replaced</i>	1	\$ 45.80	\$ 45.80	+
34	RADIATOR SIDE GARNISH <i>Confirmed</i>	2	\$ 68.00	\$ 136.00	✓
35	RADIATOR RUBBER MOUNTING <i>Replaced</i>	4	\$ 28.00	\$ 112.00	+
36	AIR CON CONDENSER <i>Replaced</i>	1	\$ 898.00	\$ 898.00	✓
37	AIR CON CONDENSER MOUNTING RUBBER <i>Replaced</i>	4	\$ 28.00	\$ 112.00	+
38	AIR DUCT <i>Replaced</i>	1	\$ 142.00	\$ 142.00	✓
39	AIR FLEXIBLE DUCT <i>Replaced</i>	1	\$ 165.00	\$ 165.00	+
40	HORN <i>Confirmed</i>	1	\$ 105.00	\$ 105.00	✓
41	WIPER WASHER TANK <i>Replaced</i>	1	\$ 165.00	\$ 165.00	+
42	FRONT CHASSIS MEMBER RH <i>Repair</i>	1	\$ 755.00	\$ 755.00	✓

11939.9
 9551.92

TOTAL PRICE \$ 17,090.90
 LESS 20% \$ 3,418.18
 SUB TOTAL PRICE \$ 13,672.72

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Missing</i>	1	\$ 50.00	\$ 50.00	✓
2	FRONT BUMPER CLIP (SET) <i>Replaced</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT BUMPER REINFORCEMENT TOP GARNISH CLIP (SET) <i>Replaced</i>	1	\$ 40.00	\$ 40.00	+
5	FRONT FENDER INNER COWLING CLIP (SET) <i>Replaced</i>	1	\$ 50.00	\$ 50.00	+
6	FRONT FENDER ARCD GARNISH CLIP (SET) <i>Replaced</i>	1	\$ 50.00	\$ 50.00	+
7	CENTRE GRILLE CLIP (SET) <i>Replaced</i>	1	\$ 40.00	\$ 40.00	20
8	BONNET SEALANT <i>Not New</i>	1	\$ 150.00	\$ 150.00	+
9	BONNET INSULATOR CLIP (SET) <i>Replaced</i>	1	\$ 50.00	\$ 50.00	30
10	FRONT SUPPORT PANEL SEALANT <i>Replaced</i>	1	\$ 80.00	\$ 80.00	+
11	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>Replaced</i>	1	\$ 50.00	\$ 50.00	20
12	RADIATOR SIDE GARNISH CLIP (SET) <i>Replaced</i>	1	\$ 50.00	\$ 50.00	20
14	COOLANT <i>Replaced</i>	1	\$ 40.00	\$ 40.00	✓

TOTAL \$ 730.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	600

TO : CHINA TAIHING MOTOR CLAIMS DEPTS
 VEHICLE NO : SLW4114R
 MODEL : HONDA VEZEL
 DATE OF ACCIDENT : 05.02.19
 TIME OF ACCIDENT : 14:45HRS

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	800
3	TUFF COAT	\$ 250.00	x
4	REMOVE AND REFIX AND RESET FRONT COLLISION BRAKING SYSTEM	\$ 250.00	120
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	x
6	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
7	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
8	FRONT CHASSIS ALIGNMENT	\$ 250.00	x
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 4,180.00

TOTAL PARTS COST : \$ 14,402.72
 TOTAL LABOUR COST : \$ 4,180.00
 TOTAL REPAIR COST : \$ 18,582.72

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY
 SERVICE ADVISOR
 ABBY
 HP : 9856 4815

Adrian Ling
 2/5 01/02/19

Total 11401.92
 h/c 9.1K

05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary detail(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Apr 2019		10 Apr 2019 14:58 Edit Adj Rpt	S\$9,100.00 Edit Estimates	S\$9,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: LOO CHOON JIN , ID: S1409917D									
Vehicle Reg. No.: SLW4114R		Date of Loss: 05/02/2019 14:00 - :59 [11 Months and 27 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D200745C02		Policy/Cover Note No.: DMCVSN18218718000							
Vehicle Reg. No. (Insured): GBH5760R		Policy No. (Claimant): MPC18A00110800							
		Excess: S\$0.00							
Repairer: Dynamic Autowork Pte. Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 22/04/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW4114R (SNM19D200745C02)
[GBH5760R]

TP
LOO CHOON JIN
Feb 5 2019 2:00PM

[-]
Dynamic Autowork Pte. Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		☒	
No	Finalized On	1st Autoworks Pte Ltd (HQ)		Thumbnail	Print				
1	08/02/19 16:42	Accident Statement		 Load HTM					
2	08/02/19 18:36	Addendum Sheet		 Load JPG	☒				
3	08/02/19 18:40	Accident Statement Addm. #1		 Load HTM					
Photos/Images						3 per page		☒	
No	Finalized On	1st Autoworks Pte Ltd (HQ)		Thumbnail	Print				
1	08/02/19 16:40	Driving License [Linked Accident Report Documents]		 Load JPG	☒				
2	08/02/19 16:40	Insurance Cert [Linked Accident Report Documents]		 Load JPG	☒				
3	08/02/19 16:40	Police Report [Linked Accident Report Documents]		 Load JPG	☒				
4	08/02/19 16:40	Police Report [Linked Accident Report Documents]		 Load JPG	☒				
5	08/02/19 16:40	Police Report [Linked Accident Report Documents]		 Load JPG	☒				
6	08/02/19 16:40	Police Report [Linked Accident Report Documents]		 Load JPG	☒				
7	08/02/19 16:40	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒				
8	08/02/19 16:40	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒				
9	08/02/19 16:41	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒				
10	08/02/19 16:41	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒				
11	08/02/19 16:41	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒				
12	08/02/19 16:41	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒				
13	08/02/19 16:41	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print				
1	10/04/19 15:15	General View		 Load JPG	☒				
2	10/04/19 15:15	General View		 Load JPG	☒				
3	10/04/19 15:15	General View		 Load JPG	☒				
4	10/04/19 15:15	General View		 Load JPG	☒				
5	10/04/19 15:15	General View		 Load JPG	☒				
6	10/04/19 15:15	General View		 Load JPG	☒				
7	10/04/19 15:15	General View		 Load JPG	☒				
8	10/04/19 15:15	General View		 Load JPG	☒				
9	10/04/19 15:15	General View		 Load JPG	☒				
10	10/04/19 15:15	General View		 Load JPG	☒				
11	10/04/19 15:15	General View		 Load JPG	☒				
12	10/04/19 15:15	General View		 Load JPG	☒				
13	10/04/19 15:15	General View		 Load JPG	☒				
14	10/04/19 15:15	General View		 Load JPG					

Assessment Reports			1 per page	☒
No	Finalized On	1st Autoworks Pte Ltd (HQ)	Thumbnail	Print
				☒
15	10/04/19 15:15	General View	 Load JPG	☒
16	10/04/19 15:15	General View	 Load JPG	☒
17	10/04/19 15:15	General View	 Load JPG	☒
18	10/04/19 15:15	General View	 Load JPG	☒
19	10/04/19 15:15	General View	 Load JPG	☒
20	10/04/19 15:15	General View	 Load JPG	☒
21	10/04/19 15:15	General View	 Load JPG	☒
22	10/04/19 15:15	General View	 Load JPG	☒
23	10/04/19 15:15	General View	 Load JPG	☒
24	10/04/19 15:15	General View	 Load JPG	☒
25	10/04/19 15:15	General View	 Load JPG	☒
26	10/04/19 15:15	General View	 Load JPG	☒
27	10/04/19 15:15	General View	 Load JPG	☒
28	10/04/19 15:15	General View	 Load JPG	☒
29	10/04/19 15:15	General View	 Load JPG	☒
30	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
31	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
32	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
33	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
34	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
35	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
36	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
37	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
38	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
39	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
40	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
41	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
42	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
43	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
44	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
45	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
46	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
47	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
48	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
49	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
50	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
51	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
52	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
53	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
54	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
55	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
56	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
57	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
58	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
59	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
60	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
61	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
62	10/04/19 15:16	Reinspection Photo	 Load JPG	☒
63	10/04/19 15:16	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	1st Autoworks Pte Ltd (HQ)	Thumbnail	Print
64	10/04/19 15:16	Reinspection Photo	Load JPG	☒
65	10/04/19 15:16	Reinspection Photo	Load JPG	☒
66	10/04/19 15:16	Reinspection Photo	Load JPG	☒
67	10/04/19 15:16	Reinspection Photo	Load JPG	☒
68	10/04/19 15:16	Reinspection Photo	Load JPG	☒
69	10/04/19 15:16	Reinspection Photo	Load JPG	☒
70	10/04/19 15:16	Reinspection Photo	Load JPG	☒
71	10/04/19 15:16	Reinspection Photo	Load JPG	☒
72	10/04/19 15:16	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/04/19 14:59	PRI CONTACT	Load PDF	
No	Finalized On	1st Autoworks Pte Ltd (HQ)	Thumbnail	Print
1	08/02/19 16:38	Sketch Plan [Linked Accident Report Documents]	Load JPG	☒
2	08/02/19 16:38	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	1st Autoworks Pte Ltd (HQ)	Thumbnail	Print
1	08/02/19 16:42	Accident Statement	Load HTM	
2	08/02/19 18:36	Addendum Sheet	Load JPG	☒
3	08/02/19 18:40	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	1st Autoworks Pte Ltd (HQ)	Thumbnail	Print
1	08/02/19 16:40	Driving License	Load JPG	☒
2	08/02/19 16:40	Insurance Cert	Load JPG	☒
3	08/02/19 16:40	Police Report	Load JPG	☒
4	08/02/19 16:40	Police Report	Load JPG	☒
5	08/02/19 16:40	Police Report	Load JPG	☒
6	08/02/19 16:40	Police Report	Load JPG	☒
7	08/02/19 16:40	Accident Photo	Load JPG	☒
8	08/02/19 16:40	Accident Photo	Load JPG	☒
9	08/02/19 16:41	Accident Photo	Load JPG	☒
10	08/02/19 16:41	Accident Photo	Load JPG	☒
11	08/02/19 16:41	Accident Photo	Load JPG	☒
12	08/02/19 16:41	Accident Photo	Load JPG	☒
13	08/02/19 16:41	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	1st Autoworks Pte Ltd (HQ)	Thumbnail	Print
1	08/02/19 16:38	Sketch Plan	Load JPG	☒
2	08/02/19 16:38	Sketch Plan #2	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19002356/ATD3E2

Date: 18/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN18218718000

Claimant Vehicle
No: SLW4114RInsured Vehicle
No: GBH5760R

Date of Loss: 05/02/2019

Nature of Claim: TP

Claim
No: SNM19D200745C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW4114R

Make & Model: HONDA VEZEL, 1.5 (A)

Reg. Date: 09/02/2018 (Man. Year: 2017)

Colour: Red

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: L15B4430528

Chassis No: RU11230524

Odometer: 21163 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Tyre Size:

Rear Left Side:

Rear Right Side:

215/60 R16

Dunlop 6 mm

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,402.72	9,761.92	4,640.80	32.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	1,640.00	2,540.00	60.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,582.72	11,401.92	7,180.80	38.64
Approved Total (Overridden) (S\$)		9,100.00		
(S\$)	18,582.72	9,100.00	9,482.72	51.03
+ GST 7.00/7.00% (S\$)	1,300.79	637.00	663.79	51.03
Nett Amount (S\$)	19,883.51	9,737.00	10,146.51	51.03

INSPECTION

Date of Assignment: 10/04/2019

Date Inspected: 11/02/2019 Inspected At:

 Dynamic Autowork Pte. Ltd (HQ)
 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki
 Bukit
 Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW4114R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	927.50 FL	*927.50 FL
2	1		*FRONT BUMPER LOWER LIP	Not Necessary	351.00 FL	*- FL
3	2		*FRONT BUMPER FOGLAMP	Not Necessary	655.40 FL	*- FL
4	2		*FRONT BUMPER FOGLAMP COVER	Not Necessary	98.00 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Cracked	189.00 FL	*189.00 FL
6	2		*FRONT BUMPER SIDE RETAINER	Necessary	46.00 FL	*46.00 FL
7	2		*FRONT BUMPER REINFORCEMENT TOP GARNISH	Not Necessary	190.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Bent	479.00 FL	*325.00 FL
9	1		*FRONT BUMPER TOWING COVER	Not Necessary	34.10 FL	*- FL
10	1		*FRONT COLLISION BRAKING SENSOR	Cracked	895.00 FL	*895.00 FL
11	1		*FRONT COLLISION BRAKING SENSOR BRACKET	Not Necessary	135.00 FL	*- FL
12	1		*FRONT FENDER	O/S Buckled	1,160.00 FL	*580.00 FL
13	2		*FRONT FENDER INNER COWLING	Not Necessary	260.00 FL	*- FL
14	2		*FRONT FENDER ARCD GARNISH	Not Necessary	306.00 FL	*- FL
15	1		*CENTRE GRILLE	Smashed	398.00 FL	*398.00 FL
16	2		*CENTRE GRILLE (CHROME)	Smashed	178.00 FL	*178.00 FL
17	1		*GRILLE LOGO	Necessary	38.00 FL	*38.00 FL
18	1		*GRILLE CENTRE SUPPORT BRACKET	Damaged	217.00 FL	*217.00 FL
19	2		*HEADLAMP (LED)	Cracked	3,718.80 FL	*3,718.80 FL
20	2		*HEADLAMP LOWER BRACKET	Cracked	128.00 FL	*128.00 FL
21	2		*HEAD LAMP SIDE BRACKET	Not Necessary	80.00 FL	*- FL
22	1		*BONNET	Distorted	1,026.00 FL	*1,026.00 FL
23	1		*BONNET LOCK	Damaged	178.00 FL	*178.00 FL
24	2		*BONNET INNER RUBBER (FRONT)	Cut	74.00 FL	*74.00 FL
25	2		*BONNET INNER RUBBER (SIDE)	Cut	58.00 FL	*58.00 FL
26	1		*BONNET INSULATOR	Crumpled	247.00 FL	*247.00 FL
27	2		*BONNET STOPPER	Not Necessary	39.00 FL	*- FL
28	2		*BONNET HINGE	Not Necessary	90.00 FL	*- FL
29	1		*FRONT SUPPORT PANEL		796.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
30	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary Deformed	185.00 FL	*185.00 FL
31	1		*RADIATOR	Cracked	1,250.60 FL	*1,250.60 FL
32	1		*RADIATOR CAP	Not Necessary	27.70 FL	*- FL
33	1		*RADIATOR CAP HOSE	Not Necessary	45.80 FL	*- FL
34	2		*RADIATOR SIDE GARNISH	Cracked	136.00 FL	*136.00 FL
35	4		*RADIATOR RUBBER MOUNTING	Not Necessary	112.00 FL	*- FL
36	1		*AIR CON CONDENSER	Dented	898.00 FL	*898.00 FL
37	4		*AIR CON CONDENSER MOUNTING RUBBER	Not Necessary	112.00 FL	*- FL
38	1		*AIR DUCT	Deformed	142.00 FL	*142.00 FL
39	1		*AIR FLEXIBLE DUCT	Not Necessary	165.00 FL	*- FL
40	1		*HORN	Cracked	105.00 FL	*105.00 FL
41	1		*WIPER WASHER TANK	Not Necessary	165.00 FL	*- FL
42	1		*FRONT CHASSIS MEMBER RH	Repair	755.00 FL	*- FL
43	1		*FRONT NUMBER PLATE	Missing	50.00 FS	*50.00 FS
44	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
45	1		*SET FRONT BUMPER REINFORCEMENT TOP GARNISH CLIP	Not Necessary	40.00 FS	*- FS
46	1		*SET FRONT FENDER INNER COWLING CLIP	Not Necessary	50.00 FS	*- FS
47	1		*SET FRONT FENDER ARCD GARNISH CLIP	Not Necessary	50.00 FS	*- FS
48	1		*SET CENTRE GRILLE CLIP	Necessary	40.00 FS	*20.00 FS
49	1		*BONNET SEALANT	Not Necessary	150.00 FS	*- FS
50	1		*SET BONNET INSULATOR CLIP	Necessary	50.00 FS	*30.00 FS
51	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
52	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
53	1		*SET RADIATOR SIDE GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
54	1		*COOLANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 17,820.90 12,149.90
 - List Item Discount on L Items 20.00/20.00% (S\$) 3,418.18 2,387.98

Total Parts (S\$) 14,402.72 9,761.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,400.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	250.00	0.00
4	REMOVE AND REFIX AND RESET FRONT COLLISION BRAKING SYSTEM	New	250.00	120.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	250.00	0.00
6	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
7	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
8	FRONT CHASSIS ALIGNMENT	New	250.00	0.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			4,180.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >