

Date : 11/02/2019

TO: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Our Customer : Lim Yi Hao

Vehicle No : SLL2968P

Model : Mazda 3

Manufacture Year : 2017

Date of Accident : 9/2/2019

Total Estimate Repair Days : 12

Total Pages : 2

Attn : Motor Claims Department
Email : motor.survey@axa.com.sg

Asher

Re: Repair Estimate For Third Party Claim against SKX4323K

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front grille chrome <i>lit</i>	1	\$182.50	\$182.50	✓
2	Front grille base <i>Not New</i>	1	\$129.00	\$129.00	+
3	Front grille "Mazda" logo <i>Not Nec</i>	1	\$58.50	\$58.50	+
4	Front bumper <i>Distorted</i>	1	\$825.50	\$825.50	✓
5	Front bumper side retainer RH <i>Repld</i>	1	\$18.70	\$18.70	✓
6	Front bumper reinforcement <i>Not Nec</i>	1	\$478.80	\$478.80	+
7	Front tow hook cover <i>Repld</i>	1	\$14.80	\$14.80	+
8	Fog lamp garnish RH <i>lit</i>	1	\$25.00	\$25.00	✓
9	Fog lamp RH ? Signal lamp RH <i>could</i>	1		190.00 \$0.00	✓
10	Headlamp RH <i>Smashed</i>	1	\$1,019.50	\$1,019.50	✓
11	Headlamp lower bracket RH <i>Repld</i>	1	\$32.20	\$32.20	+
12	Bonnet <i>Distorted</i>	1	\$1,067.30	\$1,067.30	✓
13	Bonnet rubber <i>lit</i>	1	\$63.60	\$63.60	✓
14	Front fender RH <i>Distorted</i>	1	\$383.90	\$383.90	✓
15	Front fender inner shield RH <i>Repld</i>	1	\$97.00	\$97.00	✓
16	Front fender top garnish RH <i>Repld</i>	1		\$0.00	+
17	Wiper tank <i>Repld</i>	1	\$154.50	\$154.50	✓
18	Wiper garnish RH <i>Repld</i>	1	\$216.50	\$216.50	+
19	Front door RH <i>Repld</i>		repair	repair	+
20	Support top panel RH <i>Repld</i> wheelhouse ext- <i>2nd Pnt</i>	1	\$149.60	\$149.60	+
21	Support panel RH <i>Repld</i>	1	\$469.70	\$469.70	+
22	Support panel garnish <i>could</i>	1	\$338.30	\$338.30	✓
23	Front shock absorber RH	1	\$387.00	\$387.00	+
24	Front knuckle arm RH <i>Repld</i>	1	\$383.40	\$383.40	+
25	Front knuckle arm bearing RH <i>Repld</i>	1	\$541.70	\$541.70	+
26	Front lower arm RH	1	\$484.70	\$484.70	+
27	Front chassis RH <i>Repld</i>	1	repair	repair	+
	Total			\$7,482.70	
	Less 20%			\$1,496.54	
	Sub Total 1			\$5,986.16	
A.	Spare Parts (S/Nett)				
1	Front grille clip <i>Repld</i>	8	\$4.50	\$36.00	✓ 10
2	Front bumper clip <i>Repld</i>	10	\$4.50	\$45.00	✓ 30
3	Front tyre RH <i>Repld</i>	1	\$350.00	\$350.00	x
4	Front sports rim RH <i>Repld</i>	1	\$450.00	\$450.00	x

435.8
3450.64

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
5	Front fender inner shield clip <i>new</i>	10	\$4.50	\$45.00	<i>30</i>
6	Front fender top garnish clip <i>new</i>	5	\$4.50	\$22.50	<i>x</i>
7	Support panel garnish clip <i>new</i>	7	\$4.50	\$31.50	<i>20</i>
8	Headlamp bulb RH <i>can be</i>	1	\$35.00	\$35.00	<i>2</i>
9	Day light bulb RH <i>can be</i>	1	\$25.00	\$25.00	<i>✓</i>
10	Signal lamp bulb RH <i>can be</i>	1	\$25.00	\$25.00	<i>✓ 185</i>
Sub Total 2				\$1,065.00	
Total for Parts				\$7,051.16	
B.	Labour				
1	To check wiring.			\$80.00	<i>30</i>
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,000.00	<i>600</i>
3	Spray painting all affected parts & areas.			\$1,200.00	<i>800</i>
4	To spray anti-rust undercoat.			\$60.00	<i>x</i>
5	To remove and replace front undercarriage RH.			\$180.00	<i>x</i>
6	To check wheels with computerized wheel alignment.			\$120.00	<i>x</i>
7	To knock and reshape front chassis RH.			\$250.00	<i>x 1430</i>
Total Labour				\$2,890.00	
Total Repair Cost				\$9,941.16	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Yours faithfully

Signature:

Date:

Aun Teng

f Premium Carz Services Pte Ltd

Adrian L
12/02/19.
P/P OS Pays.

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

Supplementary 148

total 5215.64. ✓

(P/P)

Date : 12/02/2019

TO: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Our Customer : Lim Yi Hao
Vehicle No : SLL2968P
Model : Mazda 3
Manufacture Year : 2017
Date of Accident : 9/2/2019
Total Estimate Repair Days : 12
Total Pages : 1

Attn : Motor Claims Department
Email : motor.survey@axa.com.sg

Re: Supplementary Repair Estimate For Third Party Claim against SKX4323K

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front fender stay RH <i>Ref</i>	1	\$75.00	\$75.00	✓
2	Radiator grille top garnish <i>could</i>	1	\$110.00	\$110.00	✓
	Total			\$185.00	
	Less 20%			\$37.00	
	Total Supplementary Repair Cost			\$148.00	

Adrian G
13/02/19

185
148.

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No