

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 285D**AAD1902-019***Not Authorised*
11 Sep @ 7150L

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD 285D

VF1ABL15AUC282333

RENAULT

LATITUDE

5.2.2019

AIG

4/2/2016

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>B</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>B</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Dis</i> 113.47	✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61	✓
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>B</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1 BOOT REAR	\$	<i>B</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	X
16	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	<i>M</i> 225.36	—
19	1 BOOT BADGE	\$	<i>M</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45	
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	

Trans-cab Auto Services Pte Ltd

AAD1902-019

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 285D

30	1 FENDER PANEL REAR RH	\$	R	3,299.13	
31	1 WHEELARCH REAR RH	\$	Sn	543.47	
32	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	
33	1 WHEEL HOUSING PANEL REAR RH	\$	R	4,682.09	
34	1 TAILLAMP LH	\$	Sn	552.55	
35	1 TAILLAMP PANEL LH	\$	R	986.70	
36	1 TAILLAMP RH	\$	Sn	552.55	
37	1 TAILLAMP PANEL RH	\$	R	986.70	
38	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	—
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	cm	404.56	—
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
41	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
42	1 EXHAUST REAR	\$	R	7,489.05	X
43	1 EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	36,036.98
10%	\$	3,603.70
	\$	32,433.28

Special Nett

1	1SET PARKING AID	\$	Short	700.00	600.00
2	1SET REAR BUMPER CLIP	\$	R	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	R	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	R	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	R	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	R	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	R	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	R	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	R	66.00	—
10	1 EXHAUST MOUNTING REAR	\$	R	17.82	X
11	1SET BOOT FINISHER CLIP	\$	R	24.20	X
12	1 REAR BOOT STICKER 'Trans-cab'	\$	R	80.00	30.00
13	1 REAR BOOT STICKER '6555-3333'	\$	R	80.00	30.00

Trans-cab Auto Services Pte Ltd**AAD1902-019**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 285D

16 1SET FENDER WHEELARCH REAR RH CLIP	\$	nn 35.00	}
17 1SET FENDER WHEELARCH REAR LH CLIP	\$	nn 35.00	
18 1 FENDER INNER TRIM CLIP LH	\$	nn 28.00	
19 1 FENDER INNER TRIM CLIP LH	\$	nn 28.00	
20 1 TAILLAMP CLIP RH	\$	nn 5.00	
21 1 TAILLAMP CLIP LH	\$	nn 5.00	
22 2 REAR WINDSCREEN SELANT	\$	nn 80.00	
23 1 WINDSCREEN MOULDING	\$	nn 100.00	
24 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00	
25 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn 385.00	
26 1 SPARE TYRE	\$	sn 330.00	

TOTAL \$ 2,280.02**TOTAL PARTS \$ 34,713.30****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 6001
To Rust-Proofing Of The Affected Areas.	\$	170.00 601
To reinstall rear bumper parking sensor.	\$	170.00 601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 601
To repair and realign rear exhaust pipe.	\$	nn 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1902-019**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 285D

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	<i>601</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i> 380.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	<i>X</i>
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>

TOTAL \$ 14,340.00**Over All Total \$ 49,053.30****(PART-BY-PART)****Repair Days***20 DAYS**5 days*