

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5931U**AAD1901-286**

Not Authored
1/1 Sup & 1850h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5931U

VF1ABL15AUC281484

RENAULT

LATITUDE

30.1.2019

AIG

6/3/2015

PART**LIST**

1	1 BUMPER COVER REAR
2	1 BUMPER LOWER REAR
3	1 BUMPER BRACKET CTR REAR
4	1 BUMEP R BRACKET SIDE RH REAR
5	1 BUMEP R RETAINER RH REAR
6	1 BUMPER REFLECTOR RH
7	1 BUMEP R BRACKET SIDE LH REAR
8	1 BUMPER RETAINER LH REAR
9	1 BUMPER REFLECTOR LH
10	1 BUMPER BEAM REAR
11	1 BUMPER BEAM BRACKET LH REAR
12	1 BUMPER BEAM BRACKET RH REAR
13	1 OUTER PANEL REAR (End Panel)
14	1 OUTER PANEL REAR (End Panel)TRIM
15	1 BOOT REAR
16	1 TAILLAMP RH
17	1 TAILLAMP PANEL RH
18	1 TAILLAMP LH
19	1 TAILLAMP PANEL LH

\$	<i>Sur</i> 1,108.46	<i>✓</i>
\$	<i>Not Auth</i> 768.84	<i>✓</i>
\$	<i>Sur</i> 113.47	<i>X</i>
\$	<i>Sur</i> 135.97	
\$	<i>Sur</i> 44.99	
\$	<i>Sur</i> 43.61	
\$	<i>Sur</i> 135.97	
\$	<i>Sur</i> 44.99	
\$	<i>Sur</i> 43.61	
\$	<i>N</i> 777.52	
\$	<i>N</i> 225.95	
\$	<i>N</i> 225.95	
\$	<i>N</i> 1,471.77	
\$	<i>Sur</i> 404.56	
\$	<i>N</i> 2,872.68	
\$	<i>Sur</i> 552.55	
\$	<i>N</i> 986.70	
\$	<i>Sur</i> 552.55	
\$	<i>N</i> 986.70	

\$ **11,496.85**10% \$ **1,149.69**\$ **10,347.17****Specical Nett**

1	1SET PARKING AID	\$	<i>Sur</i> 700.00	<i>X</i>
2	1SET REAR BUMPER CLIP	\$	<i>Sur</i> 66.00	<i>✓</i>
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>Sur</i> 33.00	<i>✓</i>

Trans-cab Auto Services Pte Ltd**AAD1901-286**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5931U

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	ra	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	ra	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	ra	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	ra	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	ra	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	ra	66.00	
10	1 EXHAUST MOUNTING REAR	\$	ra	17.82	} X
11	2 REAR WINDSCREEN SELANT	\$	ra	80.00	
12	1 WINDSCREEN MOULDING	\$	ra	100.00	
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	ra	100.00	
14	1 REAR BOOT STICKER 'Trans-cab'	\$	ra	80.00	
15	1 REAR BOOT STICKER '6555-3333'	\$	ra	80.00	
TOTAL		\$		605.82	
TOTAL PARTS		\$		10,952.99	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001
To Rust-Proofing Of The Affected Areas.	\$	ra 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	ra 170.00	X
To repair and realign rear exhaust pipe.	\$	ra 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	ra 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	ra 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1901-286**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5931U

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *nn* 170.00 X

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 X**TOTAL \$ 7,410.00****Over All Total \$ 28,710.15****(LUMP SUM)****Repair Days***10 DAYS**2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey s on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: