

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5192K****AAD1901-232***Not written  
11ump & 52d*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHC 5192K**

VF1ABL15AUC276554

RENAULT

LATITUDE

24.1.2019

**EQ**

24/1/2014

**PART****LIST**

1	BUMPER COVER FRT	\$	R	1,259.42
1	BUMPER SPOILER FRT	\$	Sm	181.75
1	BUMPER ABSORBER FRT	\$	Sm	394.68
1	BUMPER RETAINER FRT LH	\$	Sm	151.41
1	BUMPER SUPPORT FRT	\$	Sm	123.88
1	BUMPER RETAINER FRT RH	\$	Sm	150.77
1	BUMPER SUPPORT FRT	\$	Sm	123.88
1	BUMPER UNDERTRAY FRT	\$	Sm	472.83
1	BUMPER GRILLE LOWER FRT	\$	Sm	266.80
1	BUMPER FOG LAMP GRILLE LH	\$	Sm	207.21
1	BUMPER BEAM FRT	\$	R	914.08
1	HEADLAMP LH	\$	Sm	1,184.43
1	HEADLAMP PANEL FRT LH	\$	R	152.15
1	FENDER PANEL FRT LH	\$	R	783.83
1	WHEELARCH FRT LH	\$	Sm	278.84
1	FENDER BRACKET LOWER LH	\$	Sm	15.79
1	FENDER INSULATOR LH	\$	Sm	130.84
1	DOOR PANEL FRT LH	\$	R	2,844.66
1	RADIATOR GRILLE	\$	Sm	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	Sm	225.36
1	RADIATOR GRILLE FRAME	\$	Sm	1,353.75
1	RADIATOR FAN COWLING	\$	Sm	820.54
1	RADIATOR FAN MOTOR LH	\$	Sm	967.36
1	RADIATOR FAN MOTOR RH	\$	Sm	1,479.46
1	RADIATOR GRILLE FRAME	\$	Sm	1,353.75
1	FRAME FULL SUPPORT PANEL	\$	R	615.90
1	FRAME FULL SUPPORT BRACKET	\$	R	89.79
1	AIR CLEANER BOX	\$	Sm	464.20
1	AIR CLEANER HOSE	\$	Sm	175.85

*X*

**Trans-cab Auto Services Pte Ltd**

AAD1901-232

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5192K

<b>TOTAL</b>	\$	<b>18,891.00</b>
<b>10%</b>	\$	<b>1,889.10</b>
	\$	<b>17,001.90</b>

**Special Nett**

1SET	BUMPER CLIP FRT	\$	na	66.00	} X
1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
1SET	WHEELARCH CLIP FRT RH	\$	na	30.50	
1	FRONT BUMPER ADVERTISEMENT STICKER	\$	cut	300.00	150%
		\$		<b>608.00</b>	

<b>TOTAL PARTS</b>	\$	<b>17,609.90</b>
--------------------	----	------------------

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	150%
Putty and spray painting of the affected portion.	\$	3,000.00	220%
To rust-proofing of the affected areas.	\$	na	170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00 X
To check steering geometry and computer wheel alignment	\$	na	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X
To Check Electrical Lighting Concerned.	\$	na	170.00 X

**Trans-cab Auto Services Pte Ltd**

**AAD1901-232**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5192K**

To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	<i>na</i> 380.00	X
To replace, refix and top up coolant for radiator	\$	<i>na</i> 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>na</i> 170.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	X

**TOTAL \$ 9,090.00**

**Over All Total \$ 26,699.90**

**LUMP SUM (REPAIR DAY)**

**~~10-DAYS~~**

*1 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: