



ZOOM AUTOWERKS PTE LTD

832 Sims Avenue, Eunosville
#12-884 Singapore 400832
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Allowed

11 January 2019

*2/s 4600/2
7/2/19*

REG NO. : SGN 5602 Z
MAKE/MODEL : DAIHATSU SIRLON

*Take photo of the car
f dry.*

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION LIST ITEMS	AMT(\$)
1	Rear windscreen inner seal	\$ <i>neu</i> 85.00 ✓
1	Rear tailgate	\$ <i>body</i> 781.50 ✓
2	Rear tailgate dampers	\$ <i>11</i> 201.60 X
1	Rear tailgate inner board	\$ <i>11</i> 135.60 X
1	Rear tailgate inner lock	\$ <i>11</i> 231.50 ✓
1	Rear tailgate outer garnish	\$ <i>11</i> 189.50 X
1	Rear tailgate rubber	\$ <i>twi</i> 126.30 ✓
1	Rear tailgate LOGO	\$ <i>11</i> 45.00 X
1	Rear tailgate "SIRLON" emblem	\$ <i>neu</i> 42.50 ✓
1	Rear tailgate "DAIHATSU" emblem	\$ <i>neu</i> 48.50 ✓
1	Rear tailgate "1.3" emblem	\$ <i>neu</i> 42.00 ✓
1	Rear wiper arm	\$ <i>11</i> 145.00 X
1	Rear wiper motor	\$ <i>11</i> 385.00 X
2	Rear taillamps	\$ <i>o/s cu</i> 990.60 <i>12C</i>
1	Rear end panel	\$ <i>body</i> 555.60 ✓
1	Rear end panel inner garnish	\$ <i>twi</i> 198.00 ✓
1	Rear bumper	\$ <i>11</i> 625.30 ✓
2	Rear bumper brackets	\$ <i>o/s cu</i> 84.00 <i>12C</i>
1	Rear bumper clips (1 set)	\$ <i>neu</i> 50.00 ✓
2	Rear bumper side retainers	\$ <i>cu</i> 76.00 ✓
2	Rear number plate lamps	\$ <i>cu</i> 64.00 <i>12C</i>
1	Rear floor board	\$ <i>11</i> 162.00 X
1	Rear floor panel	\$ <i>crumple / suc</i> 861.50 ✓
1	Rear fender	\$ <i>11</i> 642.00 X
2	Rear fender inner trims	\$ <i>o/s cu</i> 483.20 <i>12C</i>
1	Rear exhaust pipe	\$ <i>11</i> 774.00 X
2	Rear exhaust mountings	\$ <i>11</i> 57.00 X
		\$ 8,082.20
	Less 15%	\$ 1,212.33
		\$ 6,869.87

781.00

145.00

285.00

412.00

160

545.00

32

225.10

*9- 3958.90
15%*

9- 3365.06

S.N- 280.00

(Labor - 2520.00)

6165.06

4932.

c/f: \$ 6,869.87

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$	80.00	40
1	Rear number plate with holder	\$	50.00	40
1	Rear reverse sensor (1 set)	\$	350.00	200
		\$	480.00	

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes.	\$	150.00	80
3	To remove and refit rear reverse sensor.	\$	120.00	50
4	To transfer Rear tailgate mechanism and wiring assembly.	\$	120.00	60
5	To remove and refit rear windscreen glass.	\$	180.00	120
6	To remove, refit and replace exhaust silencer and mountings.	\$	150.00	110
7	To apply undercoating.	\$	200.00	90
8	Panel beating.	\$	1,600.00	1100
9	To re-spray painting on the affected areas.	\$	1,500.00	1000
		\$	4,100.00	

2520

GRAND TOTAL : \$ 11,449.87

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: