

INS. CASE OWNER:

Lynn

CC 4 / AXA1900

LKK:

IDAC:

Surveyor:

MD

DOI:

ASSIGNMENT

Poh Kin

Date / Time:

11/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SJD 11329

Name of Insured :

Vinh Yang Lim

Insured Tel No. :

HP:

1/2/19

Excess Sec II :S\$

D.O.A :

Is driver the owner?

(YES / NO)

Nature of Accident :

Claim No. :

S9moua9/96950

Policy No. :

V116K41611X

Make / Model :

Toyota

Place of Accident :

KYE TO SOUTH BRITAIN STR RD

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SME 933C

INSRS:
WSP:
Tel :
Liability :
RMKS:

SMKT

INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 12/3/2019

After call ltr to OI: 12/3/2019

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

UTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

10/4/2019

Sent By:

Cpk

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 2,150.00

(4 days)

Reduction:

69.65

%

Email

Call

FINAL SETTLEMENT

Date/Time:

15/4/2019

Confirm with

Lee GeK

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 15

Repair Cost:

S\$ 2,150.00

Loss of Rental (LOR):

S\$ 936.25

(7 days)

x \$ 163.75

Loss of Use (LOU):

S\$ -

(\$ x

days)

Loss of Income (LOI):

S\$ -

(\$ x

days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

S\$ 7.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 3,093.25

Global Sum S\$:

3,090.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 3,090.00

Name 1:

SMKT TAXIS PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$350.00

COPY SENT

$A \times A$

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Sum Sum:	10	%	3 Val: Yes or No
----------	----	---	------------------

Date	Person Contacted
------	------------------

TOYO/YOKO or Westlake

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

$\frac{115142,150.00 \text{ (Rendita) } 4,934.59}{69.65\%}$

02/19/2001

SJD 1132 G

TATAT

Lump Sum / I.B.t. (\$)

Add Fee: Site Insp (\$

☐ Site Insp (\$

☐ Interview (\$



Tech Invs (\$)

☐ Weekend (\$)
$$) \quad S + RS \quad SI$$

Poh Kian

Section A - Accident Details

Registration Number	SHB933C
Case Reference Number	TAX/02/19/2001
Registration Date	30/10/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	YEO AH NGUAN
Type of Accident	Side Swipe
Accident Date and Time	1/2/2019 8:25 AM
Accident Reported Date and Time	1/2/2019 10:01 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24099956
Special Instruction to ARC, if any	TSS
Prepared Date and Time	1/2/2019 11:33 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Toyota

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$600.00
Total Spray Cost	\$1,494.00	\$750.00
Total Spare Part Cost	\$3,511.59	\$692.22
Total Other Cost	\$1,065.00	\$120.00
TOTAL COST	\$7,084.59	\$2,162.22
Lump Sum Total	\$7,100.00	\$2,150.00 (L/S)
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AXA
ARC / Surveyor Sign Off Date	07/02/2019 4:55 PM	07/02/2019 3:57 PM
Signature		
Remarks		L/S repair, photo after paint.

Finalized - Hwee Jie

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1902-0360	Invoice Number	
Quotation Date	25.02.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$1,014.00	\$600.00
Total Labour	\$1,014.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,494.00	\$750.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,065.00	\$120.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given
			SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given
		61604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		62591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given
		42611--47140	WHEEL DISC	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair

		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	
	75851-47900	MOULDING BODY, RH	1.00	\$673.60	100.00	\$0.00	Replace	Repair	
	65637-47021	FENDER LINER RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Check	
	67003-47080	DOOR RR/RH	1.00	\$954.50	25.00	\$715.88	Replace	Replace	
	52159-47905	BUMPER REAR	1.00	\$458.60	100.00	\$0.00	Replace	Repair	
		STICKER DECAL 6555 6888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	
	62710-47130	QUARTER GLASS RR/RH	0.00	\$846.50	0.00	\$0.00	Replace	Not Given	
Total				\$5,730.50		\$865.28			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

4363.50

865.28
- 20%

692.22
+ 600.00
+ 870.00

2162.22

US \$2150/-

26/2/19 - Finalized C/s \$2150/- 4 days.

ans



Case Details

Case Reference Number : TAX/02/19/2001
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB933C

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5589-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AXA Insurance Singapore Pte Ltd
 Accident Date and Time : 01/02/2019 12:25 AM
 Vehicle Age(In Months) : 64

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation				Surveyor Approval						Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	715.88	Replace ▾	DD
One Time Key In	Main			MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	1	0	Repair ▾	
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair ▾	
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	0	0	Check ▾	
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace ▾	NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace ▾	NEC
One Time Key In	Main			QUARTER GLASS RR/RH	1	846.50	846.50	25.00	634.88	Replace	0	0	Not Give ▾	
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give ▾	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair ▾	
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give ▾	

Total Spare Part Cost 4,389.49

Surveyor Total 865.28

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 3,511.59

Final Sur Total 692.22

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	NEC
One Time Key In	Main			WHEEL DISC	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	
Total Spare Part Cost									4,389.49	Surveyor Total 865.28				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									3,511.59	Final Sur Total 692.22				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	1,014.00	600	
Total:			1,014.00	600.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY RH REAR DOOR	378.00	200	
2	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100	
3	Main	TO RESPRAY REAR FENDER RH	378.00	200	
4	Main	TO RESPRAY RIM	180.00	50	
5	Main	TO REPSRAY REAR BUMPER	378.00	200	
Total:			1,494.00	750.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
Total:			1,065.00	120.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	
4	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0	
5	Main	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0	
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
7	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30	
8	Main	TO REMOVE / REFIT SEAT	120.00	0	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0	
10	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,065.00	120.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,511.59	692.22
Total Labour Cost	1,014.00	600.00
Total Spray Painting	1,494.00	750.00
Other	1,065.00	120.00
Overall Total	7,084.59	2,162.22
Lump Sum Repair Option	☒	☒
Lump Sum Total	7,100.00	2,150.00
Surveyor Approved Amount		2,150.00
No of Repair Days*	7	4
Remarks		L/S repair, photo after paint.
Surveyor Name		Hwee jie

Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature

D

Save

Clear

Survey Date

07/02/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Poh Kin (LKKAUTO)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Monday, 15 April 2019 4:41 PM
To: Poh Kin (LKKAUTO)
Cc: Admin A
Subject: Acceptance of offer Re: Accident on 1/2/2019 involving SHB 933C & SJD 1132G (AXA's insured) Our Ref: TAX/02/19/2001/lg

Dear Poh Kin,

We agreed to accept your offer of \$3,090.00 for our own losses. Please let us have your DS. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)
Claims Department
SMRT Automotive Services Pte Ltd



From: Poh Kin (LKKAUTO) [mailto:pohkin@lkkauto.com]
Sent: 11/04/2019 15:39
To: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis)
Cc: Admin A
Subject: RE: LOD Re: Accident on 1/2/2019 involving SHB 933C & SJD 1132G (AXA's insured) Our Ref: TAX/02/19/2001/lg
Importance: High

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Our Ref: CC4/ASM19002371/Jfb3
Your Ref: TAX/02/19/2001/lg

Dear Lee Gek,

We refer to above matter and your letter of demand.

Towards an amicable settlement and without admission of liability to our Insured's part, we have instruction from our principal to offer settlement at global sum of **\$3,090.00**(all in) on this matter.

kindly confirm acceptance.

Your prompt reply will be very much appreciated.

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Thursday, 11 April 2019 3:39 PM
To: LeeGek@smrt.com.sg
Cc: Admin A
Subject: RE: LOD Re: Accident on 1/2/2019 involving SHB 933C & SJD 1132G (AXA's insured) Our Ref: TAX/02/19/2001/lg

Importance: High

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Our Ref: CC4/ASM19002371/Jfb3
Your Ref: TAX/02/19/2001/lg

Dear Lee Gek,

We refer to above matter and your letter of demand.

Towards an amicable settlement and without admission of liability to our Insured's part, we have instruction from our principal to offer settlement at global sum of **\$3,090.00**(all in) on this matter.

kindly confirm acceptance.

Your prompt reply will be very much appreciated.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



AUTO
CONSULTANTS
PTE LTD

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



Re:<S9M01CQ9> IA Mandate uploaded

Type

🔗 Question

Message

Proceed with Proposed quantum. Thanks

Reply



<S9M01CQ9> IA Mandate uploaded

Type

🔔 Question

Message

Dear Lynn, Liability: Insured Driver collided into third party vehicle while changing lane. Liability is down against our insured. We did clarify with insured (Mr Yang) the nature of the accident and he agree to settle, aware that NCD (if any) is affected. Immediate Advice (with mandate) have been uploaded in SMART CLAIM. We hereby seek your approval to offer Third Party repairer M/s "SMRT Automotive Services Pte Ltd" is as follows: - 1)COR : \$2,150.00 + 2) Loss of Rental (7daysx\$133.75): \$936.25 + 3) LTA : \$7.00= Total: \$3,093.25. **04days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your approval please. PohKin - 10/04/2019

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 10/04/2019

Survey Details:

Date of loss	1-Feb-19
Date of appointment	11-Feb-19
Date of survey	7-Feb-19
Location of survey	SMRT AUTOMOTIVE SERVICES PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHB 933C
Make and Model	TOYOTA PRIUS
Date of registration	30/10/2013
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 7,962.49
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 692.22	list -20%
Check items (estimate)	\$ -	
Labour	\$ 1,470.00	
Total	\$ 2,162.22	
Lump Sum(if applicable)	\$ 2,150.00	

Number of days for repair	4
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

SMRT send PRI to M/s AXA on 02.02.2019
vehicle only survey on 07.02.2019 due to public holiday
TP claim 11 days for LOR, we propose 7 days for LOR

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	2,150.00
Loss of use	\$	-
Loss of rental	\$	936.25 (\$133.75 x 7 days)
Loss of income	\$	-
LTA search fees	\$	7.00
Others	\$	-
Proposed Total	\$	3,093.25

Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)

From: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) on behalf of Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis)
Sent: 02/02/2019 10:21
To: 'motor.survey@axa.com.sg'
Cc: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)); Chew Tuck Loong Kelvin (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); Chin Kim Ming (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))
Subject: RE: SHB933C- Survey (AXA)
Attachments: 2001 - 933.pdf

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHB933C** within 48 hours according to GIA guide line, involving your insured **SJD1132G**

Vehicle in Woodlands SMRT Depot

Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | bthaiyaln@smrt.com.sg



**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SJD 1132G (Insd veh)	Model:	TOYOTA PRIUS
	SHB 933C (TP veh)		
Date of Accident:	01/02/2019		

Global Sum Settlement	: [X] Yes	[] No
Repair Estimate	: \$	9,363.50
Final Repair Cost	: \$	2,150.00
Loss of Token Sum	: \$	days at \$0.00 per day
Rental (if any)	: \$	936.25 7 days
LTA / GIA Search Fee	: \$	7.00

Others:	: \$
---------	------

	: \$
Final Settlement Sum (GLOBAL SUM)	: \$ 3,090.00

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown		
1)	SMRT TAXIS PTE LTD	: \$ 3,090.00

NUR SHAQILAH BTE ABDOL
WAHAB

26/04/2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19002371/Jfb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811
ATTN: LYNN KHONG

Date : 26-04-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJD 1132G	Veh. Inspected	SHB 933C
Policy No.	VA1/GA416117	Coverage (\$)	0.00
Claim No.	S9M01CQ9	Excess (\$)	0.00
Assign From	LYNN KHONG	Assign Date	11/02/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTDKN36UX05694477	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	WEST LAKE	6 mm
L/H Front Tyre	195/65R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65R15	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/02/2019	Inspection Date	07/02/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 933C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	DOO RR/RH (DISC 25%) (CONSISTENT)	DENTED	954.50	715.88
2	PIXEL STICKER @ \$60.00 (SN) (CONSISTENT)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN) (CONSISTENT)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN) (CONSISTENT)	NECESSARY	21.60	21.60
1	BUMPER LIP COVER RR/RH (CONSISTENT)	NOT NECESSARY	118.10	-
1	SEALANT W/SCREEN (CONSISTENT)	NOT NECESSARY	37.00	-
1	BUMPER SIDE RETAINER RR/RH (CONSISTENT)	NOT NECESSARY	94.80	-
1	BUMPER SEAL, RR RH (CONSISTENT)	NOT NECESSARY	65.70	-
1	FENDER LINER RR/RH (CONSISTENT)	NOT NECESSARY	141.30	-
1	QUARTER GLASS RR/RH (CONSISTENT)	NOT NECESSARY	846.50	-
1	FENDER RR/RH (CONSISTENT)	TO REPAIR SEE LABOUR	766.80	-
1	WHEEL DISC (CONSISTENT)	TO REPAIR SEE LABOUR	1,484.20	-
1	MOULDING BODY, RH (CONSISTENT)	TO REPAIR SEE LABOUR	673.60	-
1	BUMPER REAR (CONSISTENT)	TO REPAIR SEE LABOUR	458.60	-
1	SOLAR FILM (SN) (CONSISTENT)	NOT NECESSARY	125.00	-
			5,915.50	865.28
<u>LABOUR</u>				
PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF FENDER RR/RH; WHEEL DISC; MOULDING BODY, RH AND BUMPER REAR.			1,014.00	600.00
SPRAY PAINT.			1,494.00	750.00
TO APPLY RUST-PROOFING ON AFFECTED AREA.			100.00	30.00
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	-
TO DO WHEEL ALIGNMENT / TYRE BALANCING.			120.00	60.00
TO REMOVE & REFIT REAR QUARTER GLASS RH.			120.00	-
TO REMOVE / REFIT SEAT.			120.00	-
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)			120.00	30.00
TO REPLACE SUNDRY PARTS.			100.00	-

Report Ref No. CC4/ASM19002371/Jfb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TEST AND REFIT REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,448.00	1,470.00
GRAND TOTAL			9,363.50	2,335.28
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,150.00

Report Ref No. CC4/ASM19002371/Jfb3s2

ONG HWEE JIE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.