

ASS. REC. BY:

REF

CS/CTI19002375/ Upd3 12

Special Instruction:

Surveyor:

Manny

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

11/2/19 @ 11:57am

Estimated Cost:

Bill to:

OD / TT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP7902X

Insured:

SKG7315D

at Workshop m/s

Think one Auto

Tel:

9128 8488

of

No. 18 De Fu Ave 2

Policy No:

MUPCSN 30927418022

Claim No:

SNM19D200267C02/5.

Sum Insured:

Excess:

Make of Veh:

D.O.A.

8/1/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

1:38pm @ 11/2/19

Person Contacted:

Kern

Vehicle IN/OUT

OUT

Date/Time

Action/Instruction (✓) Estimate

YP7902X-X

SKG7315D-CS/CTI19000950/R1sd3

D.O.A: 8/1/2019

REF: CTH

ASSIGNMENT

Form: Date: 12/2/19

Estimated Cost:

Of: TP/WS/TP RES/OD RES/EVA/INV/IV

To inspect Vehicle No:

YP 7902X

at Workshop No:

Think one

at:

No 18 Defu Ave 2

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

3pm

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / FR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res: Yes or No

Lump Sum:

2

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

1up

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

LTA 36823

10/8/18 2/s 4400 conf. w/ michael (had 37000.20, 89%)

RECEIVED 13 SEP 2019

Date/Time, File Pass to:

13/9 12/19/19

Date/Time, File Return to:

71

Report Format:

Lump Sum / 1.5 / 1.5

MER-TP  
4400

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

- ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Ins (\$)  
☐ Weekend (\$)

Survey Fee:

Transportation:

1. S. P. 34

1. Photo

1. Report

1. ...

TOTAL

220

Veh No: YP 7902X @ Regn: 11 17  
 Type: M/Car / M/Cycle / Bus / Van / Comp / Taxi / Prime Mover /  
 Truck / Trailer or (M)  
 Make: HINO UD TRUCKS 7013  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp Reading: 40117 T/Radio: Insured / Std / NI / NA  
 Eng/Ho:  
 C/Ho: JNCLOFIAXH402620  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Jumper / Jammed / Leaked / Burnt or  
 Brake: Jumper / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F:  
 R: 11 R 22.5  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: R/Bal. 7 mm  
 L/Bal. 7 mm  
 D.O.A. 8/1/19  
 Survey held at:  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 Rear  
 The U/C / Chassis frame / Body Structure affected due to collision.

Rear: R/Bal. 7/7 mm  
 L/Bal. 7/7 mm  
 D.O.A. 12/2/19

## Nivitha (LKK Auto)

---

**From:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Sent:** Monday, 11 February 2019 11:57 AM  
**To:** karentan@thinkone.com.sg; 'assignments'  
**Subject:** FW: YP7902X & SKG7315D ACCIDENT DATED ON 08.01.2019 (CLAIM NO. SNM19D200267C02/5)  
**Attachments:** SAS2532627.PDF  
**Importance:** High

### WITHOUT PREJUDICE

Dear Karen,

We refer to your email of 30.01.19.

Liability clear.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please refer to the attachment and proceed to survey the third party vehicle.

Thank you.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



---

**From:** Karen Tan [mailto:karentan@thinkone.com.sg]  
**Sent:** Wednesday, 30 January, 2019 12:58 PM  
**To:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Subject:** RE: YP7902X & SKG7315D ACCIDENT DATED ON 08.01.2019  
**Importance:** High

Hi Elaine,

I would like to arrange a surveyor for YP7902X. As my client is claiming against your insured SKG7315D for the above mentioned accident.

Thank you.

**Karen Tan**

Claim Advisor

Think One Autocare Pte Ltd

No.18 Defu Avenue 2

Singapore 539522

HP : 9128 8488

DID : 6844 3300 FAX : 6842 4988

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> [Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	5609M
<b>Vehicle Details</b>	
Vehicle No.:	YP7902X
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Feb 2019
Vehicle Make:	UD TRUCKS
Vehicle Model:	PKC8ELN5EP
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	GH7212283
Chassis No.:	JNCL0F1AXHU026210
Maximum Power Output:	-
Open Market Value:	\$57,282.00
Original Registration Date:	20 Nov 2017
First Registration Date:	20 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$2,865.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	19 Nov 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,004.00
COE Rebate Amount:	\$36,823.00
<b>Total Rebate Amount:</b>	<b>\$36,823.00</b>

The information contained herein is correct as at 13 Feb 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/01/2019 11:24
Date Of Accident	08/01/2019 14:15
Exact Location Of Accident	AYE AFTER CLEMENTI AVE 2 FLYOVER
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP7902X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THINK ONE LEASING PTE LTD
Co Reg No	201115609M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96788288
Alternative Phone No	OFFICE-65553300

### Vehicle Particulars

Manufacturer	UD TRUCKS
Model	PK8ELN5EPC-7.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	GOODS VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5070244660-03
Cover Note Number	

### Driver

Name of Driver	KAMIS BIN SAMSI
NRIC No	S1629477B
Date Of Birth	01/10/1964
Occupation	OUTDOOR
Date Of Driving Pass	19/09/1996
Driving Experience	22 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94891423
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	APT BLK 297 CHOA CHU KANG AVENUE 2 #09-124
Postcode	680297
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON THE 08.01.2019 AT ABOUT 14:15HR. I WAS DRIVING AT THE STATED LOCATION. I WAS ON THE LEFT MOST LANE. A VEHICLE OF SKG7315D FROM BEHIND COLLIDE AT MY REAR PORTION. NO INJURIES INCURRED IN THIS ACCIDENT.


#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKG7315D
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 08.01.2019 at about 14:15HR. I was driving at the stated location. I was on the left most lane. A vehicle of SKG7315D from behind collide at my rear portion. No injuries incurred in this accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

GAARVIG SketchPlanForm\_V3



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

9-1-19 1130

*(Signature)*

Think One Autocare Pte Ltd  
18 Defu Lane Avenue 2  
Singapore 639522

Tel: 6844 3300 Fax: 6844 9889

Name:

NRIC/FIN No.:



**Think One Autocare Pte Ltd**  
**No.18 Defu Avenue 2**  
**Singapore 539522**  
**Tel: 6844 3300 Fax: 6842 4988**

**YP7902X UD Truck PK8ELN5EPC**

No	Qty	Parts Description		Estimated Parts Price	
1	1	Rear right taillamp	17	\$ 696.00	X
2	1	Rear left taillamp	17	\$ 696.00	X
3	2	Rear taillamp bracket	17	\$ 186.00	X
				\$ 1,578.00	
Less 10%				\$ 157.80	
				<u>\$ 1,420.20</u>	

Special Nett Items

1	1	Rear liftgate complete assy	17	\$ 14,800.00	X
2	1	Rear centre lower bar	17	\$ 780.00	X
3	2	Rear liftgate liftarm bracket	17	\$ 1,270.00	X
4	1	Rear lower reinforcement bar	17	\$ 1,200.00	X
5	1	Rear lower aluminium bar	8u	\$ 860.00	X
6	1	Rear solenoid valve switch and cable	17	\$ 380.00	X
7	2	Rear liftgate red reflector	17	\$ 160.00	X
8	1	Rear no plate	17	\$ 60.00	X
9	1	Rear liftgate 'A.J.K 5m' sticker	17	\$ 60.00	X
10	1	Rear centre lower bar red/white safety sticker	17	\$ 160.00	X
11	1	Rear liftgate centre red/white sticker	17	\$ 80.00	X
12	1	Rear hydraulic pump master	17	\$ 4,200.00	X
13	2	Rear hydraulic damper (outer)	17	\$ 6,800.00	X
14	2	Rear hydraulic damper (inner)	Daye/1st	\$ 4,800.00	X
				<u>\$ 35,610.00</u>	

**Total parts**

**\$ 37,030.20**

*not about  
like*

*L/S \$ 4400  
3 day*

*Wh p wh After rep.  
12/2/19*

LKK Auto Consultants hereby notify the Repairer of the following:

- To involve before repairer spray painting
- To supply damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal financial entry is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Think One Autocare Pte Ltd  
No.18 Defu Avenue 2  
Singapore 539522  
Tel: 6844 3300 Fax: 6842 4988

**YP7902X UD Truck PK8ELN5EPC**

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	11 \$ 1,400.00 X
2	To remove and replace rear liftgate complete assy.	\$ 1,400.00 } 800
3	To test rear liftgate hydraulic system for function.	\$ 600.00 }
4	To putty and spray painting rear portion.	11 \$ 800.00 X
5	To check rear lighting and wiring.	\$ 50.00 20
6	To apply anti rust proofing to rear affected area.	11 \$ 120.00 X
<b>Total labour :</b>		<b>\$ 4,370.00</b>

**Total parts : \$ 37,030.20**

**Total labour : \$ 4,370.00**

**Total repair cost : \$ 41,400.20**

5820

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19002375/UQD3N2

Date: 16/09/2019

## REFERENCE

<b>Handling Insurer:</b>	China Taiping Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b>	DMPCSN30927418022	
<b>Claimant Vehicle No :</b>	YP7902X	<b>Insured Vehicle No :</b>	SKG7315D	
<b>Date of Loss:</b>	08/01/2019	<b>Nature of Claim:</b>	TP	<b>Claim No:</b> SNM19D200267C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	YP7902X	<b>Engine No:</b>	GH7212283
<b>Make &amp; Model:</b>	UD TRUCKS PK8ELN5EPC, 7.0 D (M)	<b>Chassis No:</b>	JNCL0F1AXHU026210
<b>Reg. Date:</b>	20/11/2017 (Man. Year: 2017)	<b>Odometer:</b>	40117 km
<b>Colour:</b>	White		
<b>Engine Capacity:</b>	7013 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (\$\$):</b>	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>		<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>	

## CONDITION OF TYRES

<b>Front Tyre Size:</b>	11R22.5	<b>Rear Tyre Size:</b>	11R22.5 (D)
<b>Front Left Side:</b>	Dunlop 7 mm	<b>Rear Left Side:</b>	Dunlop 7/7 mm
<b>Front Right Side:</b>	Dunlop 7 mm	<b>Rear Right Side:</b>	Dunlop 7/7 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	37,030.20	4,800.00	32,230.20	87.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,370.00	820.00	3,550.00	81.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>41,400.20</b>	<b>5,620.00</b>	<b>35,780.20</b>	<b>86.43</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,400.00</b>		
<b>(\$\$)</b>	41,400.20	4,400.00	37,000.20	89.37
<b>+ GST 7.00/7.00% (\$\$)</b>	2,898.01	308.00	2,590.01	89.37
<b>Nett Amount (\$\$)</b>	<b>44,298.21</b>	<b>4,708.00</b>	<b>39,590.21</b>	<b>89.37</b>

## INSPECTION

<b>Date of Assignment:</b>	13/09/2019	
<b>Date Inspected:</b>	12/02/2019	<b>Inspected At:</b> Think One Autocare Pte Ltd (HQ) No. 18 Defu Avenue 2 Singapore 539522
<b>Estimated Period of Repair:</b>	3.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 16 Sep 2019)	
<b>Parts:</b>	N/A	UD TRUCKS PK8ELN5EPC 7.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for YP7902X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RIGHT TAILLAMP	Not Necessary	696.00 FL	*- FL
2	1		*REAR LEFT TAILLAMP	Not Necessary	696.00 FL	*- FL
3	2		*REAR TAILLAMP BRACKET	Not Necessary	186.00 FL	*- FL
4	1		*REAR LIFTGATE COMPLETE ASSY	Not Necessary	14,800.00 FS	*- FS
5	1		*REAR CENTRE LOWER BAR	Not Necessary	780.00 FS	*- FS
6	2		*REAR LIFTGATE LEFTARM BRACKET	Not Necessary	1,270.00 FS	*- FS
7	1		*REAR LOWER REINFORCEMENT BAR	Not Necessary	1,200.00 FS	*- FS
8	1		*REAR LOWER ALUMINIUM BAR	Serviceable	860.00 FS	*- FS
9	1		*REAR SOLENOID VALVE SWITCH AND CABLE	Not Necessary	380.00 FS	*- FS
10	2		*REAR LIFTGATE RED REFLECTOR	Not Necessary	160.00 FS	*- FS
11	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
12	1		*REAR LIFTGATE A.J.K 5M STICKER	Not Necessary	60.00 FS	*- FS
13	1		*REAR CENTRE LOWER BAR RED/WHITE SAFETY STICKER	Not Necessary	160.00 FS	*- FS
14	1		*REAR LIFTGATE CENTRE RED/WHITE STICKER	Not Necessary	80.00 FS	*- FS
15	1		*REAR HYDRAULIC MASTER	Not Necessary	4,200.00 FS	*- FS
16	2		*REAR HYDRAULIC PUMP (OUTER)	Not Necessary	6,800.00 FS	*- FS
17	2		*REAR HYDRAULIC PUMP (INNER)	Damaged/Bent	4,800.00 FS	*4,800.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>37,188.00</b>	<b>4,800.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>157.80</b>	<b>0.00</b>
<b>Total Parts (\$\$)</b>	<b>37,030.20</b>	<b>4,800.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,400.00	0.00
2	TO REMOVE AND REPLACE REAR LIFTGATE COMPLETE ASSY }	New	1,400.00	800.00
3	TO TEST REAR LIFTGATE HYDRAULIC SYSTEM FOR FUNCTION }	New	600.00	0.00
4	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	800.00	0.00
5	TO CHECK REAR LIGHTING AND WIRING	New	50.00	20.00
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,370.00</b>	<b>820.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >