

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

12-Feb-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHB 8055 J

1 pc	n/s head lamp ✕	\$ 1,531.57
1 pc	Front bumper ✓	\$ 811.11
1 pc	Front bumper emblem ✓	\$ 27.80
1 pc	Front bumper n/s side bracket ?	\$ 32.51
1 pc	Front n/s fender ✓	\$ 514.02
		\$ 2,917.01
Less 20%		\$ 583.40
		\$ 2,333.61

S/NETT

1 set	Front bumper clips ✓	\$ 48.00
1 pc	Front n/s fender sticker ✓	\$ 30.00

Sundry \$ ~~50.00~~ 20

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc \$ ~~650.00~~ 400

To putty and spray painting on front bumper, front n/s fender \$ ~~400.00~~ 360

To apply rustproofing on the repaired and replaced panels. \$ ~~120.00~~ 50

\$ 3,631.61

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalin 11/14

12/2/19 1600h

3 Pcs

1"

Labour Part p 11

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part(s) are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Illegal modification of all parts
- Supplemental items not be surveyed and is subject to trial approval from insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____