

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 658B**AAD1902-048**

Not Authorised
61 Sep @ 5900

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHF 658B

VF1ABL15AUC278716

RENAULT

LATITUDE

5.2.2019

AXA

30/6/2014

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>CM</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>Del/An</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>Di</i> 44.99	✓
9	1 BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1 BOOT REAR	\$	<i>R</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	X
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	<i>R</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>R</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45	
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	

Trans-cab Auto Services Pte Ltd**AAD1902-048**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 658B

30	1 FENDER PANEL REAR RH	\$	R	3,299.13	}
31	1 WHEELARCH REAR RH	\$	Sn	543.47	
32	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	
33	1 WHEEL HOUSING PANEL REAR RH	\$	R	4,682.09	
34	1 TAILLAMP LH	\$	Sn	552.55	
35	1 TAILLAMP PANEL LH	\$	R	986.70	
36	1 TAILLAMP RH	\$	Sn	552.55	
37	1 TAILLAMP PANEL RH	\$	R	986.70	
38	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	
39	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56	
40	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	
41	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	
42	1 EXHAUST REAR	\$	R	7,489.05	}
43	1 EXHAUST CAP REAR	\$	R	230.49	

TOTAL	\$	36,036.98
10%	\$	3,603.70
	\$	32,433.28

Special Nett

1	1SET PARKING AID	\$	Shon	700.00	Goan
2	1SET REAR BUMPER CLIP	\$	nu	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	nu	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nu	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	nu	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	nu	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	nu	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	nu	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	nu	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	nu	17.82	X
11	1SET BOOT FINISHER CLIP	\$	nu	24.20	X
12	1 REAR BOOT STICKER 'Trans-cab'	\$	nu	80.00	30sn
13	1 REAR BOOT STICKER '6555-3333'	\$	nu	80.00	30sn

Trans-cab Auto Services Pte Ltd**AAD1902-048**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 658B

16 1SET FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	}	X
17 1SET FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00		
18 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00		
19 1 FENDER INNER TRIM CLIP LH	\$	nn	28.00		
20 1 TAILLAMP CLIP RH	\$	nn	5.00		
21 1 TAILLAMP CLIP LH	\$	nn	5.00		
22 2 REAR WINDSCREEN SELANT	\$	nn	80.00		
23 1 WINDSCREEN MOULDING	\$	nn	100.00		
24 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00		
25 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00		
26 1 SPARE TYRE	\$	sn	330.00		

TOTAL \$ 2,280.02**TOTAL PARTS \$ 34,713.30****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	3001
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1902-048**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 658B

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>nn</i> 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X

TOTAL \$ 14,340.00**Over All Total \$ 49,053.30****(LUMP SUM)****Repair Days***20 DAYS**3 day,*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: