



Repair Estimates

Date: 02/02/2019

From:

Kok Tong Transport & Engineering
Works Pte Ltd
11, Sungei Kadut, Street 2, Singapore 729232.

Tel: 68045046,
Contact person: Chua Zongyu
HP: 96728578
DOA: 29/01/2019
Policy No: DMCVSN 1763211801

To:

China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road # 16-00 Spring Leaf Tower
S 079909

Tel: 63896111
Attn:
HP:
Vehicle No: XE3554M
Chassis No: JALCYZ52KH7000065

Sr No	Part	Description	Qty	Total Price
1	8-98130-331-1	BUMPER ASM <i>PA /</i>	1	\$1,100.00
2	1-86792-077-0	BUMPER LID RH <i>X</i>	1	\$100.00
3	1-86792-076-0	BUMPER LID LH <i>PA /</i>	1	\$100.00
4	1-71707-177-1	LH MIRROR STAY <i>DT /</i>	1	\$145.60
5	1-71798-829-1	LH MIRROR STAY BRACKET <i>PA /</i>	1	\$28.70
6	1-71797-809-2	LH BRACKET OUTSIDE MIRROR <i>Cut /</i>	1	\$21.00
7	1-71798-732-0	COVER, STAY OUTSIDE MIRROR <i>ANG CRA /</i>	1	\$14.00
8	1-71798-733-0	COVER, STAY OUTSIDE MIRROR <i>MIS /</i>	1	\$14.00
9	1-86855-031-0	POWER UNIT, MIRROR STAY <i>?</i>	1	\$304.50
10	1-71998-939-3	GRIP, ASSIST FRT PANEL LH <i>PA /</i>	1	\$42.70
11	1-71998-940-3	GRIP, ASSIST FRT PANEL RH <i>PA /</i>	1	\$42.70
12	1-21410-933-2	RADIATOR ASM <i>?</i>	1	\$4,175.50
13	1-14431-060-1	COOLER, CHARGE AIR <i>?</i>	1	\$4,294.50
14	1-76210-704-0	EMBLEM, RAD GRILLE <i>Cut /</i>	1	\$109.20
15	1-76217-189-0	DECAL MODEL <i>nu /</i>	1	\$18.20
16	1-83312-112-2	LINK ASM, FRT WIPER <i>PA /</i>	1	\$174.30
17	1-86810-122-0	BRACKET, WIPER MOTOR <i>PA /</i>	1	\$250.00
18	1-86810-121-0	MOTOR ASM, WIPER <i>PA /</i>	1	\$459.90
19	1-76117-057-0	WINDSHIELD GLASS <i>PA CRA /</i>	1	\$1,507.80
20	1-76737-158-4	WEATHER STRIP <i>nu /</i>	1	\$204.40
21	1-61281-410-2	FRT PILLAR LH <i>?</i>	1	\$550.00
22	1-61270-773-3	LH PANEL OUTER BACK CORNER <i>repair</i>	1	\$494.90
23	8-98125-810-4	CLOSING SIDE STEP LH <i>DE /</i>	1	\$222.60
24	1-64080-394-2	LH DOOR ASM <i>PA /</i>	1	\$1,500.00
25	1-71101-023-1	FRT PANEL <i>DE /</i>	1	\$1,127.00
26	1-71117-270-1	GRILLE LH <i>CRA /</i>	1	\$46.20
27	1-71117-269-1	GRILLE RH <i>X</i>	1	\$46.20
28	1-71117-268-2	GRILLE CENTER <i>DE /</i>	1	\$129.50
29	1-71107-864-0	PANEL SUPPORT ASM <i>CRA /</i>	1	\$132.30
30	1-79347-007-3	CABLE FRT LID <i>X</i>	1	\$26.60
31	1-65473-144-0	WIPER PANEL <i>PA /</i>	1	\$115.50
32	1-79317-026-1	LOCK ASM FRT LID LH <i>PA /</i>	1	\$44.80
33	1-79317-025-1	LOCK ASM FRT LID RH <i>X</i>	1	\$44.80
34	1-79318-008-1	STRIKER FRT LID <i>nu /</i>	2	\$22.40
35	1-65473-185-4	LH CORNER PANEL <i>CRA /</i>	1	\$336.70

36	8-98154-745-1	LH CABIN FENDER <i>CRA</i> ✓	1	\$486.50
37	8-98105-664-1	LH DOOR FENDER <i>DE</i> ✓	1	\$240.00
38	NIL	PAINT	1	<i>1400</i> \$1,800.00

Part Cost

\$20,173.00

Labour (Bodywork, Mech, Elect)

2000 ~~\$3,120.00~~

Total Cost (Excluded GST)

\$23,293.00

Resul

Hp 90010068

14 days

4s

12/02/19 @ 0900hrs

EXCESS: 1500

Revert

Resurvey after repair

UK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: