

ASS. REC. BY:

REFCS/CTI 1900 2396 / Dsd31ⁿ²

Special Instruction:

Surveyor: Bryan ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 11/2/19 @ 9.25am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SH 9615A Insured: SJS 8317R

at Workshop m/s: Chunni Motor Tel: 65425119

of Amekapoint # 01-05/06

Policy No: _____ Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 05/02/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{lup} H.O.D. Endorsement: _____


Date/Time: 9.37am @ 11/2/19 Person Contacted: lyn Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SH 9615A - NA / INCI 6015 436 / 3 Don: 28/8/2016
	SJS 8317R - CS3 / AXA / 2017777 / Avlc3-1 Don: 12/09/2012

COG July 2026

INSURANCE

Date: _____
 Estimated Cost: _____
 ODI / TP / WS / TP RES / OD RES / EVA / INV / MV: _____
 Category / Vehicle No: _____
 At Work / Repair: _____
 of: _____
 Insurance: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Claim's Record)
 Make of Vehicle: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 CIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: 12 days Res: Yes or No
 Sum Ins: 20 % 3 Val: Yes or No
 GA / REV / REP. / 24 HRS: _____
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



Vehicle: SH 9615A Regn: 2018 July
 Type: M Car / H Cycle / Bus / Van / Lorry / Tractor / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai Ioniq CC: 1580
 Color: Blue Insured / Std / NI / NA
 Sp Reading: 99792 T/Code: Insured / Std / NI / NA
 Engine: G4LEJU046137
 C/No: KMHC851CV5U103434
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: OK / Jammed / Leaked / Burnt or _____
 Brake: OK / Jammed / Leaked / Burnt or _____
 Mod: OK / SRim / STD AIRim or _____
 Tyre Size: F: 195 / 65 R15
 R: — " —
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Davanti
 Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: 05/02/2019 D.O.I: 11/02/2019
 Survey held at: Chunni AMC
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Front & Rear
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: Chun Teiping 858 8317R

15/03/19 found 4/5 16650/- with 12 days of rep

RECEIVED 21 MAR 2019

Date/Time File Pass to: _____
 1) 21/03/19 : Prelim. Report
Typet : Final Report
 Date/Time File Return to: _____
 2) _____
 Report Format: _____
 Lump Sum / L.B. / I.S: 16,650/- HS
 Days Of Repair: 12
 Resurvey No. of Trip: 2
 Add Fee: Site Insp. (\$) Interview (\$) Team Fee (\$) Workshop (\$) _____
 Survey Fee: _____
 Transportation: _____
 1) _____
 2) _____
 3) _____
 4) _____
 5) _____
 6) _____
 7) _____
 8) _____
 9) _____
 10) _____
 11) _____
 12) _____
 13) _____
 14) _____
 15) _____
 16) _____
 17) _____
 18) _____
 19) _____
 20) _____
 21) _____
 22) _____
 23) _____
 24) _____
 25) _____
 26) _____
 27) _____
 28) _____
 29) _____
 30) _____
 31) _____
 32) _____
 33) _____
 34) _____
 35) _____
 36) _____
 37) _____
 38) _____
 39) _____
 40) _____
 41) _____
 42) _____
 43) _____
 44) _____
 45) _____
 46) _____
 47) _____
 48) _____
 49) _____
 50) _____
 51) _____
 52) _____
 53) _____
 54) _____
 55) _____
 56) _____
 57) _____
 58) _____
 59) _____
 60) _____
 61) _____
 62) _____
 63) _____
 64) _____
 65) _____
 66) _____
 67) _____
 68) _____
 69) _____
 70) _____
 71) _____
 72) _____
 73) _____
 74) _____
 75) _____
 76) _____
 77) _____
 78) _____
 79) _____
 80) _____
 81) _____
 82) _____
 83) _____
 84) _____
 85) _____
 86) _____
 87) _____
 88) _____
 89) _____
 90) _____
 91) _____
 92) _____
 93) _____
 94) _____
 95) _____
 96) _____
 97) _____
 98) _____
 99) _____
 100) _____
 101) _____
 102) _____
 103) _____
 104) _____
 105) _____
 106) _____
 107) _____
 108) _____
 109) _____
 110) _____
 111) _____
 112) _____
 113) _____
 114) _____
 115) _____
 116) _____
 117) _____
 118) _____
 119) _____
 120) _____
 121) _____
 122) _____
 123) _____
 124) _____
 125) _____
 126) _____
 127) _____
 128) _____
 129) _____
 130) _____
 131) _____
 132) _____
 133) _____
 134) _____
 135) _____
 136) _____
 137) _____
 138) _____
 139) _____
 140) _____
 141) _____
 142) _____
 143) _____
 144) _____
 145) _____
 146) _____
 147) _____
 148) _____
 149) _____
 150) _____
 151) _____
 152) _____
 153) _____
 154) _____
 155) _____
 156) _____
 157) _____
 158) _____
 159) _____
 160) _____
 161) _____
 162) _____
 163) _____
 164) _____
 165) _____
 166) _____
 167) _____
 168) _____
 169) _____
 170) _____
 171) _____
 172) _____
 173) _____
 174) _____
 175) _____
 176) _____
 177) _____
 178) _____
 179) _____
 180) _____
 181) _____
 182) _____
 183) _____
 184) _____
 185) _____
 186) _____
 187) _____
 188) _____
 189) _____
 190) _____
 191) _____
 192) _____
 193) _____
 194) _____
 195) _____
 196) _____
 197) _____
 198) _____
 199) _____
 200) _____
 201) _____
 202) _____
 203) _____
 204) _____
 205) _____
 206) _____
 207) _____
 208) _____
 209) _____
 210) _____
 211) _____
 212) _____
 213) _____
 214) _____
 215) _____
 216) _____
 217) _____
 218) _____
 219) _____
 220) _____

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Monday, 11 February 2019 9:25 AM
To: assignments
Subject: FW: Accident involving veh no: SH 9615A & SJS 8317R on 05.02.19
Attachments: 07022019170602.pdf

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 11 February 2019 9:05 AM
To: Chunni Motor <chunnimotor@gmail.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Accident involving veh no: SH 9615A & SJS 8317R on 05.02.19

Without Prejudice

Dear Sir,

We will appoint LKK accordingly.

Dear LKK,

Pls pri.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Chunni Motor [<mailto:chunnimotor@gmail.com>]
Sent: Monday, 11 February, 2019 9:02 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: Accident involving veh no: SH 9615A & SJS 8317R on 05.02.19

Dear Sir,

We appoint Henry Ng.

Thank you

Regards,
Chunni Motor Work P/L

On Mon, Feb 11, 2019 at 8:59 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Chunni Motor [<mailto:chunnimotor@gmail.com>]

Sent: Monday, 11 February, 2019 8:43 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: Accident involving veh no: SH 9615A & SJS 8317R on 05.02.19

Dear Sir,

Refer to attached LTA search.

Please revert.

Thank you

Regards,

Chunni Motor Work P/L

On Mon, Feb 11, 2019 at 8:35 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sir,

Merimen shows this not our vehicle.

Pls confirm and provide relevant documents to proof so and submit in Merimen/Audatex (where necessary) as well.

Thank you.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Chunni Motor [mailto:chunnimotor@gmail.com]
Sent: Monday, 11 February, 2019 8:14 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Fwd: Accident involving veh no: SH 9615A & SJS 8317R on 05.02.19

----- Forwarded message -----

From: **Chunni Motor** <chunnimotor@gmail.com>
Date: Thu, Feb 7, 2019 at 5:15 PM
Subject: Accident involving veh no: SH 9615A & SJS 8317R on 05.02.19
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

MCD619018945 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 07/02/2019 15:25
 SUBMITTED BY: Janet Lim Slang Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/02/2019 15:25
Date Of Accident	05/02/2019 11:05
Exact Location Of Accident	PIE TOWARDS CHANGI AIRPORT AFTER STEVEN ROAD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH9615A
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	IONIQ HYBRID
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	YEO YIAO MING
NRIC No	S7629179I
Date Of Birth	17/09/1976
Occupation	OUTDOOR
Date Of Driving Pass	22/01/1997
Driving Experience	22 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93209615
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 967B JURONG WEST STREET 93
#13-853

Postcode 642967

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) Involved in the accident 3

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1
NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name BISHAN NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-5529999 - FAX NO: 65561905

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT NO: T/20190206/2014

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: -

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJS8317R

Vehicle Make/Model/Colour NISSAN

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver XU BO WEN

NRIC/Passport Number S9744278I

Contact Number 82991733
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage FRONT
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLU3831X
 Vehicle Make/Model/Colour BMW
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver CHAN CHOON SENG
 NRIC/Passport Number S6823135C
 Contact Number 96451008
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage REAR
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name YEO YIAO MING
 Approximate Age
 Injuries Sustain NECK AND BACK
 Injured person in which vehicle? SH9615A
 Were seat belts worn? YES
 Was this injured conveyed to hospital by ambulance? NO
 Address
 Postcode

DETAILS OF INJURED PERSON 2

Name NGUYEN THI DUYEN (PAX)
 Approximate Age
 Injuries Sustain NECK AND BACK
 Injured person in which vehicle? SH9615A
 Were seat belts worn?
 Was this injured conveyed to hospital by ambulance? NO
 Address
 Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


CHUNNI MOTOR WORKS PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 07.02.2019@1230HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June Tan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attachment: T/20190206/2014

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Hm

[Signature]

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time: 07.02.2019@1230HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June Tan



**SINGAPORE
POLICE FORCE**



T/20190206/2014

1 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20190206/2014

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/02/2019 10:11		Vide Report No.:		Station Diary No.: 22	
Name of Informant: YEO YIAO MING			Address: APT BLK 967B JURONG WEST STREET 93 #13-853 SINGAPORE 642967		
ID Type / ID No.: NRIC NO / S7629179I		Contact No.:		Mobile: 93209615	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 42	Date of Birth: 17/09/1976	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 2B,3,4		Date of Expiry:	

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 05/02/2019 11:05	Type of Location: Flyover
Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE towards Changi after Steven Road exit				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

SH9615A	Car	HYUNDAI	AE IONIQ HEV 1.6 DCT	Blue	Seriously Damaged	1
SJS8317R	Car	NISSAN	TEANA 2.5 CVT ABS D/AB HID 2WD 4DR	Silver		0
SLU3831X	Car	BMW	216I GT LED NAV			0



**SINGAPORE
POLICE FORCE**



T/20190206/2014

2 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20190206/2014

CONTINUATION OF REPORT

Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Name	NGUYEN THI DUYEN	ID No.	G3308456R
Related Vehicle	SH9615A (Car)	Contact No.	NIL
Hospital/Clinic	INTEMEDICAL 24HR CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	05/02/2019	Date Discharge	05/02/2019
No. of Days granted Medical Leave	05	Degree of Injury	NIL
Name	YEO YIAO MING	ID No.	S7629179I
Related Vehicle	SH9615A (Car)	Contact No.	93209615
Hospital/Clinic	INTEMEDICAL 24HR CLINIC	Class of Driving Licence & Expiry Date	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	05/02/2019	Date Discharge	05/02/2019
No. of Days granted Medical Leave	05	Degree of Injury	NIL
Name	XU BO WEN	ID No.	S9744278I
Related Vehicle	SJS8317R (Car)	Contact No.	82991733
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20190206/2014

3 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20190206/2014

CONTINUATION OF REPORT

Name	CHAN CHOON SENG		ID No.	S6823135C
Related Vehicle	SLU3831X (Car)		Contact No.	96451008
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

Brief Details.

On 05th February 2019 at 1105hrs, I was driving my vehicle registration number: SH9615A with my passenger (wife) along PIE towards Changi after Steven Road exit

I was driving at the extreme right lane. While I was driving, there was a vehicle registration number: SLU3831X (V3) was completing to a stop. I managed to apply brake and stopped. While I was in the stationary position, there was a strong impact from my rear vehicle.

I realised that there was another vehicle registration number: SJS8317R (V2) had collision to my vehicle. Due to the strong impact, my vehicle moved forward and hit V2's rear portion.

I alighted from my vehicle and realised that it was a chain collision. There were total of 3 vehicles involved. My wife and I suffered injuries due to impact. I managed to take all particulars.

I went to seek medical attention and was given 5 days MC.

I am lodging this report for insurance claimed.



**SINGAPORE
POLICE FORCE**



T/20190206/2014

4 of 4

Report No. T/20190206/2014

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
E/
Sr Staff Sgt MOHAMAD FARID BIN JAMAL

Signature Of Informant:
[Handwritten Signature]

Signature Of Interpreter:
Not applicable

Date/Time:
06/02/2019 10:11

Officer In Charge Of Case:
TP / AEIT /
Sr Staff Sgt MOHAMAD ZULFAZDLI BIN
ABDULLAH
Contact No.: 65476204



Classification Of Case:
SN 061

Authentication Stamp
NP188

URE

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9615A

DATE : 7.02.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

ChinaTaiping

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille <i>broken</i>			\$ 1,227.50	✓
	Speaker Assy- VESS <i>2 Dam</i>			\$ 154.40	✓
	Unit Assy-SMART CRU (Radar Sensor) <i>broken</i>			\$ 2,910.90	✓ photo
	Front Bumper Cover <i>Crack</i>			\$ 418.30	✓
	Front Bumper Sponge <i>torx</i>			\$ 86.90	✓
	Front Bumper Reinforcement <i>1st</i>			\$ 1,075.10	✓
	Front Bumper Bracket Top (LH/RH) <i>HW</i>	\$	35.00	\$ 70.00	X
	Front Bumper Bracket (LH/RH) <i>HW</i>	\$	28.00	\$ 56.00	X
	Front Bumper Clips 10 pcs <i>HW</i>			\$ 22.00	✓
	Headlamp Support Panel Assy <i>2 broken</i>			\$ 949.30	✓
	Headlamp (LH/RH) <i>mount 1 broken / wall</i>	\$	1,198.80	\$ 2,397.60	✓
	Radiator Inverter <i>2 1st</i>			\$ 884.80	✓
	Radiator Shroud <i>HW</i>			\$ 275.50	X
	Radiator Air Guard (LH/RH) <i>HW</i>	\$	26.40	\$ 52.80	X
	Radiator Air Guard, Upr (LH/RH) <i>HW</i>	\$	27.50	\$ 55.00	X
	Aircon Condenser <i>1st</i>			\$ 663.60	✓
	SUB TOTAL			\$ 11,299.70	
	LESS 20%			\$ 2,259.94	
	DISCOUNTED TOTAL			\$ 9,039.76	
	Front Number Plate <i>Crack</i>			\$ 25.00	Nett ✓
	Front No Plate Trim Cover <i>HW</i>			\$ 30.00	Nett X
				\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	500/-
	Spray Painting Charge			\$ 250.00	200/-
	Wiring Charge			\$ 50.00	30/-
	Towing Charge			\$ 5.00	HW
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	180/-
	TOTAL LABOUR			\$ 1,935.00	

10790.40

8632.32

25.00

990.00

SH 9615A

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>Dented</i>			\$ 2,480.40 ✓
	Boot Lid Rubber <i>h/c</i>			\$ 127.40 ✓
	Boot Lid Hinge (LH/RH) <i>WH</i>	\$	31.30	\$ 62.60 X
	Boot Lid Lock Upper <i>st</i>			\$ 224.00 ✓
	Boot Lid 'H' Emblem <i>h/c</i>			\$ 28.00 ✓
	Emblem -Hybrid <i>h/c</i>			\$ 24.30 ✓
	Emblem -Ioniq <i>h/c</i>			\$ 31.30 ✓
	Boot Lid Glass, Lower <i>h/c</i>			\$ 384.90 ✓ photo
	Boot Lid Lamp (LH/RH) <i>CRALC</i>	\$	794.40	\$ 1,588.80 ✓
	Boot Lid Trimboard <i>WH</i>			\$ 159.70 X
	Boot Lid Trimboard Clips (10pcs) <i>WH</i>			\$ 11.00 X
	Rear Bumper <i>CRALC</i>			\$ 459.40 ✓
	Rear Bumper Reinforcement <i>st</i>			\$ 294.80 ✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>st</i>	\$	138.10	\$ 276.20 ✓
	Rear Bumper Centre Moulding Assy <i>broken</i>			\$ 451.25 ✓
	Rear Bumper Lower Centre Moulding Assy <i>WH</i>			\$ 47.50 X
	Rear Bumper Stay <i>WH</i>			\$ 138.10 X
	Rear Bumper Side Bracket (LH/RH) <i>WH</i>	\$	33.10	\$ 66.20 X
	Rear Bumper Cover Clips <i>h/c</i>			\$ 22.00 ✓
	Rear Bumper Towing Cover <i>WH</i>			\$ 98.80 X
	Rear Bumper Reserve Light <i>WH socket broken</i>			\$ 257.10 ✓
	Tail Lamp (LH/RH) <i>CRALC</i>	\$	870.40	\$ 1,740.80 ✓
	Rear Panel <i>Dented</i>			\$ 532.00 ✓
	Rear Panel Garnish <i>mounting deformed</i>			\$ 155.00 ✓
	Rear Panel Lower Panel <i>Dented</i>	\$	39.40	\$ 78.80 ✓
	Spare Tyre Panel <i>Dented</i>			\$ 892.50 ✓
	Exhaust Pipe Insulator <i>WH</i>			\$ 35.00 X
	Exhaust Silencer <i>WH</i>			\$ 943.50 X
	Exhaust Pipe Hanger <i>WH</i>			\$ 29.20 X
	Rear Windscreen Glass <i>h/c</i>			\$ 607.20 ✓ photo
	Rear Windscreen Moulding <i>WH WH</i>			\$ 28.20 X
	Rear Wiring Assy <i>WH</i>			\$ 1,521.50 X
				\$ 10656.15
				\$ 8524.92
				\$ 261.70
				\$ 13,797.45
				\$ 2,759.49
				\$ 11,037.96
				\$ 30.00
				\$ 135.70
				\$ 50.00
				\$ 46.00
				\$ 261.70

SUB TOTAL
LESS 20%
DISCOUNTED TOTAL

Boot Lid Comfort Logo Sticker *h/c*
Rear Bumper Reverse Sensor *Dent*
Rear Bumper Rubber Mat *h/c*
Rear Windscreen Sealant *h/c*

Nett ✓
Nett ✓
Nett ✓
Nett ✓

SH 9615A

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,600.00 800/-
	Spray Painting Charge			\$ 1,000.00 600/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 100.00 40/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Exhaust Pipe			\$ 150.00 60/-
			1730.00	
	TOTAL LABOUR			\$ 3,290.00
	ESTIMATE TOTAL			\$ 25,619.42
	<p>11/02/2019 @ 1000am LKA Antmal 21stmal 12 days ryan LKK Auto</p>		<p>20163.94 694.00 ----- 20857.94 4516650/-</p>	
	<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company <p>Acknowledged by Repairer: Signature: Date:</p> </div>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9615A (Supplementary)


DATE : 12.02.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper Under Centre Cover dislodged			\$ 225.00
	SUB TOTAL			\$ 225.00
	LESS 20%			\$ 45.00
	DISCOUNTED TOTAL			\$ 180.00
				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

Shamee

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9615A (Supplementary)

DATE : 11.02.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Day Light, RH <i>monety brskw</i>			S 642.50 ✓
	SUB TOTAL			S 642.50
	LESS 20%			S 128.50
	DISCOUNTED TOTAL			S 514.00 (circled)
	<p><i>11/02/2019</i></p> <p><i>2</i></p> <p><i>Shamee</i></p> <p><i>DKK Auto</i></p> <p><i>[Signature]</i></p>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119002396/DSD3Q2

Date: 01/04/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:		
Claimant Vehicle No :	SH9615A	Insured Vehicle No :	SJS8317R	
Date of Loss:	05/02/2019	Nature of Claim:	TP	Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH9615A	Engine No:	G4LEJU046137	
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVJU103434	
Reg. Date:	05/07/2018 (Man. Year: 2018)	Odometer:	99792 km	
Colour:	Blue			
Engine Capacity:	1580 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15	
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm	
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	21,088.42	18,137.94	2,950.48	13.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,225.00	2,720.00	2,505.00	47.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,313.42	20,857.94	5,455.48	20.73
Approved Total (Overridden) (S\$)		16,650.00		
(S\$)	26,313.42	16,650.00	9,663.42	36.72
+ GST 7.00/7.00% (S\$)	1,841.94	1,165.50	676.44	36.72
Nett Amount (S\$)	28,155.36	17,815.50	10,339.86	36.72

INSPECTION

Date of Assignment:	20/03/2019	
Date Inspected:	11/02/2019	Inspected At:
		CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047
Estimated Period of Repair:	12.0 days	

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 29 Mar 2019)
Parts:	N/A HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH9615A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Broken	1,227.50 FL	*1,227.50 FL
2	1		*SPEAKER ASSY -VESS	Damaged	154.40 FL	*154.40 FL
3	1		*UNIT ASSY -SMART CRU (RADAR SENSOR)	Broken	2,910.90 FL	*2,910.90 FL
4	1		*FRONT BUMPER COVER	Cracked	418.30 FL	*418.30 FL
5	1		*FRONT BUMPER SPONGE	Torn	86.90 FL	*86.90 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	1,075.10 FL	*1,075.10 FL
7	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	70.00 FL	*- FL
8	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	56.00 FL	*- FL
9	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
10	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	949.30 FL	*949.30 FL
11	2		*HEADLAMP (LH/RH)	Mtg Broken / Cracked	2,397.60 FL	*2,397.60 FL
12	1		*RADIATOR INVERTER	Bent	884.80 FL	*884.80 FL
13	1		*RADIATOR SHROUD	Not Necessary	275.50 FL	*- FL
14	2		*RADIATOR AIR GUARD (LH/RH)	Not Necessary	52.80 FL	*- FL
15	2		*RADIATOR AIR GUARD ,UPR (LH/RH)	Not Necessary	55.00 FL	*- FL
16	1		*AIRCON CONDENSER	Bent	663.60 FL	*663.60 FL
17	1		*FRONT NUMBER PLATE	Cracked	25.00 FS	*25.00 FS
18	1		*FRONT NO PLATE TRIM COVER	Not Necessary	30.00 FS	*- FS
19	1		*BOOT LID	Dented	2,480.40 FL	*2,480.40 FL
20	1		*BOOT LID RUBBER	Necessary	127.40 FL	*127.40 FL
21	2		*BOOT LID HINGE (LH/RH)	Not Necessary	62.60 FL	*- FL
22	1		*BOOT LID LOCK UPPER	Bent	224.00 FL	*224.00 FL
23	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
24	1		*EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
25	1		*EMBLEM -IONIQ	Necessary	31.30 FL	*31.30 FL
26	1		*BOOT LID GLASS ,LOWER	Necessary	384.90 FL	*384.90 FL
27	2		*BOOT LID LAMP (LH/RH)	Cracked	1,588.80 FL	*1,588.80 FL
28	1		*BOOT LID TRIMBOARD	Not Necessary	159.70 FL	*- FL
29	11		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
30	1		*REAR BUMPER	Cracked	459.40 FL	*459.40 FL
31	1		*REAR BUMPER REINFORCEMENT	Bent	294.80 FL	*294.80 FL
32	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Bent	276.20 FL	*276.20 FL
33	1		*REAR BUMPER CENTRE MOULDING ASSY	Broken	451.25 FL	*451.25 FL
34	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Not Necessary	47.50 FL	*- FL
35	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
36	2		*REAR BUMPER SIDE BRACKET (LH/RH)	Not Necessary	66.20 FL	*- FL
37	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
38	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
39	1		*REAR BUMPER REVERSE LIGHT	Socket Broken	257.10 FL	*257.10 FL
40	2		*TAIL LAMP (LH/RH)	Cracked	1,740.80 FL	*1,740.80 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
42	1		*REAR PANEL GARNISH	Mtg Deformed	155.00 FL	*155.00 FL
43	2		*REAR PANEL LOWER PANEL	Dented	78.80 FL	*78.80 FL
44	1		*SPARE TYRE PANEL	Dented	892.50 FL	*892.50 FL
45	1		*EXHAUST PIPE INSULATOR	Not Necessary	35.00 FL	*- FL
46	1		*EXHAUST SILENCER	Not Necessary	943.50 FL	*- FL
47	1		*EXHAUST PIPE HANGER	Not Necessary	29.20 FL	*- FL
48	1		*REAR WINDSCREEN GLASS	Necessary	607.20 FL	*607.20 FL
49	1		*REAR WINDSCREEN MOULDING	Not Necessary	28.20 FL	*- FL
50	1		*REAR WIRING ASSY	Not Necessary	1,521.50 FL	*- FL
51	1		*BOOT LID COMFORT LOGO STICKER	Necessary	30.00 FS	*30.00 FS
52	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
53	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
54	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
55	1		*REAR BUMPER UNDER CENTRE COVER	Dislodged	225.00 FL	*225.00 FL
56	1		*DAY LIGHT ,RH	Mtg Broken	642.50 FL	*642.50 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,281.35	22,600.75
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,192.93	4,462.81
Total Parts (\$\$)	21,088.42	18,137.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,600.00	1,300.00
2	SPRAY PAINTING CHARGE	New	1,250.00	800.00
3	WIRING CHARGE	New	100.00	60.00
4	TOWING CHARGE	New	5.00	0.00
5	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
6	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	180.00
7	TUFF KOTE	New	100.00	40.00
8	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
9	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
10	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
11	REMOVE/REFIX EXHAUST PIPE	New	150.00	60.00
Gross Labour Cost (\$\$)			5,225.00	2,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >