

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9615A (Supplementary)

DATE : 12.02.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper Under Centre Cover <i>dislodged</i>			\$ 225.00
	SUB TOTAL			\$ 225.00
	LESS 20%			\$ 45.00
	DISCOUNTED TOTAL			\$ 180.00
<p><i>[Handwritten Signature]</i></p> <p><i>[Handwritten Signature]</i></p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

Handwritten signature

VEHICLE NO : SH 9615A (Supplementary)

DATE : 11.02.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI IONIQ

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Day Light, RH <i>monety broke</i>			\$ 642.50 ✓
	SUB TOTAL			\$ 642.50
	LESS 20%			\$ 128.50
	DISCOUNTED TOTAL			\$ 514.00 (circled)
	<p><i>11/02/2019</i></p> <p><i>[Signature]</i></p> <p><i>DKK Auto</i></p> <p><i>[Signature]</i></p>			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.