

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0170/2019/GW
Date : 09-Feb-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SKR 9815 G

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Jessie Lim
Address : 161 Killiney Rd
Singapore 239569
Telephone : HP +65 96238264
Type of Claim : Third Party Claims
Policy No. : MT/00577031
Vehicle No : **SKT 47 E**
Model Code : A8 D4 3.0 TFSI QU
Model / Year : Jan-11
Engine No : CGW 002850
Chassis No : WAUZZZ4H7BN008102
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 03-Feb-19
Place of Accident : Lincoln Rd Outside United Square

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKT 47 E

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$280.00 ✓	
2	To dismantle and renew rear bumper. Repair and reshape rhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,400.00 1000	
3	To respray rear bumper, lower spoiler and rhs rear fender.	\$ 2,500.00 1100	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$5,372.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 47 E

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>VB</i>	\$ 3,342.00	
2	REAR BUMPER TRIM STRIPS <i>X</i>	\$ 828.00	
3	REAR BUMPER SPOILER <i>X</i>	\$ 614.00	
4	REAR BUMPER GUIDE SECTION-RH OUTER <i>?</i>	\$ 28.00	
5	REAR BUMPER GUIDE SECTION-RH UPPER <i>?</i>	\$ 20.00	
6	SUNDRIES <i>?</i>	\$ 300.00	
TOTAL SPARE PARTS CHARGES		:	\$ 5,132.00
TOTAL LABOUR CHARGES		\$	5,372.00
GRAND TOTAL		\$	10,504.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Jaseu - Hp 90010068

Surveyed Date

: 11/02/19 @ 1000hrs

Authorised Date

:

Excess Cost

:

5 days

Liability

:

Remarks

:

Reg 64 part

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant