

BMW Dealer

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

*4/3/2019*  
*Sunny & repair*  
*mering*



GST REG. NO : M2 - 0020081 - X

08 FEB 2019

## E S T I M A T E

Estimate No. : b1 50008	Page No. : 1 of 5
Date Estimated : 07/02/2019	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Lee Wai Kin Kelly 4 Primrose Avenue  Singapore 467238	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFP9129Z	5E91557	22/12/2017	216i GT	0

DESCRIPTION	VALUE
Replace rear boot lid, rear bumper and remove attachment e tc	1770 2,550.00
Spray painting rear boot lid and rear bumper	1730 1,923.00
To replace rear windscreen glass.	488 574.00
To conduct water leak tests.	63 75.00
To supply and install rear windscreen solar film.	451 531.00
To carry out body cavity preservation. (Per panel).	100 118.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	? 150.00
Total Labour 1: <b>6,098.00</b>	

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID	1	1,204.35	bt 1,204.35
LH TRUNK LID HINGE	1	79.35	ky 79.35
RH TRUNK LID HINGE	1	79.35	ky 79.35
REAR BUMPER CARRIER SUPPORT	1	458.10	? 458.10
RR BUMPER LH INNER SIDE GUIDE	1	45.30	? 45.30
RR BUMPER RH INNER SIDE GUIDE	1	67.55	? 67.55
LEFT PROTECT	1	67.55	? 67.55
RIGHT PROTEC	1	2.10	? 2.10
REAR BUMPER PANEL PRIMED (PDC)	1	2.10	? 2.10
SET MOUNTS PDC SENSOR REAR	1	1,029.50	de 1,029.50
REAR BUMPER TOWING FLAP EYE PRIMED	1	60.35	ney 60.35
GROMMET	1	42.85	mt 42.85
	2	0.75	we 1.50

