

INS. CASE OWNER:

CC 3 / III 1900

LKK
IDAC

Surveyor:

Paul.

DOI:

ASSIGNMENT

22/3/19

Date / Time:

11/3/19

Registered in Merimen:

11/3/19

Pre-assign / CCU / FTE



Insured Vehicle No. : SH 9615A

Name of Insured : LTPU

Insured Tel No. : HP:

Excess Sec II : \$ D.O.A. : 5/3/19

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : YEO YIN MING

Driver Tel No. : (V/L: YES / NO)

Claim No. : MUTIA 1W104

Policy No. : M1W1045

Make / Model : HYUNDAI

Place of Accident : PIE TWS LAMPAI

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SJS 831XK → SH 9615A →

SLN 3831X →

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS: 01INSRS:
WSP: performance
Tel:
Liability:
RMKS: TPINSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SLN 3831X - X
SH 9615A = 15/03/2019 (05/03/19)

22/3/19 - File pass R7 type report.
 22/3/19 - Pending mandate approval (approved)
 24/3/19 - Offer \$5453.74 as per TP W/L, by
 send pending by in.
 20/4 - by in (file pass Admin to close).

STAGE DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

I.T.A / C.H.A.:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Paul.

Repair Cost: P/P \$5453.74 (4 days) Reduction: 5259.45 % 52

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28

If NO or B 28, Ass. Lia: 0

Repair Cost: (W/L) \$5453.74

Loss of Rental (LOR): \$5 - (days)

Loss of Use (LOU): \$240.00 (560 x 4 days)

Loss of Income (LOI): \$5 - (3 x days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LO ☐ [Tick only one]

GIA/LTA Search \$5 -

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost \$5 -

Total: \$5453.74

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1: \$5453.74

Name 1:

Performance Motors Limited

Payee 2: (Strike if N.A.) \$5

Name 2:

Payee 3: (Strike if N.A.) \$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP

\$500/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III19002412/jb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 11-02-2019		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9615A	Veh. Inspected	SLU 3831X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/02/2019	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/02/2019	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 12742159W GST Reg. No. M2-0020081-X361, Alexandra Road
Sime Darby Performance Centre
Singapore 159941Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747772280, Kangkong Arang Road
East Coast Centre
Singapore 438180Tel. 63190088 (AfterSales)
Fax. 63448773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796621 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

08 FEB 2019

Estimate No. : b1 50025
Date Estimated : 07/02/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chan Choon Seng
Blk 3 Jurong Lake Link
#01-13

Singapore 648161

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3831X	5E91501	30/11/2017	216i G TOURER	0

DESCRIPTION

Replacing rear bumper panel and attachments, bootlid, etc
to knock out dents caused by the accident

VALUE

1700 2,580.00

Spray rear bumper, bootlid

1730 1,923.00

To replace rear windscreen glass.

X 574.00

To supply and install rear windscreen solar film.

X 531.00

To conduct water leak tests.

X 75.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 171.00

To carry out body cavity preservation.
(Per panel).

X 118.00

Sundries

80 ? 150.00

Total Labour 1: 6,098.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID repair ?	1	1,204.35	1,204.35
RR BUMPER LH SIDE GUIDE	1	61.50	61.50
RR BUMPER LH SIDE GUIDE	1	61.50	61.50
REAR BUMPER CARRIER ?	1	458.10	458.10
REAR BUMPER TRIM STRIP (CHROM) cat	1	107.75	107.75
REAR BUMPER PANEL PRIMED (LINES PDC DE	1	1,029.50	1,029.50
GROMMET	2	0.75	1.50
PLAQUE 74MM	1	71.25	71.25
REAR WINDOW	1	654.35	654.35
BOOTLID SEALING	1	143.00	143.00
DECOUPING RING PDC TORQUE CONVERTER ?	4	5.05	20.20
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10

10230-10

Performance Motors Limited

A member of the Lion Derby Group
Co. Reg. No. 197421559W GST Reg. No M2-0020081-X



309, Alexandra Road
Lion Derby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190211 (AfterSales)
Fax: 64747773

188, Raffles Avenue Road
East Coast Centre
Singapore 438185
Tel: 63190888 (AfterSales)
Fax: 63443773

315, Alexandra Road
Lion Derby Business Centre
Singapore 159944
Tel: 63190229 (AfterSales)
63190521/333 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 50025
Date Estimated : 07/02/2019
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3831X	5E91501	30/11/2017	2161 G TOURER	0

DESCRIPTION	QTY	PRIC	VALUE
(DG/SL) GLASS PRIMER 30ML (VP206) X	1	27.85	27.85
Total Parts :			4,130.10

Claims OD / 2nd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/03/19 @ 1130 Excess S\$ _____

Surveyor's Name Ram Sign _____

Surveyor's Tel 90012068 Authorized Yes / No _____

Authorized Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No Yes / No

Surveyor's E-mail _____

No. of Working Days Recommended 4-5 days

LION Auto Consultants hereby certify the Repairer of the following:

- To reserve parts after survey pending
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



Labour 1	1	6,098.00
Parts	1	4,130.10
Labour 2	1	0.00
Excess	1	0.00
Total GST @ 7%	1	715.97
Grand Total	1	10,944.07

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-8



SUPPLEMENTARY

Estimate No. : b1 50025
Date Estimated : 07/02/2019
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -
Chan Choon Seng
Blk 3 Jurong Lake Link
#01-13

- ACCOUNT - 219
India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 648161

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3831X	5E91501	30/11/2017	216i G TOURER	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# EXPANDING NUT • <i>nu</i> ✓	1.00	2.00		2.00
-------------------------------	------	------	--	------

Total Labour :	
Total Parts :	2.00
Total Labour & Parts :	2.00



Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401509W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No : b1 50025
Date Estimated : 07/02/2019
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -

Chan Choon Seng
Blk 3 Jurong Lake Link
#01-13

Singapore 648161

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3831X	5E91501	30/11/2017	216i G TOURER	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include making good the boot lid and knocking out dents caused by the accident	1700.00		1,700.00	
To spray paint rear bumper and boot lid	1730.00		1,730.00	
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00	
Sundries	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	1.00	2.00		2.00
REAR BUMPER TRIM STRIP (CHROM)	108.40	1.00		108.40
REAR BUMPER PANEL PRIMED (LINES PDC	1,029.50	1.00		1,029.50
GROMMET	0.75	2.00		1.50
PLAQUE 74MM	71.25	1.00		71.25

SUPPLEMENTARY ITEMS

Total Labour :	3,660.00
Total Parts :	1,212.65
Total Labour & Parts :	4,872.65
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,872.65
GST @7%:	341.09
Grand Total :	5,213.74

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401555W GST Reg. No. M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747778

288, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190884 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/510 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

08 FEB 2019

Estimate No. : b1 50025
Date Estimated : 07/02/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chan Choon Seng
Blk 3 Jurong Lake Link
#01-13

Singapore 648161

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3831X	E91501	30/11/2017	216i G TOURER	0

DESCRIPTION

Replacing rear bumper panel and attachments, bootlid, etc
to knock out dents caused by the accident

VALUE

1700 ~~2,580.00~~

Spray rear bumper, bootlid

1730 ~~1,923.00~~

To replace rear windscreen glass.

X 574.00

To supply and install rear windscreen solar film.

X 531.00

To conduct water leak tests.

X 75.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 ~~171.00~~

To carry out body cavity preservation.
(Per panel).

X 118.00

Sundries

? 150.00

Total Labour 1:

6,098.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID repair ?	1	1,204.35	1,204.35
RR BUMPER LH SIDE GUIDE ?	1	61.50	61.50
RR BUMPER LH SIDE GUIDE ?	1	61.50	61.50
REAR BUMPER CARRIER ?	1	458.10	458.10
REAR BUMPER TRIM STRIP (CHROM) CA	1	107.75	107.75
REAR BUMPER PANEL PRIMED (LINES PDC DE	1	1,029.50	1,029.50
GROMMET RE	2	0.75	1.50
PLAQUE 74MM RE	1	71.25	71.25
REAR WINDOW X	1	654.35	654.35
BOOTLID SEALING X	1	143.00	143.00
DECOUPING RING PDC TORQUE CONVERTER ?	4	5.05	20.20
(DG) CLEANER R1 (100ML) X	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) X	2	131.55	263.10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 187401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

288, Kampong Arang Road
East Coast Centre
Singapore 438189
Tel. 63190888 (AfterSales)
Fax. 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/536 (Motorrad)
Fax. 64798601 (AfterSales)
64798624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50025
Date Estimated : 07/02/2019
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3831X	5E91501	30/11/2017	216i G TOURER	0

DESCRIPTION

(DG/SL) GLASS PRIMER 30ML (VP206) X

QTY	PRIC	VALUE
1	27.85	27.85

Total Parts : 4,130.10

Claims CD / End Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/03/19 @ 1130 Excess \$ _____

Surveyor's Name Rafael Sign _____

Surveyor's Tel 90010068 Authorized Yes / No _____

Authorized Date _____ Time _____

NECESSARY MAINTS PHOTO BY SURVEYOR Yes / No _____

Surveyor's Email _____

No. of Working Days Recommended 4-5 days

LKK Auto Consultants, Inc. hereby
the Repairer of the following:

- To resolve car body body painting
- To display damaged part(s) during repairs
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



Labour 1	:	6,098.00
Parts	:	4,130.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	715.97
Grand Total	:	10,944.07

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

08 FEB 2019

Estimate No. : b1 50025
Date Estimated : 07/02/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chan Choon Seng
Blk 3 Jurong Lake Link
#01-13

Singapore 648161

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3831X	5E91501	30/11/2017	2161 G TOURER	0

DESCRIPTION

Replacing rear bumper panel and attachments, bootlid, etc
to knock out dents caused by the accident

VALUE

1700 ~~2,580.00~~

Spray rear bumper, bootlid

1730 ~~1,923.00~~

To replace rear windscreen glass.

X 574.00

To supply and install rear windscreen solar film.

X 531.00

To conduct water leak tests.

X 75.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 ~~171.00~~

To carry out body cavity preservation.
(Per panel).

X 118.00

Sundries

? 150.00

Total Labour 1:

6,098.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID repair ?	1	1,204.35	1,204.35
RR BUMPER LH SIDE GUIDE	1	61.50	61.50
RR BUMPER LH SIDE GUIDE ?	1	61.50	61.50
REAR BUMPER CARRIER ?	1	458.10	458.10
REAR BUMPER TRIM STRIP (CHROM) CEA	1	107.75	107.75
REAR BUMPER PANEL PRIMED (LINES PDC DE	1	1,029.50	1,029.50
GROMMET RA	2	0.75	1.50
PLAQUE 74MM	1	71.25	71.25
REAR WINDOW X	1	654.35	654.35
BOOTLID SEALING X	1	143.00	143.00
DECOUPING RING PDC TORQUE CONVERTER ?	4	5.05	20.20
(DG) CLEANER R1 (100ML) X	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) X	2	131.55	263.10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

383, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190889 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/538 (Motorrad)
Fax. 64786601 (AfterSales)
64786624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50025
Date Estimated : 07/02/2019
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3831X	5E91501	30/11/2017	2161 G TOURER	0

DESCRIPTION	QTY	PRIC	VALUE
(DG/SL) GLASS PRIMER 30ML (VP206) X	1	27.85	27.85
Total Parts :			4,130.10

Claims OD / 2nd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time <u>22/07/19 @ 1130</u>	Excess S\$ _____
Surveyor's Name <u>Rafael</u>	Sign _____
Surveyor's Tel <u>90010068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No <u>PML</u> Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>4-5 days</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Labour 1	:	6,098.00
Parts	:	4,130.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	715.97
Grand Total	:	10,944.07

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No	SD17V13360 /NPC2 /R00
Form	MX1
Date of Issue	06-DEC-2017
1.Index Mark and Registration No. of Vehicle:	SLU3831X
2.Chassis number of Vehicle:	WBA2D920605E91501
3.Name of Policyholder:	CHAN CHOON SENG
4.Effective date of Commencement of Insurance for the purposes of the Act:	30-NOV-2017 00:00 AM
5.Date of Expiry of Insurance:	29-NOV-2019 23:59 PM
6.Persons or Classes of Persons entitled to drive*:	
A) The Policyholder.	
B) Any other person who is driving on the Policyholder's order or with his permission.	
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.	
7.Limitations as to use*:	
Use only for social, domestic and pleasure purposes and for the Policyholder's business.	
8.The Policy does not cover:	
A) Use for hire or reward.	
B) Use for racing, pace-making, reliability trials or speed-testing.	
C) Use for the carriage of goods (other than samples) in connection with any trade or business.	
D) Use for any purpose in connection with the Motor Trade.	
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.	
I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).	
For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers  _____ Authorised Signature	
For Information only:	
COVERAGE :	Comprehensive, Unlimited Windscreen, NCD Protection
SUM INSURED:	MARKET VALUE AT THE TIME OF LOSS
EXCESS:	Section I S\$300, Additional Excess For Young & Inexperienced Drivers S\$2500, Windscreen Excess S\$0
FINANCE COMPANY:	DBS BANK LTD
PRODUCER NAME:	SD CONTEGO SERVICES

PLGG/PLGG/08-DEC-17

S1_CI_T1_T3_OE_Template2-Ver1.

08-DEC-17

REPUBLIC OF SINGAPORE DRIVING LICENCE


 Licence Member **S6823135C**
 Name **CHAN CHOON SENG**
 Birth Date **24 Jun 1968**
 Issue Date **22 Sep 2003**

0008699530



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S6823135C**


CHAN CHOON SENG
 陳俊成
 CHINESE
 Date of Birth **24-06-1968** Sex **M**
 Country of Birth **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	12 Aug 1993
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	30 Jun 1988

NP 428A

Licence No: S6823135C



000361


 NRIC No: **S6823135C**


 Blood Group **O+** Date of issue **30-05-1993**

APT BLK 3 JURONG LAKE LINK #01-13
SINGAPORE 848161
 NRIC No: S6823135C Date: 08/10/2017

Cecilia

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III- Direct Settlement (PODS)

India Ref: MCT19020104
Claimant Ref: SLU 3831X

We/I, PERFORMANCE MOTORS LIMITED ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANT PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 5,213.74 (repair cost), S\$ 240.00 (loss of use/rental), S\$ - (search fee), vehicle no. SLU 3831X that was damaged pursuant to the accident which occurred on 05/02/2019 (date) at PIE (location) involving vehicle no. SH 9615A (insured vehicle). This is pursuant to the inspection conducted on 22/03/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHAN CHOON SENG ("the third party claimant") of vehicle no. SLU 3831X to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLU 3831X (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 5,453.74 to PERFORMANCE MOTORS LIMITED

Dated this 10 day of September 2019

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Performance Motors Limited
303 Alexandra Road
Sine Darby Performance Centre
Singapore 159941

Nationality:

Occupation:

WITNESS:

Signature:

MRB

Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANT PTE LTD

NRIC:

199607198R

Address:

51 UBI AVE 1 #02-25

PAYA UBI INDUSTRIAL PARK S(408933)

Nationality:

Occupation:

Print Received Message

This mail is associated with :

***SLU3831X (MCT19020104)**
[SH9615A]

TP
CHAN CHOON SENG
Feb 5 2019 11:00AM
[COMFORT TRANSPORTATION PTE LTD]
Performance Motors Limited

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 05/08/2019 15:27 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5453.74) - SLU3831X - Claim Handler: Priya

Approved:5453.74:Please request TP WS to raise Tax Invoice for Cost of repairs in III's name



Joy

India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
Attention: Motor Claims

"Without Prejudice"

Your Ref:

Our Ref:

Date:

Subject:

11 June 2019

ACCIDENT INVOLVING VEHICLES SLU3831X & SH9615A ON 05.02.2019

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$ 5213.74
Loss of use	:	S\$ 240.00 (S\$60.00 x 4 days)
Total	:	S\$ 5453.74

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill
3. Copy of Certificate of Insurance
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Performance Motors
Limited
1800-Call-BMW
(1800-2255-269)
www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel Aftersales:
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel Aftersales:
6319 0527
Fax 6479 6624

280
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel Aftersales:
6319 0698
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401559W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Cresendo Lagman
Customer Service Manager, Body & Paint

Performance Motors Limited

A member of the Sims Derby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SLU3831X & SH9615A ON 5/2/19.

I, Chan Choon Seng owner of Vehicle Registration No. SLU3831X hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:


Name: Chan Choon Seng (Date) 7 Feb 2019
NRIC No.: S6823135C

In the presence of:


Name: _____ (Date) _____
NRIC No.: _____

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: **MCT19020104**
Claimant Ref: **SLU 3831X**

We/I, Performance Motors Limited ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$5213.74 (repair cost), S\$240.00 (loss of use/rental), S\$ - (search fee), vehicle no. SLU3831X that was damaged pursuant to the accident which occurred on 5/2/19 (date) at PIE (Towards Changi Airport) (location) involving vehicle no. S19615P (insured vehicle). This is pursuant to the inspection conducted on 22/3/19 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Chen Chuan Song ("the third party claimant") of vehicle no. SLU3831X to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLU3831X (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 5,453.74 to Performance Motors Limited

Dated this 10 day of September 20 19

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

PERFORMANCE MOTORS LIMITED
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
TEL: 63190100 (Sales)
63190111 (AfterSales)

WITNESS:

Signature:



MRB

Signed by appointed Surveyor

Name:

NRIC:

Address:

Nationality:

Occupation:

LKK Auto Consultants Pte Ltd

199609198R

51 Ubi Ave 1 #02-25

Paya Ubi Industrial Park S(408933)

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190088 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/536 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1347443

Date IN : 22/03/2019

Motor Claim Advisor: Joseph Yaguel

Page No. : 1 of 2

Invoice Number : 2107053 / WSB

Invoice Date : 06/06/2019

Payment Terms : 30 Days From Invoice

Invoice By : Toh Jing Xuan

- CUSTOMER INFORMATION -

Mr Chan Choon Seng
Blk 3 Jurong Lake Link
#01-13

Singapore 648161

- INVOICE TO - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3831X	5E91501	30/11/2017	216I G TOURER	27365

- - - - LABOUR 1 - - - -

To replace rear bumper and attachments including make good the bootlid and knock out dented area caused by the accident.

To respray rear bumper and bootlid.

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 05.02.2019. 3RD PARTY CAR : SH9615A.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO ON 22.03.2019 AT 11:30AM. AUTHORISED REPAIR BY MS JOY IRENE FROM LKK AUTO ON 15.02.2019 VIA EMAIL.

PROPOSE LOSS OF USE = \$60x4. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.

NETT

1,700.00

1,730.00

150.00

80.00

0.00

0.00

Total Labour 1: 3,660.00

- - - - PARTS - - - -

REAR BUMPER TRIM STRIP (CHROM)

REAR BUMPER PANEL PRIMED (LINES PDC

PLAQUE 74MM

GROMMET

EXPANDING NUT

Qty	Retail Price	NETT
1	108.40	108.40
1	1,029.50	1,029.50
1	71.25	71.25
2	0.75	1.50
2	1.00	2.00

Total Parts : 1,212.65

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159943
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : **B1 1347443**

Date IN : **22/03/2019**

Motor Claim Advisor: **Joseph Yaguel**

Page No. : **2 of 2**

Invoice Number : **2107053 / WSB**

Invoice Date : **06/06/2019**

Payment Terms : **30 Days From Invoice**

Invoice By : **Toh Jing Xuan**

Labour Charges :	3,580.00	Total Labour & Parts Charges :	S\$ 4,872.65
Parts Charges :	1,212.65	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	80.00	Invoice Total Amount Exclude GST :	S\$ 4,872.65
		GST @ 7% :	S\$ 341.09
		Invoice Total Amount Include GST :	S\$ 5,213.74

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 5,213.74**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Feb 2019 Edit Reg		22 Mar 2019 00:00 Edit Adj Rpt	S\$4,872.65 Edit Estimates	S\$4,872.65 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -								
Main Claimant:	CHAN CHOON SENG, ID: S6823135C								
Vehicle Reg. No.:	SLU3831X	Date of Loss:	05/02/2019 11:00 - :59 [14 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19020104	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SH9615A	Policy No. (Claimant):	SD17V13360/VPC2/ROO						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 20/02/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (05/08/2019): Alert - Adj Mandate Approved (S\$5453.74) - SLU3831X - Claim Handler: Priya - III_SG (14/02/2019): Alert - Adj Mandate Approved (S\$0.00) - SLU3831X - Claim Handler: Priya									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLU3831X (MCT19020104)
[SH9615A]
TP
CHAN CHOON SENG
Feb 5 2019 11:00AM
[COMFORT TRANSPORTATION PTE LTD]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/08/19 11:56	General View	 Load JPG	☒
2	05/08/19 11:56	General View	 Load JPG	☒
3	05/08/19 11:56	General View	 Load JPG	☒
4	05/08/19 11:56	General View	 Load JPG	☒
5	05/08/19 11:56	General View	 Load JPG	☒
6	05/08/19 11:56	General View	 Load JPG	☒
7	05/08/19 11:56	General View	 Load JPG	☒
8	05/08/19 11:56	General View	 Load JPG	☒
9	05/08/19 11:56	General View	 Load JPG	☒
10	05/08/19 11:56	General View	 Load JPG	☒
11	05/08/19 11:56	General View	 Load JPG	☒
12	05/08/19 11:56	General View	 Load JPG	☒
13	05/08/19 11:56	General View	 Load JPG	☒
14	05/08/19 11:56	General View	 Load JPG	☒
15	05/08/19 11:56	General View	 Load JPG	☒
16	05/08/19 11:56	General View	 Load JPG	☒
17	05/08/19 11:56	General View	 Load JPG	☒
18	05/08/19 11:56	General View	 Load JPG	☒
19	05/08/19 11:56	General View	 Load JPG	☒
20	05/08/19 11:56	General View	 Load JPG	☒
21	05/08/19 11:56	General View	 Load JPG	☒
22	05/08/19 11:56	General View	 Load JPG	☒
23	05/08/19 11:56	General View	 Load JPG	☒
24	05/08/19 11:56	General View	 Load JPG	☒
25	05/08/19 11:56	General View	 Load JPG	☒
26	05/08/19 11:56	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/02/19 17:42	TP ESTIMATE	 Load PDF	
2	11/02/19 17:42	TP GIA REPORT	 Load PDF	
3	25/03/19 17:47	TP ESTIMATE- MARKED	 Load PDF	
4	02/08/19 09:20	WORKSHOP INVOICE	 Load PDF	
5	02/08/19 09:20	LOD	 Load PDF	
6	24/09/19 15:29	DISCHARGE VOUCHER	 Load PDF	
7	24/09/19 15:29	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	12/02/19 08:46	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19002412/R1GB3Q2

Date: 24/09/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant SLU3831X Insured Vehicle No: SH9615A
 Vehicle No: SLU3831X
 Date of Loss: 05/02/2019 Nature of Claim: TP Claim No: MCT19020104

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU3831X
 Make & Model: BMW 216I, 1.5 (A) Engine No: 36025092B38A15A
 Reg. Date: 30/11/2017 (Man. Year: 2017) Chassis No: WBA2D920605E91501
 Colour: Grey Odometer: 27365 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,282.75	1,292.65	2,990.10	69.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,948.00	3,580.00	2,368.00	39.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,230.75	4,872.65	5,358.10	52.37
+ GST 7.00/7.00% (S\$)	716.15	341.09	375.06	52.37
Nett Amount (S\$)	10,946.90	5,213.74	5,733.16	52.37
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
	Nett Liability (S\$)	5,453.74		

INSPECTION

Date of Assignment: 22/03/2019

Date Inspected: 22/03/2019 Inspected At:

Performance Motors Limited
 (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Aug 2019)

Parts: M1-MPV BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLU3831X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	1,204.35 FS	*- FS
2	1		*RR BUMPER LH SIDE GUIDE	Serviceable	61.50 FS	*- FS
3	1		*RR BUMPER LH SIDE GUIDE	Serviceable	61.50 FS	*- FS
4	1		*REAR BUMPER CARRIER	Serviceable	458.10 FS	*- FS
5	1		*REAR BUMPER TRIM STRIP (CHROM)	Cracked	108.40 FS	*108.40 FS
6	1		*REAR BUMPER PANEL PRIMED (LINES PDC	Deformed	1,029.50 FS	*1,029.50 FS
7	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
8	1		*PLAQUE 74MM	Necessary	71.25 FS	*71.25 FS
9	1		*REAR WINDOW	Not Necessary	654.35 FS	*- FS
10	1		*BOOTLID SEALING	Not Necessary	143.00 FS	*- FS
11	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
12	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS
13	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	263.10 FS	*- FS
14	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS
15	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
16	1		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS

F=Franchise part. S=SpecNett.

Total Parts (S\$) 4,282.75 1,292.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACING REAR BUMPER PANEL AND ATTACHMENTS, BOOTLID, ETC TO KNOCK OUT DENTS CAUSED BY THE ACCIDENT.	New	2,550.00	1,700.00
2	SPRAY REAR BUMPER, BOOTLID.	New	1,923.00	1,730.00
3	TO REPLACE REAR WINDSCREEN GLASS.	New	574.00	0.00
4	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM.	New	531.00	0.00
5	TO CONDUCT WATER LEAK TESTS.	New	75.00	0.00
6	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	150.00
7	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	118.00	0.00
Gross Labour Cost (S\$)			5,948.00	3,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >