

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

08 FEB 2019

Estimate No. : b1 50025
Date Estimated : 07/02/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chan Choon Seng
Blk 3 Jurong Lake Link
#01-13

Singapore 648161

- ACCOUNT - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3831X	5E91501	30/11/2017	216i G TOURER	0

DESCRIPTION

Replacing rear bumper panel and attachments, bootlid, etc
to knock out dents caused by the accident

VALUE

1700 2,550.00

Spray rear bumper, bootlid

1730 1,923.00

To replace rear windscreen glass.

X 574.00

To supply and install rear windscreen solar film.

X 531.00

To conduct water leak tests.

X 75.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 171.00

To carry out body cavity preservation.
(Per panel).

X 118.00

Sundries

? 150.00

Total Labour 1: **6,098.00****DESCRIPTION**

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID repair ?	1	1,204.35	1,204.35
RR BUMPER LH SIDE GUIDE ?	1	61.50	61.50
RR BUMPER LH SIDE GUIDE ?	1	61.50	61.50
REAR BUMPER CARRIER ?	1	458.10	458.10
REAR BUMPER TRIM STRIP (CHROM) CEX ✓	1	107.75	107.75
REAR BUMPER PANEL PRIMED (LINES PDC DE ✓	1	1,029.50	1,029.50
GROMMET RE ✓	2	0.75	1.50
PLAQUE 74MM RE ✓	1	71.25	71.25
REAR WINDOW X	1	654.35	654.35
BOOTLID SEALING X	1	143.00	143.00
DECOUPING RING PDC TORQUE CONVERTER ?	4	5.05	20.20
(DG) CLEANER R1 (100ML) X	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) X	2	131.55	263.10

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 50025**
Date Estimated : **07/02/2019**
Prepared By : **Joseph Yaguel**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3831X	5E91501	30/11/2017	216i G TOURER	0

DESCRIPTION	QTY	PRIC	VALUE
(DG/SL) GLASS PRIMER 30ML (VP206) X	1	27.85	27.85
Total Parts :			4,130.10

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/03/19 @ 1130 Excess S\$ _____

Surveyor's Name Rafael Sign _____

Surveyor's Tel 90012668 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 4-5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	6,098.00
Parts	:	4,130.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	715.97
Grand Total	:	10,944.07

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **