

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

08 FEB 2019

Estimate No. : b1 50025
Date Estimated : 07/02/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -Chan Choon Seng
Blk 3 Jurong Lake Link
#01-13

Singapore 648161

- ACCOUNT - 219India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3831X	5E91501	30/11/2017	216i G TOURER	0

DESCRIPTIONReplacing rear bumper panel and attachments, bootlid, etc
to knock out dents caused by the accident**VALUE**

1700 2,560.00

Spray rear bumper, bootlid

1730 1,923.00

To replace rear windscreen glass.

574.00

To supply and install rear windscreen solar film.

531.00

To conduct water leak tests.

75.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

To carry out body cavity preservation.
(Per panel).

118.00

Sundries

150.00

Total Labour 1:

6,098.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID repair	1	1,204.35	1,204.35
RR BUMPER LH SIDE GUIDE	1	61.50	61.50
RR BUMPER LH SIDE GUIDE	1	61.50	61.50
REAR BUMPER CARRIER	1	458.10	458.10
REAR BUMPER TRIM STRIP (CHROM)	1	107.75	107.75
REAR BUMPER PANEL PRIMED (LINES PDC)	1	1,029.50	1,029.50
GROMMET	2	0.75	1.50
PLAQUE 74MM	1	71.25	71.25
REAR WINDOW	1	654.35	654.35
BOOTLID SEALING	1	143.00	143.00
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796501 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50025
Date Estimated : 07/02/2019
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.
SLU3831X

CHASSIS NO.
5E91501

REGN. DATE
30/11/2017

MODEL
216i G TOURER

MILEAGE
0

DESCRIPTION

(DG/SL) GLASS PRIMER 30ML (VP206) X

QTY	PRIC	VALUE
1	27.85	27.85
Total Parts :		4,130.10

Claims OD / 2nd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 22/03/19 @ 1130 Excess S\$ _____

Surveyor's Name Ram Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 4-5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Labour 1	:	6,098.00
Parts	:	4,130.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	715.97
Grand Total	:	10,944.07

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 50025
Date Estimated : 07/02/2019
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -
Chan Choon Seng
Blk 3 Jurong Lake Link
#01-13

Singapore 648161

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3831X	5E91501	30/11/2017	216i G TOURER	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT * <i>nu ✓</i>	1.00	2.00		2.00

Total Labour :	
Total Parts :	2.00
Total Labour & Parts :	2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 50025
Date Estimated : 07/02/2019
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -
Chan Choon Seng
Blk 3 Jurong Lake Link
#01-13
Singapore 648161

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLU3831X	5E91501	30/11/2017	216i G TOURER	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include making good the boot lid and knocking out dents caused by the accident	1700.00		1,700.00	
To spray paint rear bumper and boot lid	1730.00		1,730.00	
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00	
Sundries	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *				
REAR BUMPER TRIM STRIP (CHROM)	1.00	2.00		2.00
REAR BUMPER PANEL PRIMED (LINES PDC	108.40	1.00		108.40
GROMMET	1,029.50	1.00		1,029.50
PLAQUE 74MM	0.75	2.00		1.50
	71.25	1.00		71.25

SUPPLEMENTARY ITEMS

Total Labour :	3,660.00
Total Parts :	1,212.65
Total Labour & Parts :	4,872.65
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,872.65
GST @7%:	341.09
Grand Total :	5,213.74