

Not with work
Resurvey B4 paint



ESTIMATE TO REPAIR

5-7 days

VEHICLE NO. : SJN 1030 P
MAKE : TOYOTA
MODEL : ESQUIRE 2.0XI A
YEAR : 2017
CHASSIS NO : ZRR800234592

SURVEYOR NAME :
DATE OF SURVEY : 13 FEB 2019
TIME OF SURVEY :

DATE : 11-Feb-19
DATE OF ACCIDENT : 31-Jan-19
THIRD PARTY REF : SMC 2437 R / AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			BT/CM	\$ 664.00 ✓
2 pcs	Rear Bumper Bracket		\$ 142.10		\$ 284.20 ?
2 pcs	Rear Bumper Reatiner		\$ 115.60	015 D17	\$ 231.20 ✓
2 pcs	Rear Bumper Reflector		\$ 85.60	015 CM	\$ 171.20 ✓
1 pc	Rear End Panel				\$ 918.00 ?
1 pc	Rear End Panel Garnish				\$ 258.00 ?
1 pc	Rear Spare Tyre Panel				\$ R 856.90 X
1 pc	Rear Spare Tyre Top Cover				\$ 148.50 ?
2 pcs	Taillamp		\$ 647.80		\$ 1,295.60 ?
1 pc	Taillamp Lower Garnish		\$ 134.10	015 Bu	\$ 268.20 ✓
1 pc	Tailgate				\$ B 1,685.00 ✓
1 pc	Tailgate Rubber				\$ 356.00 ?
1 pc	Tailgate Lock				\$ In 498.00 ✓
1 pc	Tailgate Emblem				\$ Rec 57.10 ✓
1 pc	Tailgate Outer Mounting				\$ 758.55 ?
1 pc	Rear Windscreen Moulding				\$ Rec 160.00 ✓
					\$ 8,610.45
	Less 25%				\$ 2,152.61
					\$ 6,457.84
1 tube	Rear Windscreen Sealant	S.Nett			\$ Rec 40.00 ✓
1 set	Rear Bumper Sensor	S.Nett			\$ 300.00 ?
1 pc	Rear Number Plate	S.Nett			\$ In 40.00 X
	To putty and spray painting			8601	\$ 1,200.00
	To transfer tailgate fittings				\$ 601 80.00
	To remove and refix rear windscreen glass				\$ 120.00 ✓
	To remove and refix cushion seats and trining			601	\$ 120.00
	To anti-rust				\$ 120.00 ?
	Labour Charges				\$ 1,000.00 ?
TG/RA-					\$ 9,477.84

LKK Auto Consultants hence notify the Repaired of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0