

ESTIMATE TO REPAIR

VEHICLE NO. : SJN 1030 P
 MAKE : TOYOTA
 MODEL : ESQUIRE 2.0XI A
 YEAR : 2017
 CHASSIS NO : ZRR800234592

SURVEYOR NAME :
 DATE OF SURVEY :
 TIME OF SURVEY :

DATE : 11-Feb-19
 DATE OF ACCIDENT : 31-Jan-19
 THIRD PARTY REF : SMC 2437 R / AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 664.00
2 pcs	Rear Bumper Bracket		\$ 142.10		\$ 284.20
2 pcs	Rear Bumper Reatiner		\$ 115.60		\$ 231.20
2 pcs	Rear Bumper Reflector		\$ 85.60		\$ 171.20
1 pc	Rear End Panel				\$ 918.00
1 pc	Rear End Panel Garnish				\$ 258.00
1 pc	Rear Spare Tyre Panel				\$ 856.90
1 pc	Rear Spare Tyre Top Cover				\$ 148.50
2 pcs	Taillamp		\$ 647.80		\$ 1,295.60
1 pc	Taillamp Lower Garnish		\$ 134.10		\$ 268.20
1 pc	Tailgate				\$ 1,685.00
1 pc	Tailgate Rubber				\$ 356.00
1 pc	Tailgate Lock				\$ 498.00
1 pc	Tailgate Emblem				\$ 57.10
1 pc	Tailgate Outer Mounting				\$ 758.55
1 pc	Rear Windscreen Moulding				\$ 160.00
					\$ 8,610.45
	Less 25%				\$ 2,152.61
					\$ 6,457.84
1 tube	Rear Windscreen Sealant	S.Nett			\$ 40.00
1 set	Rear Bumper Sensor	S.Nett			\$ 300.00
1 pc	Rear Number Plate	S.Nett			\$ 40.00
	To putty and spray painting				\$ 1,200.00
	To transfer tailgate fittings				\$ 80.00
	To remove and refix rear windscreen glass				\$ 120.00
	To remove and refix cushion seats and trining				\$ 120.00
	To anti-rust				\$ 120.00
	Labour Charges				\$ 1,000.00
TG/RA-					\$ 9,477.84

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd