

ASS. REC. BY:

REF: CS/FCI19002437/ Uad3m2 Special Instruction:

Surveyor: Marcus ASSIGNMENT (Office)From (Person): serene of FCI Date/Time: 6pm @ 11/2/19

Estimated Cost: Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLX 5327G Insured: SH 6259Pat Workshop m/s Focus Auto Tel: 68869097of 1 Kalki Bkt Ave 6 #02-50Policy No: Claim No: D19000886MFSH

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 02/02/2019CA / REV / REP. / REV 24 HRS 105 H.O.D. Endorsement:Date/Time: 11/2/19 @ 6:05pm Person Contacted: Mr. Sin Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	<u>SLX 5327G</u>	
	<u>SH 6259P - CS/FCI 19000579/Dsd3</u>	<u>DUA: 8/1/19</u>
<u>2/7/2019</u>	<u>Revised pending estimate via email</u>	
<u>2/7/19 @ 3:57pm</u>	<u>revised to serene via email</u>	

(08/11/13) wef

ASS. REC. BY: Marius

REF:

Fc1/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX53276at Workshop m/s Focus

of _____

Insured: SH 6258P

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 786c.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: dep 7800 Vehicle: IN / OUTVeh No: SLX53276 Yr Regn: 3, 18Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Toyota Sienna c.c. 1496Colour: white A/C: Insured / Std / NI / NASp. Reading: 15416 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH F228 H 3300049535

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or shutBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or hankook

Front

Rear

R/Bal. 2 mmR/Bal. 2 mmL/Bal. 2 mmL/Bal. 2 mmD.O.A. 2/2/19D.O.I. 11/2/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt & N/S RearThe U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/2/19 LIA 47129 9pm
 4/5 \$6000 conf. with AH way
 (red \$7534.30, 56%)

RECEIVED 22 FEB 2019

Date/Time, File Pass to?

☐ : Preli. Report11/2/20 Final☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS SI

Photos 058Others 2/2/19

TOTAL

3x15=45

170445

50

50

86

401

Report Format: TPLump Sum / I.B.I. (\$) 6000



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000856MFSH

Date: 21 February 2019

Our Ref: CS/FCI19002437/Uqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLX 5327G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/02/2019 at the premises of M/s FOCUS AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>13,534.30</u> .
Revised Estimate Amount	: S\$ <u>6,000.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the n/s front & n/s rear portion. The undercarriage affected due to collision.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	04-02-2019	Our Ref No. D19000856MFSH
Accident Date	02-02-2019	Claim Type. Third Party
Insured Vehicle	SH6259P	Third Party Vehicle. SLX5327G
Survey Location	NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-50	
Contact Person.	SIN	
Contact No.	68869097/ 0	Fax No. 64819095
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED (NO EST.)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FOCUS AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 21 February 2019 3:57 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000856MFSH/1
Attachments: CSFCI19002437Uqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SLX 5327G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 12 February 2019 4:40 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000856MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLX 5327G on 11/2/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 11 February 2019 6:03 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000856MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 12 February 2019 4:40 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000856MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLX 5327G on 11/2/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 11 February 2019 6:03 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Serener@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000856MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.



BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



AVIVA

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Mercedes Benz E63S, 16 Jan 2014, \$232888.



Rare Top Of The Line E63 S
AMG. Hellacious V8 Bassy Note.
Wolf In Sheep's Cloth!
ACM Automobiles StarAd



Browse by Category

Sort by Date Posted

4 vehicles

Toyota Sienta

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	Toyota Sienta		Any	Any	2018	Any	Any	
		Toyota Sienta Hybrid 1.5A G	\$89,500	\$9,100 /yr	27-Jun-2018	1,496 cc	60 km	
		Fuel Type: Petrol-Electric						
		Condition Like New, Elegant White MPV, Other Colors Available Too, Low Fuel Consumption With Hybrid, Flexible In House Loan Packag						
		Prime Motor & Leasing						
		Posted: 11-Feb-2019	Tags: 2018 Toyota Sienta, 2018 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota					
		Toyota Sienta Hybrid 1.5A G	\$90,888	\$9,270 /yr	27-Jun-2018	1,496 cc	-	
		Fuel Type: Petrol-Electric						
		Elegant Yellow MPV, Other Colors Available Too, Low Fuel Consumption With Hybrid, Flexible In-House Loan Packages Available.						
		Prime Motor & Leasing						
		Posted: 06-Feb-2019	Tags: 2018 Toyota Sienta, 2018 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota					
		Toyota Sienta Hybrid 1.5A G	\$86,800	\$8,870 /yr	25-Apr-2018	1,496 cc	-	
		Elegant Silver MPV, One Owner Only, Low Fuel Consumption With Hybrid, Low Maintenance Cost, Low Mileage Done, With Warranty, Dr						
		Minimum Down Payment,						
		Prime Motor & Leasing						
		Posted: 01-Feb-2019	Tags: 2018 Toyota Sienta, 2018 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota					
		Toyota Sienta Hybrid 1.5A X	\$89,988	\$8,450 /yr	23-Nov-2018	1,496 cc	65 km	
		Fuel Type: Petrol-Electric						
		Make And Assemble In Japan. 5 Years Or 100,000Km Warranty! View To Appreciate. Call Now.						
		Vincar Pte Ltd						
		Posted: 30-Jan-2019	Tags: 2018 Toyota Sienta, 2018 toyota sienta, Toyota Sienta, toyota sienta, Toyota, Sienta, sienta, Used Toyota					

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

V

For old advertisements, view **Expired ads**

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 4193H

Vehicle Details

Vehicle No.: SLX5327G
Vehicle to be Exported: No
Intended Deregistration Date: 02 Feb 2019
Vehicle Make: TOYOTA
Vehicle Model: SIENTA 1.5 CVT STD
Primary Colour: Silver
Manufacturing Year: 2017
Engine No.: 2NRX270849
Chassis No.: MHFZ28H3300049535
Maximum Power Output: 79.0 kW (105 bhp)
Open Market Value: \$16,599.00
Original Registration Date: 29 Mar 2018
First Registration Date: 29 Mar 2018
Transfer Count: 0
Actual ARF Paid: \$16,599.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Mar 2028
PARF Rebate Amount: \$12,449.00

Intended COE Rebate Details

COE Expiry Date: 28 Mar 2028
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$38,000.00
COE Rebate Amount: \$34,782.00
Total Rebate Amount: \$47,231.00

The information contained herein is correct as at 02 Feb 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4193H
Vehicle Details	
Vehicle No.:	SLX5327G
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5 CVT STD
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2NRX270849
Chassis No.:	MHFZ28H3300049535
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$16,599.00
Original Registration Date:	29 Mar 2018
First Registration Date:	29 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$16,599.00 <i>8259</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Mar 2028
PARF Rebate Amount:	\$12,449.00
Intended COE Rebate Details	
COE Expiry Date:	28 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,000.00
COE Rebate Amount:	\$34,680.00
Total Rebate Amount:	\$47,129.00

The information contained herein is correct as at 12 Feb 2019

OK

VEHICLE NO:

SLX5327G

MAKE & MODEL:


Toyota Sienta

DATE OF ACCIDENT	02 / 02 / 2019
TIME OF ACCIDENT	0215 (AM) / PM
LOCATION OF ACCIDENT	Along East Coast Road
Exact Purpose use during accident	Private Use
NAME OF OWNER	Heng Kim Meng
TELP NO	93630333
NRIC	S7144193H
CLAIM TYPE	OD / THIRD PARTY / Reporting Only
PRIVATE HIRE	YES / NO ?
INSURANCE CO.	AXA
TYRE OF COVERAGE	Comprehensive / Third Party / Third Party Fire & Theft
POLICY NO.	VPA/P2094726
NAME OF DRIVER	As above / If No: Ea Bee Hua
NRIC	S7343761Z
DATE OF BIRTH	26 / 11 / 1973
OCCUPATION	Outdoor / Indoor
DATE OF DRIVING PASS	04 / 06 / 1994
GENDER	Male / Female
CONTACT NO.	93230633 Office: Home:
ADDRESS	12 Evervale Link #08-23
DRIVER HAVE ANY OWN VEHICLE	NO / If yes: Reg No:
RELATIONSHIP	Employee / Hirer / Spouse / Parent / Friend / If No:
WEATHER CONDITION	Clear / Raining / Dizzling / Other:
ROAD SURFACE	Dry / Wet / Other:
ANY INJURIES	NO / If yes: Who?
CONTACT NO.	
POLICE REPORT	NO / If yes: Where?
VEHICLE B NO.	SH 6259P
NAME	OW Aik Sing
CONTACT NO.	82228885
VEHICLE C NO.	Any passengers:
VEHICLE D NO.	Any passengers:
VEHICLE E NO.	Any passengers:
VEHICLE F NO.	Any passengers:
ANY WITNESS	
WITNESS CONTACT NO.	
Have you been approach by unknown person soliciting (s)/	
Referring accident claims assistance?	YES / NO
Found	
PARTICULAR WORKSHOP	Progressive Auto Pte Ltd
TELP NO.	1 Kaki Bukit Avenue 6
CONTACT PERSON	Autobay @ kaki bukit
FAX NO.	#02-48/50 Singapore 417883
	Tel : 6844 4620
	Fax: 6844 4625

Sketch Plan #2 Pg. 1

SKETCH PLAN

East Coast Dr.



Veh A : SLX5327G.

veh B : SH6259P.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/2/19 time about 2.15 am, I was driving my vehicle SLX5327G along East Coast Road, Suddenly Vehicle B SH6259P from the junction U-turn hit onto my vehicle front left hand portion, cause my vehicle damage.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature

Date & Time:


 Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST:201004495R RCB NO:201004495R

M/S : FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 6507 3848

FAX: 6507 3849

ATTN: Motor Claim Department

Estimate No: EST0000819

Date: 12 Feb 2019

Policy No: p2094726

Veh Reg No: SLX5327G

Make/Model: TOYOTA SIENIA 1.5
CVT STD

Chassis No: MHFZ28H3300049535

Engine No: 2NRX270849

Reg. Date: 29-03-2018

Your Ref No: SLX5327G

Claim Type: Third Party

Accident Date: 02-02-2019

TP Veh Reg No: SH6259P

Estimate Repair Cost for Vehicle No :SLX5327G

PAGE:1/2

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
TOYOTA SIENIA				
List Price				
1 Front Fender	589.6000	1 PC	589.60	—
2 Front Fender Dust Cover LH	195.8000	1 PC	195.80	—
3 Front Fender Dust Cover Clipse	5.5000	6 PC	33.00	—
4 Front Head Lamp LH	3,350.6000	1 PC	3,350.60	—
5 Front Bumper	689.8000	1 PC	689.80	—
6 Front Bumper Side Retainer LH	85.9000	1 PC	85.90	—
7 Front Bumper Protector LH	290.4000	1 PC	290.40	—
8 Front Bumper Reinforcement	516.9000	1 PC	516.90	—
9 Front Grille	617.6000	1 PC	617.60	—
10 Front Bumper Clipse	5.5000	8 PC	44.00	—
11 Front Door LH	1,100.9000	1 PC	1,100.90	—
12 Front Door Hinges Lower LH	121.9000	1 PC	121.90	—
13 Front Door Rubber LH	169.5000	1 PC	169.50	—
14 Front Shock Absorber LH	986.9000	1 PC	986.90	—
15 Front Knuckle Arm LH	516.8000	1 PC	516.80	—
16 Front Rod Link LH	161.9000	1 PC	161.90	—
17 Front Lower Arm LH	882.9000	1 PC	882.90	—
18 Front Hub Bearing LH	586.4000	1 PC	586.40	—
19 Front Steering Ball Joint LH	126.4000	1 PC	126.40	—
20 Front Steering Tie Rod End LH	180.4000	1 PC	180.40	—
21 Rear Door LH	1,150.9000	1 PC	1,150.90	—
22 Rear Door Protector LH	198.6000	1 PC	198.60	—
23 Rear Fender Protector LH	101.9000	1 PC	101.90	—
			12,699.00	25
		Less 25%	3,174.75	9,524.30
Special Net				
24 Front Tyre LH	300.0000	1 PC	300.00	—
25 Front Sport Rim LH	850.0000	1 PC	850.00	—
			1,150.00	1,150.00

not Affected
Lian
2/5 6000
11/2/19
take place through
Sdy.

1021.10

435.20

325.10

6697.40
5023.25

42180

102 144
400

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST:201004495R RCB NO:201004495R

M/S : FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 6507 3848

FAX: 6507 3849

ATTN: Motor Claim Department

Your Ref No: SLX5327G

Claim Type: Third Party

Accident Date: 02-02-2019

TP Veh Reg No: SH6259P

Estimate No: EST0000819

Date: 12 Feb 2019

Policy No: p2094726

Veh Reg No: SLX5327G

Make/Model: TOYOTA SIENTA 1.5
CVT STD

Chassis No: MHFZ28H3300049535

Engine No: 2NRX270849

Reg. Date: 29-03-2018

Estimate Repair Cost for Vehicle No :SLX5327G

PAGE:2/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
Labour				
26 Panel Beating	1,200.0000	1 PC	1,200.00	600
27 Towing	50.0000	1 PC	50.00	✓
28 Check Wiring	60.0000	1 PC	60.00	30
29 Rust Proofing	60.0000	1 PC	60.00	✓
30 To Remove & Replace Door Assy	160.0000	1 PC	160.00	60
31 To Adjust Alignment	50.0000	1 PC	50.00	✓
32 To Remove & Replace Front Under Carriage	280.0000	1 PC	280.00	200
33 To Spray Painting	1,000.0000	1 PC	1,000.00	900
			2,860.00	2,860.00

Total S\$ 13,534.34
25

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND FIVE HUNDRED THIRTY FOUR AND CENTS THIRTY ONLY

For FOCUS AUTO PTE LTD

Focus Auto Pte Ltd

No 1 Kaki Bukit Ave 6 Auto Bay

#02-50 Singapore 417883

AUTHORISED SIGNATURE

we notify
that the repair work is being carried out on the basis of the estimate provided by the insurance company. The repair work is subject to the approval of the insurance company. The repair work is carried out on the basis of the estimate provided by the insurance company. The repair work is subject to the approval of the insurance company.

Acknowledged by Repairer:
Signature:
Date:

P-5023-25
S.N-544
14th-1950
7577-05



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19002437/Uqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 25-02-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6259P	Veh. Inspected	SLX 5327G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000856MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	11/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MHFZ28H3300049535	Colour	WHITE	
Odometer	15416	Steering	AFFECTED	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	HANKOOK	8 mm	
L/H Front Tyre	185/60 R15	HANKOOK	8 mm	
R/H Rear Tyre	185/60 R15	HANKOOK	8 mm	
L/H Rear Tyre	185/60 R15	HANKOOK	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT AND N/S REAR PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/02/2019	Inspection Date	11/02/2019	
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 5327G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER	DISTORTED	589.60	589.60
1	FRONT FENDER DUST COVER LH	TORN	195.80	195.80
6	FRONT FENDER DUST COVER CLIPSE @\$5.50	NECESSARY	33.00	33.00
1	FRONT HEAD LAMP LH	CRACKED	3,350.60	1,021.10
1	FRONT BUMPER	DISTORTED	689.80	689.80
1	FRONT BUMPER SIDE RETAINER LH	CRACKED	85.90	85.90
1	FRONT BUMPER PROTECTOR LH	GRAZED	290.40	290.40
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	516.90	-
1	FRONT GRILLE	NOT NECESSARY	617.60	-
8	FRONT BUMPER CLIPSE @\$5.50	NOT NECESSARY	44.00	-
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,100.90	-
1	FRONT DOOR HINGES LOWER LH	NOT NECESSARY	121.90	-
1	FRONT DOOR RUBBER LH	NOT NECESSARY	169.50	-
1	FRONT SHOCK ABSORBER LH	BENT	986.90	435.20
1	FRONT KNUCKLE ARM LH	BENT	516.80	516.80
1	FRONT ROD LINK LH	SERVICEABLE	161.90	-
1	FRONT LOWER ARM LH	BENT	882.90	882.90
1	FRONT HUB BEARING LH	NECESSARY	586.40	325.10
1	FRONT STEERING BALL JOINT LH	SERVICEABLE	126.40	-
1	FRONT STEERING TIE ROD END LH	BENT	180.40	180.40
1	REAR DOOR LH	DENTED / BENT	1,150.90	1,150.90
1	REAR DOOR PROTECTOR LH	GRAZED	198.60	198.60
1	REAR FENDER PROTECTOR LH	GRAZED	101.90	101.90
	LESS 25% DISCOUNT		-3,174.75	-1,674.35
			9,524.25	5,023.05
SPECIAL NETT ITEMS				
1	FRONT TYRE LH (LOCAL PURCHASE)(\$180.00)(80%)(SN)	PUNCTURE	300.00	144.00
1	FRONT SPORT RIM LH (SN)	BENT	850.00	400.00
			1,150.00	544.00

Report Ref No. CS/FCI19002437/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT DOOR LH.		1,200.00	600.00
	TOWING.		50.00	50.00
	CHECK WIRING.		60.00	30.00
	RUST PROOFING.		60.00	60.00
	TO REMOVE & REPLACE DOOR ASSY.		160.00	60.00
	TO ADJUST ALIGNMENT.		50.00	50.00
	TO REMOVE & REPLACE FRONT UNDER CARRIAGE.		280.00	200.00
	TO SPRAY PAINTING.		1,000.00	900.00
			2,860.00	1,950.00
	GRAND TOTAL		13,534.25	7,517.05
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,000.00

Report Ref No. CS/FCI19002437/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.