

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SJX9282Z
 TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/WL

Claim Type: Third Party

Accident Date: 10/02/2019

TP Veh Reg No: SKN7531J

Estimate No: ES1991128/WL

Date: 11 Feb 2019

Policy No: 5096340050-01

Veh Reg No: SJX9282Z

Make/Model: SUBARU IMPREZA 4DR
 1.5R AWD 4AT ABS

Chassis No: JF1GE3KS59G004044

Engine No: EL15D648258

Reg. Date: 23/07/2010

Estimate Repair Cost to Vehicle No :SJX9282Z

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	654.10	1 PC	654.10	✓
2 REAR BUMPER REINFORCEMENT	232.10	1 PC	232.10	✓
3 REAR BUMPER CLIPS	3.90	6 PCS	23.40	✓
4 REAR BOOT	1,012.90	1 PC	1,012.90	✓
5 REAR BOOT INNER LOCK	263.10	1 PC	263.10	✓
6 REAR BOOT INNER RUBBER	168.30	1 PC	168.30	508.30
7 REAR BOOT EMBLEM (SUBARU)	78.10	1 PC	78.10	✓
8 REAR BOOT EMBLEM (IMPREZA)	60.50	1 PC	60.50	✓
9 REAR SPARE TYRE TOP TOOL BOX	119.20	1 PC	119.20	✓
10 REAR SPARE TYRE TOP BOARD	450.30	1 PC	450.30	✓
11 REAR CENTRE PANEL	333.30	1 PC	333.30	✓
12 REAR CENTRE PANEL INNER TOP GARNISH	164.30	1 PC	164.30	?
13 REAR FENDER INNER GARNISHS	310.10	2 PCS	620.20	?
14 TAILLAMP LH	421.80	1 PC	421.80	✓
15 REAR EXHAUST PIPE	612.30	1 PC	612.30	?
			5,213.90	
		Less 20%	1,042.78	4,171.12
Special Net				
16 REVERSE SENSOR	200.00	1 PC	200.00	✓
			200.00	200.00
Labour				
17 TOWING (4 WHEEL)	100.00	1 LA	100.00	✓
18 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, TO CUT, WELD & RENEW REAR PANEL, KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT, REAR FENDERS & REALIGN THE SAME	1,000.00	1 LA	1,000.00	900
19 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR FENDERS, BOOT, HINGES, REAR BUMPER	1,000.00	1 LA	1,000.00	900
20 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	40.00	1 LA	40.00	✓
21 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,200.00	2,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$ 6,571.12
 Add GST @ 7% 459.98
 Total Amount Payable S\$ 7,031.10

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE



Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com

Business Reg. No.: 53349344K

NO. 25796

CASH SALE / JOB ORDER

Date: 10/2/19

Messrs: Cash
车牌 SIX 9282 X 车型 Subaru
Vehicle No. SIX 9282 X Model No: Subaru
时间 (日/夜) 38 05-04 W. 2 联络号码 98371514
Time (day/night): 38 05-04 W. 2 Contact No: 98371514
由 Tempines St 86
Location: Tempines St 86
到 38 05-04 W. 2
To: 38 05-04 W. 2
银额 1007 其他 Others:
Cash \$ 1007
经手人 Authorised By:
Tow Truck Driver Name: [Signature]

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☒ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

注意: 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一概由车主自行负责。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

E. & O. E.