

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5516K

AAD1902-030

*Not Authored
C/Sy @ 2550/*

Vehicle No.:	SHC 5516K
Chassis No.:	VF1ABL15AUC278840
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	4.2.2019
Third Party Insurer :	AIG
Date of Registration :	11/7/2014

PART		LIST	
1 BUMPER COVER FRT	\$	<i>Bur</i> 1,259.42	✓
1 BUMPER SPOILER FRT	\$	<i>Sm</i> 181.75	X
1 BUMPER ABSORBER FRT	\$	<i>Sm</i> 394.68	X
1 BUMPER RETAINER FRT RH	\$	<i>M1</i> 150.77	✓
1 BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88	} X
1 BUMPER UNDERTRAY FRT	\$	<i>Sm</i> 472.83	
1 BUMPER GRILLE LOWER FRT	\$	<i>Sm</i> 266.80	
1 BUMPER FOG LAMP GRILLE RH	\$	<i>Sm</i> 207.21	
1 BUMPER BEAM FRT	\$	<i>R</i> 914.08	
1 HEADLAMP RH	\$	<i>Sm</i> 1,184.43	} X
1 HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	
1 FENDER PANEL FRT RH	\$	<i>R</i> 783.83	✓
1 WHEELARCH FRT RH	\$	<i>Sm</i> 278.84	} X
1 FENDER BRACKET LOWER RH	\$	<i>Sm</i> 15.79	
1 FENDER INSULATOR RH	\$	<i>Sm</i> 130.84	
1 DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66	
1 WIPER RESERVOIR	\$	<i>Sm</i> 348.25	
1 WIPER RESERVOIR NECK	\$	<i>Sm</i> 136.11	} X
1 WIPER RESERVOIR MOTOR	\$	<i>Sm</i> 270.06	
1 RADIATOR GRILL	\$	<i>Sm</i> 1,707.78	
TOTAL	\$	11,824.17	
10%	\$	1,182.42	
	\$	10,641.75	

Special Nett

1SET BUMPER CLIP FRT	\$	<i>nc</i> 66.00	✓
1 BUMPER BRACKET CLIP FRT RH	\$	<i>nc</i> 12.00	X
1 BUMPER SUPPORT CLIP FRT RH	\$	<i>nc</i> 10.50	X
1SET BUMPER GRILLE LOWER CLIP	\$	<i>nc</i> 69.00	X

Trans-cab Auto Services Pte Ltd

AAD1902-030

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5516K

1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	<i>na</i> 80.00	<i>60sn</i>
1	FRONT RIGHT DOOR STICKER 'CHASSIS'	\$	<i>na</i> 50.00	<i>15sn</i>
		\$	157.50	
TOTAL		\$	10,799.25	

TOTAL PARTS**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	<i>400l</i>
Putty and spray painting of the affected portion.	\$	3,000.00	<i>660l</i>
To rust-proofing of the affected areas.	\$	170.00	<i>30l</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>15l</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	<i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	<i>na</i> 380.00	<i>X</i>
To replace, refix and top up coolant for radiator	\$	<i>na</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1902-030

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5516K

To vacuum, replace, refix and recharge Air Intercooler

\$ *NA* 170.00 X

TOTAL \$ 8,210.00

Over All Total \$ 19,009.25

LUMP SUM (REPAIR DAY)

~~10~~ DAYS

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: