

INS. CASE OWNER

CC 6/AIG1900

LKK

IDAC

Surveyor:

Addition

DOI:

ASSIGNMENT

18/1/10

Date / Time:

18/1/10

Registered in Merimen:

18/1/10

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKX 690VB

Name of Insured:

KOH KOK TEKH

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

8/1/10

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age:

JUMIE KOH KOK TEKH

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

6287466266

Policy No.:

20066565

Make / Model:

7040TH

Place of Accident:

WT 1

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SU 6055x



INSRS:

WSP:

Tel:

Liability:

RMKS:

Zero

Gravity



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SU 6055x - x

SKX 690VB - x

STAGE

DATE / PIC

Non-Reporting Ir (1st)

Non-Reporting Ir (2nd)

Non-Reporting Ir (Final)

Notification Ir (if non-pickup)

Call OI:

Email: 08.06.10

After call Ir to OI:

Documentation Check List: Handler Typist

Notification Ir (if non-pickup)

After call Ir to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GLA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: LWP

Repair Cost:

45

SS 3,850

1

5 days) Reduction:

4%

%

Email

Call

FINAL SETTLEMENT

Date/Time: 18-06-10

Confirm with TP/Rev

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28. Ass. Lia:

Repair Cost:

SS 3,850.00

OIG REPAIR ENDED TP

Loss of Rental (LOR):

SS 500.00

1

5 days) A +100

Loss of Use (LOU):

SS -

(5

x days)

Loss of Income (LOI):

SS -

(5

x days)

LOR only

LOU only

LOR + LOU

LOR + LO

LOR + LO

LOR + LO

LOR + LO

[Tick only one]

GLA/LTA Search:

SS 7.45

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost:

SS -

Total:

SS 4,357.45

Global Sum SS:

FINAL PAYMENT

Date/Time: 18-06-10

Confirm with: TP/Rev

Email

Call

Payee 1:

SS 4,357.45

Name 1:

ZERO GRANTY

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: 30 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLQ6055X Yr Regn: 2017 JulyType: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel cc 1496Colour: White A/C: Insured / Std / NI / NASp. Reading 39711 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: R411207757Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 12/02/19Survey held at Zero GravityDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAIG.

45. → 3,250 (3224.04 46%)

mv :

PV :

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report

Final Report

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS. \$

Photos

Others

TOTAL



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Buss.Reg.No.: 5288887X

Attn: Adrian

QUOTATION

No : QT-000159

AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Aches.

Your Ref. : SIO6902B
 Vehicle No. : SLQ6055X
 Make & Model : HONDA VEZEL
 Chasis No. : RU11207757
 Engine No. : L15B4407756
 Accident Date : 08/02/2019
 Policy No. : DMPPHQ18-004817
 Date : 12/02/2019
 Page : 1 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price S\$	Amount S\$
1	REAR BOOT <i>Dented</i>	1.0	PCS 1,459.10	1,459.10
2	WINDSCREEN MOULDING (REAR) <i>new</i>	1.0	PCS 82.10	✓ 82.10
3	LOGO (H) <i>new</i>	1.0	PCS 32.30	X 32.30
4	EMBLEM (VEZEL) <i>new</i>	1.0	PCS 68.70	✓ 68.70
5	LAMP (REAR) (L/H) <i>cut</i>	1.0	PCS 354.80	✓ 354.80
6	REAR BOOT INNER TRIM BOARD <i>Dented</i>	1.0	PCS 217.90	✓ 217.90
7	REAR BOOT INNER TRIM BOARD CLIPS <i>new</i>	12.0	PCS 4.50	30 54.00
8	REAR BOOT ADJUSTER RUBBER <i>new</i>	2.0	PCS 9.20	X 18.40
9	REAR BOOT INNER LOCK <i>Damaged</i>	1.0	PCS 224.60	✓ 224.60
10	REAR BOOT LOCK STRIKER <i>new</i>	1.0	PCS 26.10	X 26.10
11	REAR BOOT WEATHERSTRIP <i>cut</i>	1.0	PCS 125.60	✓ 125.60
12	REAR END PANEL <i>Repair</i>	1.0	PCS 762.40	1 762.40
13	SENSOR (KEY) <i>could</i>	1.0	PCS 128.90	✓ 128.90
14	REAR BUMPER <i>Dented</i>	1.0	PCS 980.00	880 980.00
15	BUMPER CLIP (CLIP) <i>new</i>	6.0	PCS 4.50	✓ 27.00
16	BUMPER SIDE RETAINER (L/H/R) <i>new</i>	1.0	PCS 19.50	✓ 19.50
17	BUMPER SIDE RETAINER (R/H/R) <i>new</i>	1.0	PCS 19.50	✓ 19.50
18	BUMPER SIDE (REAR) (L/H) <i>new</i>	1.0	PCS 181.30	✓ 181.30
19	REAR BUMPER REFLECTOR (L/H) <i>could</i>	1.0	PCS 81.60	✓ 81.60
20	Discount 20 %			-972.76
21	SubTotal (L)			3,891.04
22	REAR END PANEL SEALANT <i>new</i>	1.0	BT 50.00	X 50.00
23	REVERSE SENSOR <i>Damaged</i>	1.0	SET 280.00	200 280.00
24	REVERSE CAMERA <i>new</i>	1.0	PCS 450.00	X 450.00
25	STICKER (BUMPER) <i>new</i>	1.0	PCS 120.00	60 120.00
26	MOULDING (CHROME) (REFLECTOR) <i>cut</i>	1.0	PCS 60.00	60 60.00

3541.50

2833.20

320



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Buss.Reg.No.: 5288887X

QUOTATION

No : QT-000159

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Your Ref. : SKX6902B
 Vehicle No. : SLQ6055X
 Make & Model : HONDA VEZEL
 Chasis No. : RU11207757
 Engine No. : L15B4407756
 Accident Date : 08/02/2019
 Policy No. : DMPPHQ18-004817
 Date : 12/02/2019
 Page : 2 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
27	SubTotal (S)			980.00
28	PANEL BEATING & REPLACING OF THE ABOVE	1.0 X	700	700.00
29	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0 X	80	80.00
30	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0 X	X	80.00
31	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0 X	30	30.00
32	TO TRANSFER REAR BOOT FITTING	1.0 X	80	80.00
33	TO REMOVE REVERSE SENSOR/CAMERA	1.0 X	1660	1660.00
34	TO PROVIDE UNDER TURFOODE	1.0 X	X	150.00
35	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0 X	650	650.00
36	SubTotal (LABOUR)			2,220.00

3850

total: 4813.20
 4/5: 3850
 05 Days.

SINGAPORE DOLLAR SEVEN THOUSAND NINETY ONE AND CENTS FOUR ONLY

E. & O.E

Total	S\$	7,091.04
Discount	S\$	0.00
Net Total	S\$	7,091.04

Terms: C.O.D.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey

Customer's Signature/Co. Stamp

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

ZERO GRAVITY

Any claim for fault/workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made within (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.

Acknowledged by Repairer

Signature:

Date:

Zero Gravity

2 Kaki Bukit Ave 2
#01-25 Kaki Bukit Autohub Singapore 417921
Tel: 67412845 Fax: 67412170

13/05/2019

AIG ASIA PACIFIC INSURANCE PTE. LTD
AIG Building 78 Shenton Way
#07-16 Singapore 079120

Sirs / Madams

RE: ACCIDENT INVOLVING VEHICLE(S) SLQ6055X & SKX6902B AT CHOA CHU KANG
LOT 1 EXIT CARPARK ON 08/02/2019.

We understand that you are the insurer of vehicle SKX6902B.

I/We wish to inform you that my/our vehicle SLQ6055X have been completed repairs to my/our satisfaction by ZERO GRAVITY. I/We therefore propose to claim from your as follows:

1. Cost of Repair	S\$3850.00
2. LTA Search Fee	S\$7.45
3. Loss of Rental (S\$120.00 X 5 Days)	S\$600.00

Please let us have your reply soonest possible.

Thank you.

Yours faithfully

TIFFANY

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Saturday, 8 June 2019 5:04 PM
To: EUNICEKOHKAIEN@GMAIL.COM
Subject: ACCIDENT INVOLVING SKX 6902B AND SLQ 6055X ON 08/02/2019

Our Ref: CC6/AIG19002477/Aeb3

08 JUNE 2019

KOH KOK TEOH / EUNICE KOH KAI'EN

Dear Sir/Madam,

ACCIDENT INVOLVING SKX 6902B AND SLQ 6055X ON 08/02/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORITY

ACCIDENT ON: 08/02/2019

INVOLVING VEHICLE(S) NO.: SLQ6055X & SKX6P02B

AT/ALONG: Choa Chu Kang LOT 1 Exit Carpark

I, ZHANG DAN NRIC No/Co Reg. No.: S8776552 of

BLK286, #12-320, Choa Chu Kang Ave 3 Singapore 680286

Owner/Driver of motor vehicle registration no: SLQ6055X insured by

MS Eg Insurance Company Limited under policy no: DMPDHQ18-004817 do hereby

authorize m/s **Zero Gravity** ("my Repairer") of 2 Kaki Bukit Ave 2, # 01-25 Kaki Bukit

Autohub, Singapore 417921, to act as my representative in my claim ~~against my insurance~~

~~and/or~~ against the owner(s) / driver(s) of motor vehicle(s) registration no(s):

SKX6P02B in respect of the above-mentioned accident.

I also hereby authorize my repairer to proceed repair to my vehicle, give all further instructions on my behalf concerning the said claim and as such, all future correspondences should be addressed to my repairer.

My repairer is further authorized to receive on my behalf monies claims, correspondence and to give a valid discharge and I also hereby appoint my repairer as my attorney and to sign any discharge voucher or any other documents in connection with this matter on and for my behalf.

I confirm that in the event of unsuccessful claim against the negligent party and/or my own insurer (if only under comprehensive cover) for the damages caused to my vehicle, I agree to pay for all the costs and incidentals incurred by my repairer.

I the above-mentioned vehicle owner/driver hereby affirm the above-mentioned statement to be true and correct.

Date this 11 day of 02 Year 2019

Signature : [Signature]
(Company Stamp if applicable)

Full Name : ZHANG DAN

NRIC No : S8776552

Contact No : (HP) 90678483 (O) 65701965 (H) 66337610

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **ZERO GRAVITY** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$3,850.00** (Repair Cost), **S\$500.00** (Loss of Use/Rental), **S\$7.45** (Disbursement) for vehicle no. **SLO 6055X** that was damaged pursuant to the accident which occurred on **08/02/2019** (date) along **CHOA CHU KANG LOT 1 EXIT CAR PARK** (location) involving vehicle no/s **SKX 6902B**.

This is pursuant to the inspection conducted on **11/04/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **ZHANG DAN** ("the third party claimant") of vehicle no. **SLO 6055X** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLO 6055X** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 19th (day) of June (month) 2019 (year)



LWP

Signed by appointed surveyor



Signed by "the workshop" (with chop)



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
Tel: +65 67412845 Fax No: +65 67412170
Email: zero_gravity@singnet.com.sg
Buss.Reg.No.: 52888887X

FINAL REPAIR BILL

No : I-007300

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Your Ref. : SIX6902B
Vehicle No. : SLQ6055X
Make & Model : HONDA VEZEL
Chasis No. : RU11207757
Engine No. : L15B4407756
Accident Date : 08-02-2019
Policy No. : DMPPHQ18-004817
Date : 13-05-2019
Page : 1 of 1

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
1	Lumpsum	1.0 X		3,850.00

SINGAPORE DOLLAR THREE THOUSAND EIGHT HUNDRED FIFTY ONLY

E. & O.E



Customer's Signature/Co. Stamp

ZERO GRAVITY

Total	S\$	3,850.00
Discount	S\$	0.00
Net Total	S\$	3,850.00

Terms: C.O.D.

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.

SLQ6055X

**ZG PTE LTD**

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67477100

Buss.Reg.No.: 201317155Z

HIRER'S PARTICULARS I/We _____

If Different From of _____

Section ①

Hereinafter called "the Hirer" hereby confirm having agreed to hire this day from ZG PTE LTD. Hereinafter called "the Owner" the undermentioned Vehicle at the rental fees as shown below and I further agree that I shall be held responsible for:-

1) THIRD PARTY ONLY MOTOR VEHICLE COVERAGE

the Excess which is the maximum amount of \$2500 to cover for any third party damage or injury claims and also bear the full cost of any damage caused to the hired Vehicle resulting from any single accident including loss from inability to let the same Vehicle out on hire of loss resulting from theft and destruction of the Vehicle.

2) COMPREHENSIVE MOTOR VEHICLE COVERAGE

A) If the Rental Vehicle is damaged or destroyed while it is in the possession the Hirer, Hirer agrees to pay any required insurance deductible.

B) Hirer will be responsible for the full amount of the excess not exceeding \$2000 for own damages and \$1500 for third party claims upon reporting of any accidents.

3) Only persons above 22 years of age with more than 2 years driving experience, authorised licensed and signing this agreement may drive the Vehicle whether or not such damage or loss is by person/persons known or unknown to me or by negligence or any breach by me of the Terms and Conditions of Hire, hereinafter mentioned and printed at the back hereof.

Vehicle Regn No: <u>SJP5834A</u>		Rental Agreement: NO. <u>X 00009</u>	
Section ① Hirer's And/Or Driver's Particulars		Date & Time OUT: <u>11/02/2019</u> <u>11:40am</u>	
Name: <u>ZHANG DAN</u>		Date & Time IN: <u>16/02/2019</u> <u>02:35pm</u>	
Address: <u>Blk 286, #12-320</u> <u>Choa Chu King Ave 3, Singapore 680286</u>		Chargeable	Rates Amount
I/C No./Passport No: <u>58776552</u>		<u>5</u> Days	@ \$ <u>120.00</u> \$ <u>600.00</u>
Type of I/C/Passport: <u>Singapore Citizen</u>		Weeks	@ \$
Driving Licence No: <u>58776552</u>		Months	@ \$
Pass Date: <u>13 Aug 2015</u>			
Date of Birth: <u>28 June 1987</u>			
Place of Issue: <u>Singapore</u>			
a) Third Party Only Policy Excess \$2500/-		Insurance:	
b) Comprehensive Policy Excess \$3500/-		Total Charge:	\$ <u>600.00</u>
Vehicle Must Be Returned To Owner's Office By:		Security Deposit	
		Total Payable	
		Amount Paid	
		Delivery Fees	
IMPORTANT!		Collection Fees/Misc.	
For Singapore Use only		Extra Hours @ \$	
Fuel Tank OUT (E) (%) (%) (%) (%) (%) (%) (F)	Rates Do Not Include Fuel		
Fuel Tank IN (E) (%) (%) (%) (%) (%) (%) (F)	Refuelling		
Vehicle No: <u>1)</u>	From:	To:	
Vehicle No: <u>2)</u>	From:	To:	
Tools	Spare Tyre	Accessories	Total Additional Charges
Vehicle Issued By:			
Vehicle Collected By:			
NOTE: HIRER AND /OR DRIVER IS LIABLE FOR ALL PARKING, TRAFFIC AND SMOKY EXHAUST VIOLATION		Grand Total	\$ <u>600.00</u>

I/We have read and hereby agree to the terms and conditions on both sides of this rental agreement.

HIRER MUST NOT CARRY SAND AND CEMENT ON THE VEHICLE

PLS CHECK ENGINE OIL AND RADIATOR WATER EVERY MORNING

Date: 11/02/2019Signed: [Signature]

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 11 Feb 2019 / 14:53:02

Receipt Date/Time : 11 Feb 2019 / 14:53:02

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190211-002008

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHA8533B				
As at 10 Feb 2019/12:50:00				
Insurance Co: MS FIRST CAPITAL INSURANCE LIMITED				
1	Insurance Enquiry - SHA8533B Enquiry Fee 20190211144942079834	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
Result of Insurance Enquiry - SKX6902B				
As at 08 Feb 2019/14:00:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
2	Insurance Enquiry - SKX6902B Enquiry Fee 20190211144942114422	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	14.00	0.98	14.98
	Rounding Difference			0.03
	Total Amount Payable			14.95
Paid By				
	xxxxxxxxxxxx5595	Credit Card: Visa/MasterCard		14.95
	Total			14.95
	Cash Change			0.00
	Tendered Amount			14.95
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING





























Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2019 Edit Reg		12 Feb 2019 00:00 Edit Adj Rpt	S\$3,850.00 Edit Estimates	S\$3,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KOH KOK TEON , ID: S1795650G								
Main Claimant:	ZHANG DAN , ID: S8776552J								
Vehicle Reg. No.:	SLQ6055X	Date of Loss:	08/02/2019 14:00 - :59 [18 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6282249663SG	Policy/Cover Note No.:	2100446565 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKX6902B	Policy No. (Claimant):	DMPPHQ18-004817						
		Excess:							
Repairer:	Zero Gravity (Kaki Bukit) 2 Kaki Bukit Ave 2, #01-25 Kaki Bukit Autohub, 417921 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/02/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ6055X (6282249663SG)
[SKX6902B]
TP
ZHANG DAN
Feb 8 2019 2:00PM
[KOH KOK TEOH]
Zero Gravity

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1			Edit		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
2	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
3	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
4	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
5	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
6	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
7	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
8	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
9	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
10	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
11	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
12	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
13	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
14	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
15	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
16	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
17	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
18	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
19	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
20	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
21	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
22	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
23	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
24	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
25	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
26	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
27	13/05/19 18:22		General View												1			Load JPG <input checked="" type="checkbox"/>		
28	13/05/19 18:22		Replacement Part Photo												1			Load JPG <input checked="" type="checkbox"/>		
29	13/05/19 18:22		Replacement Part Photo												1			Load JPG <input checked="" type="checkbox"/>		
30	13/05/19 18:22		Replacement Part Photo												1			Load JPG <input checked="" type="checkbox"/>		
31	13/05/19 18:22		Replacement Part Photo												1			Load JPG <input checked="" type="checkbox"/>		
32	13/05/19 18:22		Replacement Part Photo												1			Load JPG <input checked="" type="checkbox"/>		
33	13/05/19 18:22		Replacement Part Photo												1			Load JPG <input checked="" type="checkbox"/>		
34	13/05/19 18:22		Replacement Part Photo												1			Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
36	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
37	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
38	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
39	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
40	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
41	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
42	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
43	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
44	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
45	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
46	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
47	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
48	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
49	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
50	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
51	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
52	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
53	13/05/19 18:22	Replacement Part Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/02/19 18:38	TP GIA REPORT	 Load PDF	
2	14/05/19 08:53	TP ESTIMATE	 Load PDF	
3	08/06/19 17:05	LETTER TO OI	 Load PDF	
4	03/07/19 15:32	WORKSHOP INVOICE	 Load PDF	
5	03/07/19 15:32	AUTHORISATION TO ACT FORM	 Load PDF	
6	03/07/19 15:32	Release Voucher	 Load PDF	
7	03/07/19 15:32	RENTAL RECEIPT	 Load PDF	
8	03/07/19 15:32	LTA SEARCH	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/02/19 11:22	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKX6902B (Insd veh)	Model:	HONDA VEZEL 1.5 (A)
	SLQ6055X (TP veh)		
Date of Accident:	08/02/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	7,091.04	
Final Repair Cost	: \$	3,850.00	
Loss of Use	: \$	_____ days at \$0.00 per day	
Rental (if any)	: \$	500.00	5 days
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	4,357.45	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Zero Gravity	: \$	4,357.45
2)		: \$	
3)		: \$	

HUEY YON

03 Jul
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19002477/AEB3Q2

Date: 03/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100446565
 Claimant Vehicle No: SLQ6055X Insured Vehicle No: SKX6902B
 Date of Loss: 08/02/2019 Nature of Claim: TP Claim No: 6282249663SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ6055X
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4407756
 Reg. Date: 17/07/2017 (Man. Year: 2016) Chassis No: RU11207757
 Colour: White Odometer: 39711 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,871.04	3,153.20	1,717.84	35.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	1,660.00	560.00	25.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,091.04	4,813.20	2,277.84	32.12
Approved Total (Overridden) (S\$)		3,850.00		
Nett Amount (S\$)	7,091.04	3,850.00	3,241.04	45.71
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,357.45		

INSPECTION

Date of Assignment: 12/02/2019
 Date Inspected: 12/02/2019 Inspected At: Zero Gravity (Kaki Bukit)
 2 Kaki Bukit Ave 2, #01-25 Kaki Bukit
 Autohub
 Singapore 417921
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	1,459.10 FL	*1,100.00 FL
2	1		*WINDSCREEN MOULDING (REAR)	Necessary	82.10 FL	*82.10 FL
3	1		*LOGO (H)	Not Necessary	32.30 FL	*- FL
4	1		*EMBLEM (VEZEL)	Necessary	68.70 FL	*68.70 FL
5	1		*LAMP (REAR)(L/H)	Cut	354.80 FL	*354.80 FL
6	1		*REAR BOOT INNER TRIM BOARD	Deformed	217.90 FL	*217.90 FL
7	12		*REAR BOOT INNER TRIM BOARD CLIPS	Necessary	54.00 FL	*30.00 FL
8	2		*REAR BOOT ADJUST RUBBER	Not Necessary	18.40 FL	*- FL
9	1		*REAR BOOT INNER LOCK	Damaged	224.60 FL	*224.60 FL
10	1		*REAR BOOT LOCK STRIKER	Not Necessary	26.10 FL	*- FL
11	1		*REAR BOOT WEATHERSTRIP	Cut	125.60 FL	*125.60 FL
12	1		*REAR END PANEL	Repair	762.40 FL	*- FL
13	1		*SENSOR (KEY)	Cracked	128.90 FL	*128.90 FL
14	1		*REAR BUMPER	Deformed	980.00 FL	*880.00 FL
15	6		*BUMPER CLIP (CLIP)	Necessary	27.00 FL	*27.00 FL
16	1		*BUMPER SIDE RETAINER (L/H/R)	Necessary	19.50 FL	*19.50 FL
17	1		*BUMPER SIDE RETAINER (R/H/R)	Necessary	19.50 FL	*19.50 FL
18	1		*BUMPER SIDE (REAR) (L/H)	Torn	181.30 FL	*181.30 FL
19	1		*REAR BUMPER REFLECTOR (L/H)	Cracked	81.60 FL	*81.60 FL
20	1		*BTL REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
21	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
22	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
23	1		*STICKER (BUMPER)	Necessary	120.00 FS	*60.00 FS
24	1		*MOULDING (CHROME) (REFLECTOR)	Cut	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	5,843.80	3,861.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	972.76	708.30
Total Parts (\$\$)	4,871.04	3,153.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & REPLACING OF THE ABOVE	New	800.00	700.00
2	TO REMOVE AND REFIT COMPONENTS /FACILITATE THE REPAIR	New	120.00	80.00
3	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	New	80.00	0.00
4	TO CHECK WIRING SYSTEM ,FOCUS LIGHTINGS	New	50.00	30.00
5	TO TRANSFER REAR BOOT FITTING	New	120.00	80.00
6	TO REMOVE REVERSE SENSOR /CAMERA	New	150.00	120.00
7	TO PROVIDE UNDER TURFCODE	New	150.00	0.00
8	TO PUTTY AND RE-SPRAY AFFECTED PORTION	New	750.00	650.00
Gross Labour Cost (S\$)			2,220.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >