

## Vic (LKKAUTO)

---

**From:** Vic (LKKAUTO)  
**Sent:** Tuesday, 5 November, 2019 10:16 AM  
**To:** Lee, Ming-Yao  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** Your Ref: 8229263504SG - ACCIDENT INVOLVING VEHICLES SBH 82Y AND SKZ 6321S ON 30/01/2019 - LKK REF CC4/AIG19002479/Ghb3

Dear Ming Yao,

We refer to the above matter and to our email in merimen dated 12/07/2019.

Please be informed that Insured reported and insisted that there was no collision between both vehicles.

As such, TP repairer had furnish us a copy of their client's video footage (uploaded in merimen).

Based on the footage, TP vehicle drove passed the Insured vehicle when it also moved out towards the left.

Furthermore, our surveyor upon inspection of the TP vehicle observed damages to the RH sillgarnish step chrome of the TP vehicle. Likely, the Insured's tyre may have likely brushed the step chrome of the TP vehicle.

Kindly let us have your view / opinion / instructions for this matter.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.