

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C**AAD1902-023**

Not Authored
8775.00

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5980C

VF1ABL15AUC281511

RENAULT

LATITUDE

2.2.2019

AIG

23/3/2015

PART**LIST**

1	BUMPER COVER FRT	\$	<i>N.C (CRM)</i>	1,259.42
1	BUMPER SPOILER FRT	\$	<i>Sn</i>	181.75
1	BUMPER ABSORBER FRT	\$	<i>Sn</i>	394.68
1	BUMPER RETAINER FRT LH	\$	<i>Sn</i>	151.41
1	BUMPER SUPPORT FRT	\$	<i>Sn</i>	123.88
1	BUMPER RETAINER FRT RH	\$	<i>Sn</i>	150.77
1	BUMPER SUPPORT FRT	\$	<i>Sn</i>	123.88
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i>	472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i>	266.80
1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i>	207.21
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i>	207.21
1	BUMPER BEAM FRT	\$	<i>R</i>	914.08
1	TOW COVER FRT	\$	<i>Sn</i>	28.61
1	HEADLAMP LH	\$	<i>N.C (CRM)</i>	1,184.43
1	HEADLAMP HARNESS	\$	<i>Sn</i>	928.29
1	FENDER PANEL FRT LH	\$	<i>R</i>	783.83
1	WHEELARCH FRT LH	\$	<i>Sn</i>	278.84
1	FENDER BRACKET LOWER LH	\$	<i>Sn</i>	15.79
1	FENDER INSULATOR LH	\$	<i>Sn</i>	130.84
1	DOOR PANEL FRT LH	\$	<i>R</i>	2,844.66
1	DOOR HINGE UPPER LH	\$	<i>R</i>	261.28
1	DOOR HINGE LOWER LH	\$	<i>R</i>	300.55
1	DOOR CHECK FRT LH	\$	<i>Sn</i>	194.77
1	DOOR LOCK FRT LH	\$	<i>R</i>	908.75
1	DOOR CATCH FRT LH	\$	<i>R</i>	131.23
1	DOOR HANDLE OUTER FRT LH	\$	<i>Sn</i>	477.76
1	DOOR HANDLE COVER FRT LH	\$	<i>Sn</i>	13.22
1	DOOR HANDLE MODULE FRT LH	\$	<i>Sn</i>	133.60
1	DOOR REGULATOR FRT LH	\$	<i>Sn</i>	505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>Sn</i>	796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>Sn</i>	120.97

Trans-cab Auto Services Pte Ltd**AAD1902-023**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C

1	DOOR PANEL REAR LH	\$	<i>N</i> 2,844.66
1	DOOR GUIDE REAR LH	\$	<i>Sn</i> 176.82
1	DOOR HINGE UPPER LH	\$	<i>N</i> 274.50
1	DOOR HINGE LOWER LH	\$	<i>N</i> 300.55
1	DOOR CHECK REAR LH	\$	<i>Sn</i> 203.06
1	DOOR LOCK REAR LH	\$	<i>Sn</i> 908.75
1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i> 126.49
1	DOOR HANDLE CAP REAR LH	\$	<i>Sn</i> 35.52
1	DOOR HANDLE SEAL REAR LH	\$	<i>Sn</i> 7.89
1	DOOR HANDLE COVER REAR LH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE REAR LH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR REAR LH	\$	<i>Sn</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>Sn</i> 893.75
1	DOOR REGULATOR NUT REAR LH	\$	<i>na</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>na</i> 6.31
1	DOOR FINISHER REAR LH	\$	<i>Sn</i> 423.10
1	DOOR MOULDING REAR LH	\$	<i>Sn</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>na</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>Sn</i> 6.91
1	DOOR CASING REAR LH	\$	<i>Sn</i> 1,509.06
1	DOOR WATER SHIELD REAR LH	\$	<i>Sn</i> 30.39
1	DOOR CASING CLIP	\$	<i>na</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>Sn</i> 48.74
1	DOOR FINISHER INNER REAR LH	\$	<i>Sn</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>N</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>N</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>N</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>N</i> 20.33
1	DOOR GRAB HANDLE REAR LH	\$	<i>Sn</i> 210.96
1	DOOR BLIND REAR LH	\$	<i>Sn</i> 741.80
1	DOOR WHEATHESTRIIP REAR LH	\$	<i>Sn</i> 410.66
1	DOOR SEAL REAR LH	\$	<i>Sn</i> 162.02
1	DOOR GLASS RUNNER SEAL REAR LH	\$	<i>Sn</i> 229.31
1	DOOR WAIST SEAL OUTER REAR LH	\$	<i>Sn</i> 334.69
1	DOOR WAIST SEAL INNER REAR LH	\$	<i>Sn</i> 115.64
1	FENDER PANEL REAR LH	\$	<i>N</i> 3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	<i>Sn</i> 671.45
1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47
1	BUMPER COVER REAR	\$	<i>Sn</i> 1,108.46
1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84

X

Trans-cab Auto Services Pte Ltd

AAD1902-023

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C

1	BUMPER BRACKET CTR REAR	\$	Sn	113.47	}	X	
1	BUMEPR RETAINER LH REAR	\$	Sn	44.99			
1	BUMPER BEAM REAR	\$	N	777.52			
1	BUMPER BEAM BRACKET LH REAR	\$	Sn	225.95			
1	DOOR MIRROR ASSY LH	\$	Sn	1,483.40			
1	TAILLAMP LH	\$	Sn	552.55			
1	ROCKER PANEL INNER GARNISH LH	\$	Sn	466.51			
1	ROCKER PANEL INNER LH	\$	N	1,024.79			
1	ROCKER PANEL CENTER LH	\$	N	990.25			
		\$		38,486.50			
10%		\$		3,848.65			
		\$		34,637.85			

Special Nett

1SET	BUMPER CLIP FRT	\$	Nn	66.00	}	X
1	BUMPER BRACKET CLIP FRT LH	\$	Nn	12.00		
1	BUMPER SUPPORT CLIP FRT LH	\$	Nn	10.50		
1SET	BUMPER GRILLE LOWER CLIP	\$	Nn	69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	Nn	70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	Nn	20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	Nn	30.00		
1SET	WHEELARCH CLIP FRT LH	\$	Nn	30.50		
1	FRONT DOOR STICKER 'Trans-cab'	\$	Nn	80.00	}	X
1	FRONT DOOR STICKER 'Chassis'	\$	Nn	50.00		
1	REAR DOOR STICKER '6555 3333'	\$	Nn	80.00		
1	DOOR CHECK BOLT	\$	Sn	22.69		
1	DOOR GUIDE SCREW	\$	Sn	10.85		
1	DOOR HINGE BOLT	\$	Sn	10.85		
1	DOOR HINGE NUT RH	\$	Sn	14.60		
1	DOOR CHECK BOLT	\$	Sn	22.69		
1	DOOR CHECK NUT	\$	Sn	3.75	}	X
1	DOOR LOCK SCREW L70Y	\$	Sn	6.12		
1	DOOR CATCH SCREW L70Y	\$	Sn	10.06		

TOTAL \$ **619.63**TOTAL PARTS \$ **35,257.48**

Trans-cab Auto Services Pte Ltd**AAD1902-023**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	2001
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
Putty and spray painting of the affected portion.	\$	4,200.00	4401
To rust-proofing of the affected areas.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To Check Electrical Lighting Concerned.	\$	4 170.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	4 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To lift-up engine with gear box and refit.	\$	4 440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	4 440.00	X
To remove and refit air bag system and reset.	\$	4 480.00	X

Trans-cab Auto Services Pte Ltd**AAD1902-023**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C

To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	na 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	↪ 380.00	X
To replace, refix and top up coolant for radiator	\$	↪ 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	↪ 170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	↪ 170.00	X
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	↪ 170.00	X

TOTAL \$ 13,450.00**Over All Total \$ 48,707.48****LUMP SUM(REPAIR DAY)****20 DAYS****2 day,**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: