

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9896G**AAD1902-036***Not Notarized
11 Sep @ 2900h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 9896G

VF1ABL15AUC277841

RENAULT

LATITUDE

1.2.2019

EQ

9/5/2014

	PART
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER ABSORBER FRT
1	BUMPER RETAINER FRT RH
1	BUMPER SUPPORT FRT
1	BUMPER UNDERTRAY FRT
1	BUMPER GRILLE LOWER FRT
1	BUMPER FOG LAMP GRILLE RH
1	BUMPER BEAM FRT
1	HEADLAMP RH
1	HEADLAMP PANEL FRT RH
1	FENDER PANEL FRT RH
1	WHEELARCH FRT RH
1	FENDER BRACKET LOWER RH
1	FENDER INSULATOR RH
1	DOOR PANEL FRT RH
1	WIPER RESERVOIR
1	WIPER RESERVOIR NECK
1	WIPER RESERVOIR MOTOR
1	RADIATOR GRILL

LIST

\$	<i>Bu</i>	1,259.42	✓
\$	<i>SL</i>	181.75	X
\$	<i>SL</i>	394.68	X
\$	<i>Di</i>	150.77	✓
\$	<i>SL</i>	123.88	} X
\$	<i>SL</i>	472.83	
\$	<i>SL</i>	266.80	
\$	<i>SL</i>	207.21	
\$	<i>R</i>	914.08	
\$	<i>SL</i>	1,184.43	}
\$	<i>R</i>	152.15	
\$	<i>R</i>	783.83	✓
\$	<i>Tn</i>	278.84	✓
\$	<i>SL</i>	15.79	} X
\$	<i>SL</i>	130.84	
\$	<i>R</i>	2,844.66	
\$	<i>SL</i>	348.25	
\$	<i>SL</i>	136.11	
\$	<i>SL</i>	270.06	}
\$	<i>SL</i>	1,707.78	
TOTAL	\$	11,824.17	
10%	\$	1,182.42	
	\$	10,641.75	

Specical Nett

1SET	BUMPER CLIP FRT	\$
1	BUMPER BRACKET CLIP FRT RH	\$
1	BUMPER SUPPORT CLIP FRT RH	\$
1SET	BUMPER GRILLE LOWER CLIP	\$

<i>SL</i>	66.00	✓
<i>SL</i>	12.00	X
<i>SL</i>	10.50	X
<i>SL</i>	69.00	X

Trans-cab Auto Services Pte Ltd

AAD1902-036

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9896G

1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	<i>nr</i> 80.00 <i>60sn</i>
1	FRONT RIGHT DOOR STICKER 'CHASSIS'	\$	<i>nr</i> 50.00 <i>15sn</i>

\$	157.50
----	--------

TOTAL	\$	10,799.25
--------------	-----------	------------------

TOTAL PARTS**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	<i>500l</i>
Putty and spray painting of the affected portion.	\$	3,000.00	<i>660l</i>
To rust-proofing of the affected areas.	\$	170.00	<i>30l</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nr</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>60l</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nr</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>20l</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nr</i> 380.00	<i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	<i>nr</i> 380.00	<i>X</i>
To replace, refix and top up coolant for radiator	\$	<i>nr</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1902-036**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9896GTo vacuum, replace, refix and recharge Air
Intercooler

\$ 170.00 X

TOTAL \$ 8,210.00**Over All Total \$ 19,009.25****LUMP SUM (REPAIR DAY)**~~10 DAYS~~

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: