

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100
ATTN: Motor Claim Department

FAX: 62244174

Xiao Tony

Claim Type: Third Party
Accident Date: 04/02/2019
TP Veh Reg No: SHC8855L

Estimate No: EST1900041

Date: 09 Feb 2019

Veh Reg No: **SJR1403B**

Make/Model: HONDA FREED 1.5G A

Chasis No: GB31009825

Reg. Date: 10/06/2009

Your Ref No: SHC8855L

Estimate Repair Cost to Vehicle No :SJR1403B

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC REAR BUMPER <i>del</i>	576.70	-
2	1 PC REAR BUMPER SIDE RETAINER RH <i>men</i>	41.50	-
3	1 PC REAR SHOCK ABSORBER RH <i>men</i>	198.60	-
4	1 PC REAR WHEEL HUB RH <i>del</i>	334.70	-
5	1 PC REAR AXLE <i>del</i>	997.80	-
		2,149.30	
	Less 20%	429.86	1,719.44
	Special Net		
6	1 PC REAR BUMPER SPOILER <i>del</i>	650.00	550
7	1 PC REAR TYRE RH <i>men</i>	350.00	4
8	1 PC REAR TYRE RIM RH <i>del</i>	800.00	500
		1,800.00	1,800.00
	Labour		
9	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	600.00	400
10	1 TO REMOVE AND REFIT UNDERCARRIAGE	550.00	250
11	1 TO SPRAY PAINTING	750.00	600
12	1 TO CHECK WIRING	50.00	30
13	1 TO CHECK WHEEL ALIGNMENT	120.00	80
		2,070.00	2,070.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62244174

ATTN: Motor Claim Department

Claim Type: Third Party

Accident Date: 04/02/2019

TP Veh Reg No: SHC8855L

Estimate No: EST1900041

Date: 09 Feb 2019

Veh Reg No: SJR1403B

Make/Model: HONDA FREED 1.5G A

Chasis No: GB31009825

Reg. Date: 10/06/2009

Your Ref No: SHC8855L

Estimate Repair Cost to Vehicle No :SJR1403B

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
		Total	S\$ 5,589.44
		Add GST @ 7%	391.26
		Total Amount Payable	S\$ 5,980.70

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED EIGHTY AND CENTS SEVENTY ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian C
L/s 13/02/19
04 days.
Total 3970.56
4/5 3150

Kang

COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company:
VIN:
Date

KANG CAR REPAIRER PTE LTD
SJR 1403 B
13.2.19 17:14



SJR 1403 B

Factory Japan 2017.0.1 : Honda : Freed : GB3

Front : Left

Actual	Before	Specified Range
-0°26'	-0°26'	-1°00' 1°00'
3°31'	3°31'	2°15' 4°15'
-0°08'	-0°08'	-0°08' 0°08'
20°25'	20°25'	10°50' 12°50'
19°59'	19°59'	9°50' 13°50'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°18'	-0°18'	-1°00' 1°00'
3°31'	3°31'	2°15' 4°15'
-0°03'	-0°03'	-0°08' 0°08'
10°45'	10°45'	10°50' 12°50'
10°27'	10°27'	9°50' 13°50'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°08'	-0°09'	-0°45' 0°45'
0°00'	0°00'	
9°40'	9°40'	
-0°11'	-0°11'	-0°17' 0°17'

Rear : Left

Actual	Before	Specified Range
-1°19'	-1°19'	-2°00' 0°00'
0°10'	0°09'	0°00' 0°17'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-2°08'	-2°08'	-2°00' 0°00'
-0°28'	-0°29'	0°00' 0°17'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
0°48'	0°48'	
-0°19'	-0°20'	0°00' 0°33'
0°19'	0°19'	
0mm	0mm	