

Case Details

Case Reference Number : TAX/02/19/2035
Type of Repair : Accident Repair
Vehicle Registration Number : SHC4754X

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-5647-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : FWD SINGAPORE PTE LTD
Accident Date and Time : 08/02/2019 01:30 AM
Vehicle Age(In Months) : 34

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	NEC
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair	
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	NEC
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	NEC
One Time Key In	Main			WHEEL DISC	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	
Total Spare Part Cost									2,252.70		Surveyor Total		149.40	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0	
Final Spare Part Cost									2,252.70		Final Sur Total		149.40	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	507.00	400	
Total:			507.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR FENDER RH	378.00	200	
3	Main	TO RESPRAY RIM	180.00	50	
Total:			936.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
5	Main	TO WASH AND VACUUM	60.00	0	
Total:			460.00	20.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,252.70	149.40
Total Labour Cost	507.00	400.00
Total Spray Painting	936.00	450.00
Other	460.00	20.00
Overall Total	4,155.70	1,019.40
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	1,019.40
Surveyor Approved Amount		1,019.40
No of Repair Days*	5	3
Remarks	-	P/P REPAIR,PHOTO BEFORE PAINT
Surveyor Name		Hwee jie

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Signature		
		Save Clear
Survey Date	13/02/2019	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: