



VIRIAN

Section A - Accident Details

Registration Number	SHC4754X
Case Reference Number	TAX/02/19/2035
Registration Date	1/4/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TAN GEOK SWEE
Type of Accident	Side Swipe
Accident Date and Time	8/2/2019 9:30 AM
Accident Reported Date and Time	8/2/2019 10:43 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24100020
Special Instruction to ARC, if any	DAMAGE REAR R/H SIDE TP VEHICLE NO SGP8845J
Prepared Date and Time	10/2/2019 4:09 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Left/Right Side

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$400.00
Total Spray Cost	\$936.00	\$450.00
Total Spare Part Cost	\$2,252.70	\$149.40
Total Other Cost	\$460.00	\$20.00
TOTAL COST	\$4,155.70	\$1,019.40 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Kim Ming Chin	Hwee Jie (LKK) / FWD
ARC / Surveyor Sign Off Date	10/02/2019 4:17 PM	13/02/2019 12:42 PM
Signature		
Remarks		P/P REPAIR, PHOTO BEFORE PAINT

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1903-0063	Invoice Number	
Quotation Date	05.03.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$507.00	\$400.00
Total Labour	\$507.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
Total Spray Painting & Panel Beating	\$936.00	\$450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$460.00	\$20.00

149.40
+ 400.00
+ 470.00
1019.40

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.80	100.00	\$0.00	Replace	Repair R
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given X
		61604-47090	FENDER RR/RH	1.00	\$788.80	100.00	\$0.00	Replace	Repair R
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace ✓
			STICKER DECAL SMRT	1.00	\$7.80	0.00	\$7.80	Replace	Replace ✓
		42611-47140	WHEEL DISC	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair R
Total					\$2,893.80		\$149.40		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Case Details

Case Reference Number : TAX/02/19/2035
Type of Repair : Accident Repair
Vehicle Registration Number : SHC4754X

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-5647-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : FWD SINGAPORE PTE LTD
Accident Date and Time : 08/02/2019 01:30 AM
Vehicle Age(In Months) : 34

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0	Repair	x R
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	/ NEC
One Time Key In	Main			BUMPER SIDE RETAINER R/R/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	x NM
One Time Key In	Main			FENDER R/R/RH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair	x R
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	/ NEC
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	/ NEC
One Time Key In	Main			WHEEL DISC	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	0	Repair	x R
Total Spare Part Cost									2,252.70		Surveyor Total		149.40	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0	
Final Spare Part Cost									2,252.70		Final Sur Total		149.40	

Labour's Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	507.00	400	
Total:			507.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR FENDER RH	378.00	200	
3	Main	TO RESPRAY RIM	180.00	50	
Total:			936.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	AK
3	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
5	Main	TO WASH AND VACUUM	60.00	0	
Total:			460.00	20.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	2,252.70	149.40
Total Labour Cost	507.00	400.00
Total Spray Painting	936.00	450.00
Other	460.00	20.00
Overall Total	4,155.70	1,019.40
Lump Sum Repair Option	0	0
Lump Sum Total	0.00	1,019.40
Surveyor Approved Amount		1,019.40
No of Repair Days*	5	3
Remarks		P/P REPAIR, PHOTO BEFORE PAINT
Surveyor Name		Hwee Jie

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Signature		
		Save Clear
Survey Date	13/02/2019	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: