



96 MOTORSPORTS PTE LTD

64 Kaki Bukit Ave 6 Singapore (417893)

Email: Sheela.sim@96motorsports.com

Tel: 86840506

TPAKA
Xiao Tony

VEHICLE NUM:

SJV 4973 G

MAKE & MODEL:

SUZUKI SX4 (4 DOOR)

MILEAGE:

TYRE: FRONT

TYRE: REAR

CHASSIS NUM:

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE	ADJUSTED PRICE
1	BOOT LID <i>Branded</i>	1	\$ 657.90	✓
2	BOOT LID BADGE	1	\$ 67.00	✓
3	BOOT LID EMBLEM (VVT) <i>per</i>	1	\$ 68.00	✓
4	BOOT LID EMBLEM (SX4)	1	\$ 67.00	✓
5	BOOT LID OUTER GARNISH <i>new</i>	1	\$ 181.20	x
6	BOOT LID OUTER GARNISH CLIP <i>new</i>	10	\$ 30.00	x
7	BOOT LID NUMBER PLATE LAMP L+R <i>new</i>	2	\$ 92.00	x
8	BOOT LID KEY LOCK <i>new</i>	1	\$ 121.00	f
9	BOOT LID STOPPER <i>new</i>	2	\$ 40.00	p
10	BOOT LID INNER LOCK <i>changed</i>	1	\$ 145.60	✓
11	BOOT LID LOCK CATCH <i>new</i>	1	\$ 56.80	x
12	BOOT LID WEATHERSTRIP <i>new</i>	1	\$ 188.60	✓
13	BOOT LID HINGE L+R <i>new</i>	2	\$ 168.60	f
14	REAR BUMPER <i>changed</i>	1	\$ 656.80	✓
15	REAR BUMPER SIDE RETAINER L+R <i>new</i>	2	\$ 120.00	✓
16	REAR BUMPER CLIP <i>new</i>	10	\$ 50.00	30
17	REAR BUMPER REINFORCEMENT <i>best</i>	1	\$ 168.60	—
18	REAR BUMPER REFLECTOR L+R <i>new</i>	2	\$ 298.50	x
19	END PANEL <i>Deleted</i>	1	\$ 572.00	✓
20	END PANEL TOP TRIM <i>changed</i>	1	\$ 182.40	✓
21	END PANEL TOP TRIM CLIP <i>new</i>	10	\$ 30.00	10
22	SPARE TYRE PANEL TOP BOARD <i>new</i>	1	\$ 452.00	x
23	TAIL LAMP L+R <i>changed</i>	2	\$ 675.80	✓
24	TAIL LAMP INNER SEAL L+R <i>new</i>	2	\$ 80.00	40
25	TAIL LAMP CLIP <i>new</i>	10	\$ 20.00	—
26	TAIL LAMP PANEL L+R <i>Revis</i>	2	\$ 363.40	f
27	REAR FENDER L+R <i>Revis</i>	1	\$ 1,399.40	f
28	REAR FENDER INNER TRIM L+R <i>new</i>	2	\$ 268.40	f
29	REAR FENDER INNER TRIM CLIP <i>new</i>	10	\$ 30.00	f
30	REAR WINDSCREEN MOULDING <i>per</i>	1	\$ 120.00	f
31	REAR WINDSCREEN INNER SEAL	1	\$ 50.00	p
32	REAR EXHAUST SILENSER <i>new</i>	1	\$ 678.80	4

