



**ESTIMATE TO REPAIR**

VEHICLE NO. : SKA 3127 M  
 MAKE : B.M.W  
 MODEL : X6 3.0 A  
 YEAR : 2011  
 CHASSIS NO : WBAFG22070LL80464

SURVEYOR NAME :  
 DATE OF SURVEY : 18.02.2019  
 TIME OF SURVEY :

DATE : 12-Feb-19  
 DATE OF ACCIDENT : 28-Jan-19  
 THIRD PARTY REF : SHB 9981 D / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper				\$ 1,273.80 <sup>7</sup>
1 pc	O/S Front Fender Arch Garnish				\$ 205.75 <sup>7</sup>
16 pcs	O/S Front Fender Arch Garnish Clips		\$ 5.00		\$ <sup>Me</sup> 80.00 <sup>✓</sup>
	To putty and spray painting				\$ 450.00 <sup>400</sup>
	Labour Charges				\$ 350.00 <sup>220</sup>
<p><i>Not Authorized</i>  <i>Repair B4 paint</i>  <i>3 days</i></p>					
<p>LKK Auto Consultants hereby notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer            Signature:            Date:</p>					
TG/RA-	<b>Total</b>				<b>\$ 2,359.55</b>

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721  
 Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg  
 Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd