

kh



ESTIMATE TO REPAIR

VEHICLE NO. : SKA 3127 M
 MAKE : B.M.W
 MODEL : X6 3.0 A
 YEAR : 2011
 CHASSIS NO : WBAFG22070LL80464

SURVEYOR NAME :
 DATE OF SURVEY : 18.02.2019
 TIME OF SURVEY :

DATE : 12-Feb-19
 DATE OF ACCIDENT : 28-Jan-19
 THIRD PARTY REF : SHB 9981 D / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper			<i>m/m</i>	\$ 1,273.80 <i>2/</i>
1 pc	O/S Front Fender Arch Garnish				\$ 205.75 <i>2/</i>
16 pcs	O/S Front Fender Arch Garnish Clips		\$ 5.00		\$ 80.00 <i>2/</i>
	To putty and spray painting				\$ 450.00 <i>400</i>
	Labour Charges				\$ 350.00 <i>220</i>
<i>Not with work Repair by paint 3 days</i>					
Parts \$1353.80					
Labour \$620.00					
\$1973.80					
-20% \$394.76					
\$1579.04					
<i>4/8 \$1550.00</i> <i>27/2/19</i>					
TG/RA-	Total				\$ 2,359.55
	<i>03 days</i>				

Lim Tan Motor Pte Ltd

Bik 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website: www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd